## Figure: 28 TAC §34.1302(b)

6002.152(	Branch office registration	\$1,000.00	34.617	Failure to\$500.00
a)	certificate required			distribute/retain certificate
				Installation inspection \$50.00-
6002.154(	No licensed employee	\$1000.00	34.618	improperly \$500.00
a)				performed/documented
	No license	\$3,000.00	34.618	Installation inspection \$500.00
b)				improperly documented
6002.154(	Licensee not an employee of	\$750.00	34.618	Installation inspection\$500.00
c)	registered firm			docs not on file for 5 yrs
	Engage in business w/o license or registration			
	certificate	+ - ,		
			34.619(a)	System/modification not
	Adopted Standards			planned by authorized\$3,000.00
				person
		\$50.00-		
34.616(b)(	Violation of standards	\$500.00	34.619(b)	Plans not submitted to\$500.00
4)	established by 34.607			АНЈ
	Violation of standards	\$50.00-		
34.6616(b	established by manufacturers	\$500.00	34.619(b)	Plans incorrectly\$250.00
)(4)				submitted to AHJ

	requirements (NFPA 72,			
	§10.3.2)			
				Labels
	Location Business Practices		34.620(a)	Installation label not affixed to inside of\$500.00 control panel cover
34.610(a)	Failure to maintain business location	\$500.00	34.620(d)	Installation label improperly formatted or\$500.00 incomplete
34.610(b)	Designated employee	\$500.00	34.620(f)	Installation label incorrectly formatted or\$500.00 incomplete (1 or 2 family)
34.610(c)	Registration information not displayed on vehicle	\$250.00	34.621(a)	Service label not affixed\$500.00 to control panel cover
34.611(f)( 2)	Failure to notify SFMO of termination of employee within 14 days		34.621(b)	Information about yellow or red label not on service\$500.00 label that corrected the impairments
34.616(b)( 1)	Installation not performed by or under direct supervision of authorized licensee		34.623(c) (yellow) 34.624(c)	Owner or AHJ not\$500.00 notified of impairment
,			(red)	

	Certifying licensee not			
	licensed under ACR of			Service label improperly
34.616(b)(	primary registered firm or	\$1,000.00	34.621(h)	formatted or incomplete \$500.00
1)	certifying licensee not present			
	for			
	final acceptance test			
	Licensee attaching label not			Inspection/test label not
34.616(b)(	_	\$1,000.00	34.622(a)	filled out in detail or not\$500.00
	primary registered firm	, .,		affixed to inside of
				control panel cover
	Service and maintenance not			
34.616(b)(	performed by or under direct	\$3,000.00	34.622(d)	Owner or AHJ not\$500.00
2)	supervision of authorized			notified of impairment
	licensee			
	, S	\$250.00-		Inspection/test label
6002.302(	Misrepresentation of goods	\$1,000.00	34.622(j)	incorrectly \$500.00
a)(3)	or services			formatted/incomplete
	Failure to revise or change an	\$250.00		
34.610(h);	address within the required			
	14 days of change			
34.611(d)	, ,			
				Completed yellow label
	Monitoring		34.623(a)	not attached to outside\$500.00

			of control panel of impaired system
Monitoring an alarm for an unregistered firm	\$3,000.00		Yellow label incorrectly\$500.00 formatted/incomplete
Connecting an alarm to an unregistered monitoring firm	\$2,000.00	34.624(a)	Completed red label not attached to outside of\$1,000.00 impaired system
No licensed technician at central station	\$1,000.00		Red label improperly\$500.00 formatted/incomplete

34.613(a)(5)(B)	Lapse of Insurance				
Months	Punitive	+	Amount saved		Total
0 - 1	\$200	+	\$125	=	Warning Letter
1 - 2	\$500	+	\$250	=	\$750
2 - 3	\$500	+	\$375	=	\$875
3 - 4	\$500	+	\$500	=	\$1,000
4 - 5	\$500	+	\$625	=	\$1,125
5 - 6	\$500	+	\$750	=	\$1,250
6 - 7	\$750	+	\$875	=	\$1,625
7 - 8	\$750	+	\$1,000	=	\$1,750
8 - 9	\$750	+	\$1,125	=	\$1,875
9 - 10	\$750	+	\$1,250	=	\$2,000
10 - 11	\$750	+	\$1,375	=	\$2,125
11 - 12	\$750	+	\$1,500	=	\$2,250