Report Prepared for the
Texas Secretary of State
Elections Division

Voting System Certification
Evaluation Report

Election Systems and Software (ESS)
Unity 3.4.1.0 Voting System

Introduction

This report summarizes the findings and observations regarding the conformance of the Election Systems and Software (ESS) Unity 3.4.1.0 voting system to the requirements of the State of Texas.

Pursuant to Texas Administrative Code §81.60, ES&S submitted their application for state certification. Included with their application was their Technical Data Package (TDP) and their test report upon which the EAC based their national certification. The EAC/NIST NVLAP accredited Voting System Test Laboratory (VSTL) was NTS, formerly Wyle Labs. The EAC certification of this system was to the 2002 version of the Voluntary Voting System Guidelines (VVSG) and not the newer 2005 version. Under EAC rules modifications to previously certified voting systems may be certified to the older version of the VVSG but the modifications themselves are required to meet the newer requirements of the 2005 standard. Accordingly the majority of this system was evaluated to the 2002 version, see Appendix A - EAC Certificate of Certification, but modifications were evaluated to the 2005 version of the VVSG.

To provide chain-of-custody, a copy of all firmware/software and source code was s sent directly from NTS. It was installed in the early part of the examination under the supervision of the Texas examination team.

The ESS Unity 3.4.1.0 Voting System was evaluated for certification by the State of Texas on June 9-10, 2014.

Recommendation

The ESS Unity 3.4.1.0 Voting System is recommended for certification, with observations and comments presented in this report. The system was judged to comply with the voting system requirements of the State of Texas.

This recommendation is being made with the observation that prior versions of the system are being successfully used to run elections, including in Texas. A variety of features introduced in this version bring improvements to the version of the system currently in use and so would be a step forward for those counties that use the Unity system.

Further, Unity version 3.4.1.0 of the system has been deployed and is being used successfully in other states. The EAC maintains an interactive map identifying jurisdictions that are using EAC certified systems. They also maintain a report database of problems reported by election officials with certified systems. These resources were consulted and are the basis for the statement that this system, but more widely, its immediate predecessor, the Unity 3.4.0.0, is being used in a number of jurisdictions.

Remedial Actions

The following remedial actions are recommended:

Use of Merged 3.0.1.1 and 3.4.1.0

As noted this system does not support a DRE but ESS stated that those counties that used their DRE could run the Unity 3.0.1.1 and Unity 3.4.1.0 in parallel and merge the results. It is recommended that this functionality be evaluated before being approved for use in Texas.

Documentation of Audit Logs

As noted it was found that the process for gathering the full set of log files is not clear. Further the messages vary across the system components with cryptic or sometimes absent explanation of the meaning of the message or the action that should be taken. For a large percentage the only action recommended is to call the companies service representative. It is recommended that ESS be asked to provide a clear process for gathering a full set of system log files and clear explanations for understanding them. For errors and abnormal events both the meaning of the message and the correct action to be taken should be clear.

A further problem is that in contrast to the treatment of the iVotronic DRE in Unity 3.0.1.1 the Unity 3.4.1.0 makes analysis of the audit logs so labor intensive as to be prohibitive. In the Unity 3.0.1.1 system all iVotronic logs are gathered along with their vote tallies and a composite output of all the logs can be provided. This allows for quick and automatic scanning of the full set of audit log files to see if any of the units reported errors or abnormal events. In contrast the M100 and DS200 only provide a printout of their logs. These units are used in large numbers in some jurisdictions. Like any mechanical or electrical device, some units will have problems. The inability to have the logs electronically for timely review and appropriate remediation of problems is a major deficiency to election administration.

Lack of continuous feed real time audit logging

The M100 and DS200 do not support a continuous feed printer for real time audit logs and therefore should not be used in early voting or in a central count function.

Mark recognition thresholds

The ballot mark acceptance and rejection thresholds of the scanners in the system is not documented. Further those thresholds are determined by the vendor and they are different for

each scanner. The mark acceptance and rejection thresholds should be clearly known by election officials. Further testing of marks near those thresholds should be performed to verify the consistency of each scanner to recognize ballot marks that irregular in some way. This information is important if election officials are to accurately count irregular marks in a close election or recount.

Sincerely,

H. Stephen Berger

Contents

Candidate System

This section describes the candidate system, the ESS Unity 3.4.1.0 Voting System.

System Components

The system is comprised of the components listed in Table 1 and shown functionally in Figure 1. This information is based on companies "Application for Texas Certification of Voting System" (Form 100).


Figure 1 - ESS Unity 3.4.1.0 Process Flow

Version: 1.0
Date: July 10, 2014

Table 1 - ESS Unity 3.4.1.0 System Components

#	Unit/Application	Version	Function
colspan=4	**System Components**		

#	Unit/Application	Version	Function
1	Unity	3.4.1.0	Election Management System
	Election Management Software		
2	Audit Manager	7.5.2.0	Provides password security and a real-time audit log of user inputs and system outputs for Election Data Manager and Ballot Image Manager.
3	Election Data Manager (EDM)	7.8.2.0	Defines precinct, contest and candidate data and generates the election database.
4	Election Reporting Manager (ERM)	7.9.0.0	Results consolidation and reporting software.
5	ESS Image Manager (ESSIM)	7.7.2.0	Formats paper ballots and output files for programming ballot marking devices (BMD).
6	Hardware Programming Manager (HPM)	5.9.0.0	Generates election definition media for voting system equipment.
7	Log Monitor Service	1.1.0.0	Monitors Windows Event Viewer and closes any active Election Management System (EMS) program if the system detects the improper deactivation of the Windows Event Viewer.
	AutoMark		
8	AIMS	1.3.257	Generates equipment configurations for the AutoMARK Voter Assist Terminal (VAT).
9	AutoMARK	1.3.2907	Accessible ballot marking system that supports audio ballot playback and ballot marking for voters with low vision or with physical disabilities.
10	Voter Assist Termnial (VAT) Previewer	1.3.2907	Allows the user to preview audio text and screen layout prior to downloading election-day media.
	Ballot Scanners		
11	M100	5.4.4.5	Precinct ballot tabulator used to process ballots at a polling place.
12	DS200	1.7.0.0	Precinct ballot tabulator used to process ballots at a polling place.
13	M650	2.2.2.0	Central ballot scanner for high-volume tabulation of mail ballots, absentee ballots or Election Day ballots.
14	DS850	2.9.0.0	Central ballot scanner for high-volume tabulation of mail ballots, absentee ballots or Election Day ballots.

Components Not Previously Certified

The following components have not previously been certified in Texas:

System Components			
#	Unit/Application	Version	Function
1	DS200	1.7.0.0	Precinct Ballot Scanner
2	DS850	2.9.0.0	Central Count Ballot Scanner
3	Log Monitor Service	1.1.0.0	Log Monitor
4	VAT Previewer	1.3.2907	Previewer

Comparison to Prior and Successor Systems

The prior ESS voting system certified in Texas was the Unity 3.0.1.1, certified on March 3, 2008.

Comparison to Previous Version			
#	Unit/Application	3.0.1.1 Version	3.4.1.0 Version
1	Unity	3.0.1.1	3.4.1.0
Election Management Software			
2	Audit Manager	7.3.0.0	7.5.2.0
3	Election Data Manager (EDM)	7.4.4.0	7.8.2.0
4	Election Reporting Manager (ERM)	7.1.2.1	7.9.0.0
5	ESS Image Manager (ESSIM)	7.4.2.0	7.7.2.0
6	Hardware Programming Manager (HPM)	5.2.4.0	5.9.0.0
AutoMark			
7	AutoMARK	1.1.2258	1.3.2907
8	AIMS	1.2.18	1.3.257
Ballot Scanners			
9	M100	5.2.1.0	5.4.4.5
10	M650	2.1.0.0	2.2.2.0

ESS has received EAC national certification for several successor systems, including:

Successor Voting Systems		
#	System	Date of EAC Certification
1	EVS 5.0.0.0	May 16, 2013
2	EVS 5.0.1.0	March 18, 2014

Important insights for the evaluation of the ESS Unity 3.4.1.0 can be gained by comparing it to its predecessor and successor systems.

Many components are common to the version of the system previously certified in Texas. Accordingly it may be assumed that the experience using the prior version of the system will be similar to that of the new system. However, some prior issues in earlier versions of the system have been resolved. These may be identified by studying the change log and engineering change orders on the system from the 3.0.1.1 version to the 3.4.1.0 version.

It is noteworthy that several components are no longer being manufactured. Specifically the Automark, M100 and M650 are no longer being manufactured. The DS200 is the replacement for the M100 and the DS850 is the replacement for the M650. It would appear that these components are being included in this certification to insure that they are included in the certified configuration and may be used in a system mixed with their replacement units.

Examination Report

Description of the Examination

The examination occurred on June 9-10, 2014. It was preceded by the delivery of the companies Forms 100 and 101, Technical Data Package, authorization letters and related documents. The system software and firmware was provided directly from the VSTL that had examined the system to the VVSG for national certification.

On the first day of the examination, the technical examiners (Stephen Berger, Tom Watson and James Sneeringer), Christina Adkins and some members of the election division staff were present to observe and verify the installation of the vendor's software. SHA-1 digital signatures were recorded of the software provided by NTS and the software and firmware was installed onto the system. Photos of the equipment and labels were taken and where hardware and firmware versions could be provided either on a screen or printed, those were produced and recorded.

Christian Adkins with assistance from Secretary of State Staff Attorney Yahitza Nunez tested the the AUTOMARK Voter Assist Terminal ("AutoMARK") for compliance with state and federal accessibility guidelines.

On the second day ESS staff reviewed the Unity 3.4.1.0, including its configuration and the function and role of the various components in the voting system. An overview of the changes from the last version certified in Texas, the Unity 3.0.1.1, was delivered.

The examiners tested each piece of equipment using a pre-marked "test deck" of ballots. The test deck had been hand tallied by staff from the Secretary of State's office on ballots provided by the vendor. Voted ballots were tabulated through the M100 (precinct ballot counter), DS200 (precinct ballot counter), M650 (central tabulator), and DS850 (central tabulator). The tabulation reports from the M100, DS200, M650, and DS850 all matched and were correct.

The conclusion of the exam was that the Unity 3.4.1.0 meet the Voting System Standards outlined in Sections 122.001, 122.032, 122.033, and 122.0331 of the Texas Election Code and the rules outlined in Chapter 81, Subchapter C of the Texas Administrative Code.

Observations & Findings

DRE Support

Because the system does not include the iVotronic, ESS's DRE, the vendor was asked how jurisdictions that use the iVotronic could continue to use them with the new system. Their response was that they could continue to use them with Unity 3.0.1.1 and merge the results of that system with the 3.4.1.0, which would be required if that jurisdiction had acquired the DS200, DS850 or updated other components to the 3.4.1.0 level. However, ES&S did not bring a Unity 3.0.1.1 system to demonstrate how the merger of the two systems would take place. Therefore, the merge functionality has not been evaluated.

Continuous feed printer for real time audit logs

It was observed that the M100 and DS200 do not provide a continuous feed printer for real time audit log. Texas Administrative Code §81.62 requires that any central accumulator must have a

continuous feed printer dedicated to a real-time audit log.   Since, neither the M100 nor the DS200 support this requirement they should not be used for early voting or as central tabulators.

Mark recognition and mark rejection thresholds

Ballot scanners have thresholds to differentiate a valid mark from a stray mark or smudge. Further, the ballot scanners in the Unity 3.4.1.0 system were developed at different times and all use different technologies for detecting marks. For large, well marked selections all the scanners are likely to detect them the same way. However, for marks that approach the scanner's threshold the same mark may be read differently by different scanners, even in the same voting system.

In a study of ballot marks made in real elections on mail-in ballots a wide distribution of marks was found, Table 2. In a close election the accurate reading of the marks that are smaller, lighter or otherwise irregular becomes increasingly important.

Table 2 – Distribution of Ballot Marks

Ballots Mark Distribution				
Instrument **Pen**				**Pencil**
Color **Black**	**Blue**	**Red**	**Green**	**Grey**
Contrast **Dark**	**Dark**	**Dark**	**Dark**	**Dark**
% Fill				
> 75% 24207	7387	25	3	7435
50 - 75% 7860	661	0	0	718
25 - 50% 287	89	0	0	81
15 - 25% 10	0	0	0	20
10 - 15% 24	0	0	0	0
5 - 10% 10	0	0	0	1
< 5% 5	0	0	0	0
Contrast **Light**	**Light**	**Light**	**Light**	**Light**
% Fill				
> 75% 0	12	0	0	186
50 - 75% 0	0	0	0	107
25 - 50% 0	0	0	0	56
15 - 25% 0	0	0	0	15
10 - 15% 0	0	0	0	8
5 - 10% 0	0	0	0	10
< 5% 0	0	0	0	2

It is important that election officials know what the threshold of their ballot scanners are and what kinds of marks may read inconsistently because they are close to the threshold of the scanner. In the Unity 3.4.1.0 system there are four different thresholds for determining that is a valid mark and four different thresholds for determining what is a smudge or stray mark and should be ignored. However, these thresholds are not documented in the TDP. Further when asked the answer given by the company is very difficult to relate so that a mark that is close to the threshold can be identified.

A particular problem with the DS200 is that it performs a bitonal conversion on scanned marks before trying to recognize them. A bitonal conversion takes the electronic image of a mark and

converts all pixels to either pure black or pure white. The problem with performing the bitonal conversion before trying to recognize a mark is that a mark that is very clear to the human eye may fall below the stray mark threshold and be ignored after the conversion, as shown in Figure 2

Ballot Mark Images		
#	JPG	After Conversion to Bi-Tonal
1		
2		
3		
4		
5		
6		
7		
8		
9		

Figure 2 – Some marks go through the bitonal conversion better than others

To deal with close elections election officials need to know what kinds of marks their scanners will have problems will and then have procedures for giving ballots with those kinds of marks special handling. However, to do that the mark recognition and mark rejection thresholds must be known and known in a way that an election official can identify a mark that may be problematic and deal with it appropriately.

Compliance Checklist

The following checklist includes all Texas voting system requirements. The complete checklist is provided as detailed support for the conclusion and recommendation of this report.

Vendor: Election Systems & Software	**Voting System: 3.4.1.0**

Pre-Test Requirements

	Yes	No
• Is Form 100 complete and satisfactory?	☒	☐
• Review Form 100 - Schedule A - Have recommendations/issues made from previous exams been corrected or addressed?	☒	☐
• Review Form 101 - Are responses satisfactory?	☒	☐
• Review change logs and provide information for testing or questioning vendor	☒	☐
• Training manuals appear complete?	☐	☒
• Training manuals appear to be easy to use? • In several areas the user manuals were found difficult to use, notably regarding instructions on how to gather the full set of system audit logs, the meaning of the messages in those logs and the appropriate actions in response to any errors or unexpected events.	☐	☒
• Check with other jurisdictions where system is in use and ask questions regarding system, support and training. • No information from other jurisdictions was used in this exam.	☐	☒
• Did the system receive favorable reviews? • No reviews of this system were available for this exam.	☐	☒
• Do all configurations listed in application seem feasible? Keep this in mind during the examination to make sure components necessary to ensure the security are included in all configurations and that the configurations will meet the counties needs (scanner used as central and/or precinct, etc..)	☒	☐
• Vendors' proposals shall state a clear, unequivocal commitment that the election management and voter tabulation software user's application password is separate from and in addition to any other operating system password.	☒	☐
• Vendor's system shall support automated application password expiration at intervals specified by a central system administrator.	☒	☐
• Vendor shall discuss the steps required by the system administrator to implement and maintain automated password expiration. This discussion will include narrative concerning the degree to which the application password expiration capabilities are based on (a) the server or client's operating system, (b) the software application, or (c) both	☒	☐
• The vendor's proposal shall state the name of any automated incident, issue, or problem tracking system used by the firm in providing support to its election system clients.	☒	☐

Verify Installation

	Yes	No
• Verify/List all hardware	☒	☐
• Verify/List all COTS hardware/software versions	☒	☐
• Is the COTS hardware being demonstrated the same version as what was tested at the VSTL?	☒	☐
• Is the COTS software being demonstrated the same version as what was tested at the VSTL?	☒	☐
• Witness or actual install the software and firmware with the SOS CDs received from VSTL.	☒	☐

Texas Law	Federal Law				

System Review

				Yes	No
TEC 122.001		•	Preserves the secrecy of the ballot	☒	☐
TEC 122.001		•	Is suitable for the purpose for which it is intended	☒	☐
TEC 122.001		•	Operates safely, efficiently, and accurately and complies with the error rate standards of the voting system standards adopted by the EAC	☒	☐
TEC 122.001		•	Is safe from fraudulent or unauthorized manipulation (physical exam and review of manuals)	☐	☒
TEC 122.001		•	Permits voting on all offices and measures to be voted on at the election	☒	☐
TEC 122.001	HAVA	•	Warns of Overvote - Prevents counting votes on offices and measures on which the voter is not entitled to vote	☒	☐
	HAVA	•	Warns of Undervote	☒	☐
TEC 122.001		•	Prevents counting votes by the same voter for more than one candidate for the same office or, in elections in which a voter is entitled to vote for more than one candidate for the same office, prevents counting votes for more than the number of candidates for which the voter is entitled to vote	☒	☐
TEC 122.001		•	Prevents counting a vote on the same office or measure more than once	☒	☐
TEC 122.001		•	Permits write-in voting	☒	☐
TEC 122.001		•	Is capable of permitting straight-party voting	☒	☐
TEC 65.007		•	Is capable of cross-over votes	☒	☐
TEC 122.001	HAVA	•	Is capable of providing records from which the operation of the voting system may be audited	☐	☒
		•	Is it easy to choose the appropriate ballot style?	☒	☐
		•	Is the number of ballot styles available on a unit limited?	☒	☐
		•	Can you cancel the marking of a ballot after starting? Explain how.	☒	☐
		•	Is there a way to properly secure all ports on the system?	☒	☐
		•	Are instructions provided in the documentation for securing the system?	☒	☐
		•	Usable for curbside voting?	☒	☐
		•	How to setup or modify audio files	☒	☐
		•	How to adjust volume	☒	☐
		•	Does the system have any RF (Radio Frequency) communications?	Yes	No

	•	Parts of the TDP and other documentation mention use of modems with the system. It is not clear if this includes or does not include RF modems. It is also not clear how this functionality is disabled although use of such modems would take the system outside of the scope of this certification.	☐	☒
	•	Have representatives of the visually impaired community evaluated the accessibility of the system?	Yes ☒	No ☐
	•	Test both early voting and election day - all functions opening/closing	Yes ☒	No ☐
	•	Does system include sip 'n puff for accessibility	Yes ☒	No ☐
	•	Does system include paddles for accessibility	Yes ☒	No ☐

Texas Real-time Audit Log Review

TEC 81.62	•	A central tabulating device must include a continuous feed printer dedicated to a real-time audit log, which prints out all significant election events and their date and time stamps. See VVSG 2005: 2.2.5.2.1.d: "The audit record shall be active whenever the system is in an operating mode. This record shall be available at all times, though it need not be continually visible." 2.2.5.2.1.g: "The system shall be capable of printing a copy of the audit record."	Yes ☐	No ☒
TEC 81.62	•	Log error messages and operator response to those messages See VVSG 2005 Section 2.2.5.2.2.a & 4.4.3.d	Yes ☒	No ☐
TEC 81.62	•	Log the number of ballots read for a given precinct See VVSG 2005 Section 4.4.4.a & c & e	Yes ☒	No ☐
TEC 81.62	•	Log completion of reading ballots for a given precinct See VVSG 2005 Section 4.4.3.b.3	Yes ☒	No ☐
TEC 81.62	•	Log the identity of the input ports used for modem transfers from precincts See VVSG 2005 Section 4.4.2.g.1-4	Yes ☒	No ☐
TEC 81.62	•	Log users logging in and out from election system See VVSG 2005 4.4.3.a.4, 4.4.3.d, 6.5.5.a & c	Yes ☒	No ☐
TEC 81.62	•	Log precincts being zeroed See VVSG 2005 4.4.3.b.2	Yes ☒	No ☐
TEC 81.62	•	Log reports being generated See VVSG 2005 4.4.3.d	Yes ☒	No ☐
TEC 81.62	•	Log diagnostics of any type being run See VVSG 2005 4.4.2.a & d	Yes ☒	No ☐
	•	Print any attempt to tally or load votes that have already been tallied or	Yes	No

				Yes	No
		counted, identifying the precinct or source of the votes and flagging it as a duplicate		☒	☐
		• Print starting the tally software (e.g. from the operating system) or exiting the tally software, or any access to the operating system.		Yes ☒	No ☐
		• Record if a printer is paused, turned off, turned on, disconnected, and when reconnected.		Yes ☒	No ☐

Optical Scan System Review

			Yes	No
TEC 122.001		• Preserves the secrecy of the ballot	Yes ☒	No ☐
TEC 122.001		• Is suitable for the purpose for which it is intended	Yes ☒	No ☐
TEC 122.001		• Operates safely, efficiently, and accurately and complies with the error rate standards of the voting system standards adopted by the EAC	Yes ☒	No ☐
TEC 122.001		• Is safe from fraudulent or unauthorized manipulation (physical exam and review of manuals)	Yes ☒	No ☐
TEC 122.001		• Permits voting on all offices and measures to be voted on at the election	Yes ☒	No ☐
TEC 122.001	HAVA	• Warns of Overvote - Prevents counting votes on offices and measures on which the voter is not entitled to vote	Yes ☒	No ☐
	HAVA	• Warns of Undervote	Yes ☒	No ☐
TEC 122.001		• Prevents counting votes by the same voter for more than one candidate for the same office or, in elections in which a voter is entitled to vote for more than one candidate for the same office, prevents counting votes for more than the number of candidates for which the voter is entitled to vote	Yes ☒	No ☐
TEC 122.001		• Prevents counting a vote on the same office or measure more than once	Yes ☒	No ☐
TEC 122.001		• Permits write-in voting	Yes ☒	No ☐
TEC 122.001		• Is capable of permitting straight-party voting	Yes ☒	No ☐
TEC 65.007		• Is capable of cross-over votes	Yes ☒	No ☐
TEC 122.001	HAVA	• Is capable of providing records from which the operation of the voting system may be audited	Yes ☒	No ☐
		• Reports available by precinct?	Yes ☒	No ☐
		• In order to perform a manual recount, can you print cast vote records for a precinct (including early voting, ED and absentee?) from an individual DRE?	Yes ☒	No ☐
TEC 127.154		• Does each unit have a permanent identification number?	Yes ☒	No ☐
		• Is there a way to properly secure all ports on the system?	Yes ☒	No ☐
		• Are instructions provided in the documentation for securing the system?	Yes ☒	No ☐

Appendix A - EAC Certificate of Certification

United States Election Assistance Commission

Certificate of Conformance

ES&S Unity 3.4.1.0
Election Systems & Software

2002 VSS
EAC
CERTIFIED

The voting system identified on this certificate has been evaluated at an accredited voting system testing laboratory for conformance to the *2002 Voting System Standards (2002 VSS)*. Components evaluated for this certification are detailed in the attached Scope of Certification document. This certificate applies only to the specific version and release of the product in its evaluated configuration. The evaluation has been verified by the EAC in accordance with the provisions of the EAC *Voting System Testing and Certification Program Manual* and the conclusions of the testing laboratory in the test report are consistent with the evidence adduced. This certificate is not an endorsement of the product by any agency of the U.S. Government and no warranty of the product is either expressed or implied.

Product Name: Unity

Model or Version: Version 3.4.1.0

Name of VSTL: NTS

EAC Certification Number: ESSUnity3410

Date Issued: April 4, 2014

Chief Operating Officer & Acting Executive Director
U.S. Election Assistance Commission

Scope of Certification Attached

Appendix B - Digital Signatures of Software Examined

There were 1,641 files on the installation media provide by NTS for this exam. SHA-1 digital signatures of those files were recorded to confirm continuity of the software certified in this exam with that tested by NTS and certified by the EAC. These signatures can be used to verify that the software used in the future is identical to that examined during this exam.

File Name / SHA-1 Hash

File Name	SHA-1 Hash
2014-05-19 Unity 3.4.1.0 SentToTX.decoder.sda.exe	EF1E31FA16E817827F4C95CFC8CFA310D64C445E
2014-05-19 Unity 3.4.1.0 SentToTX.sda.exe	14C19CC77F27148F017BC32328C9791732C2075D
Key.doc	D5D86E09CEA53D18F88D222AD44D2F3481C62E2C
EssCrypt.dll	C773495CE71E5D75F2853873DD33F623280C34CB
EssCrypt.lib	D2BDA064991CEC27C63AF8109B10ACB13E9A25C5
AuditManager.exe	6BDEB53C20E12E866596E65B02043E5065C72EB7
CB_650.DLL	A9EBFEED43B01C963915C47C5743CAC9C02C9441
CB_650.lib	7D1F618DD049B773EBB1BBB7B781B7372A357767
cb_eagl.dll	980198141012F803525A41531951C391160B0FA5
cb_eagl.lib	C7702EFE035CFAD1CB3F6C564149F95968C942FE
CB_HPMCoNG.dll	38F1B5E44AF59BC4D633335047F3DCD40ECD7573
CB_HPMCoNG.lib	DBDC582FAD7F8F29A1C255002568A4796782A44B
cb_m100.dll	4267B95A15A4AA8CAD44450F1ABB9524843837CA
cb_m100.lib	B1095543418183035B3C8C03D7C0F898230BF2A9
cb_peb.dll	2C508E17C643AC7258BF9ADB35CA05BDD0AE2F02

cb_peb.lib	98D77EE9AB4EB90DD018AB3EA7AD58E53823569A
cb_rand.dll	6BBAE3C007ECFC919F63D11A7EC460A1D635788E
cb_rand.lib	98C7F63EA86D3BADE2186A7FCCCA75AD00F555E9
CB_XML.dll	C12439F8C53053D8711F196D134AF88DABB8DD99
CB_XML.lib	ACB4F1528216F1D6DDEC0B8BCD270867F4CEEDD2
CB_XMLConv.dll	3257ED9779F55FDA933EBF0BD82EC2D4DB93138E
CB_XMLConv.lib	B2203605C1315477835CF024ECF7315EEDA2DBE4
CF_Utility.exe	EB2B57C79E9EA49E88C8AED3BC157DC3223045C6
CRCDLL.dll	AAD7E2520EBBA67DF3ECF789CE614DFB7DBB04B3
CRCDLL.lib	4D1B4298482B139753265AB6F125F229191EB4D8
Bdm.exe	284EC4C53E7A85AC8DA9FFA3EB34A67834C03B09
ElectionPackager.exe	EC8A771D2C6B6ED1A0BBFD8350FA48E97FAD54E4
ACUCFG.cob	B5F87D03A97B00DF64AAB928B89431BEED8C5140
AERO.cob	1E29AF6687FD5DEFA6F2831E874A9FBD9733B9C6
AERODB.cob	0B60B1A45DE161194F5437E214385487ACAF6CF3
AS100PCM.cob	21FFE7CC993A58EFA50E9B2FFCEA4BBDBC3D1302
AS550.cob	BCAEF12DBAE9D62BF7B48B186D01ED5ACE2661AA
ASCIFILE.cob	18F631C75CB2B8A17D279180C557E13E860F3F51
CANVASS.cob	626DB10AA782041FA64E27CF0EEDEC75CB85BEB8
CANVASS2.cob	D27B3FD0A2C7150B124BFB885BC84DBC3ED7052B
CASTATE.cob	627CF0D2B800ABBEAC01E77FC49B3189E52660DD
CAXREF.cob	5F68D337C39D9F8F0D81AAD3704893913F3C2D1A
CCRESULT.cob	3014E5EDDF43E4A14FC831CA623220A1C5B99518

CHECKERR.cob	185D121080F829ABFC4AEFAAF6CF8046F94FD16F
CHIDISTS.cob	4F37AB435E1B960EE9D6DF1B2DF05AF06F6BDF22
CHNGELEC.cob	7CF12CFA6FAEA1774856D551514CD2FF5C6F7D44
CLEARCOD.cob	23AFB3196C87E88937FF30549A7557319DC9BB97
CNTLFILE.cob	2871841C558FBDEC553072D3AB09A22A01EDE384
CODEDBAL.cob	3ACD0E66026C4ED4A6D00DB2DF6AB3F581929D0F
CODEFILE.cob	536E9CC0AD725D6C46B695785DB4BAD4B1B9F90A
CONTDISP.cob	401A9C81189E04A9775B97B974541B9D4CBDCFEF
CONTEST.cob	1793B385A3E67664DF5407A6EE4D3C75EA209A2E
COPYINIT.cob	730034BF37F2C557F5C2DDFBAF0C88D6DAE17F15
COPYRES.cob	9DE8F904594A778E31C9FE47752DD269AE3FF572
CP.cob	3BB294BB082B9C8DC450059D265AC03AF5CB628E
CPYMERGE.cob	C20FB6B7C31864D55B6856B0DDB317ADF06C0367
DELPRFLS.cob	890151974C26B544A59EB6CBCEE4DF750C2DEC06
DELSFILE.cob	1A249A53D8366D8BE9FCE4EC45B50A2D5F9A3B85
DISPRPT.cob	34C0A600F7441BDFF90E90BD8B9472F8B0304A32
DISPSUSP.cob	DA51C32DB851BE6677553375BA367B98C70AE74B
DS200LEG.cob	88EA0D9DA115BAAC36952C75B0608878B490C17C
DS200STK.cob	B6BB3E8F6E683CAC5B22134B31C6665C8A59851D
DSCAN200.cob	BF05B76EBE2B8BF276514CE26E92A2AC32D2EE5B
ERM.REV	2956959F591BB29B20A599449EF9A5FCFAC89B6A
ETP4C.cob	5B78D7021E70B59F961D600D7391A47CA2DFAB0A
FILEIO.cob	9F9F3288648F49411FC377100956695859F7D615

FILESEL.cob	E8ADB55631CBEFBBBF7EE35FC08F359428203B18
GRPMAINT.cob	B0251F911D28623621D97242331C0B3D650296E6
GRPUTIL.cob	C2108CA95D1067C97F70C8C6F5A74937A66640A3
HARDWARE.cob	2D17883DBE71621D535F4D3F4F9495E37E0CECA9
JURISCTL.cob	60A6863B3BDD321F18A6AA7017E2B4924D6E1A98
LASTATE.cob	6F4C6C190E06BBBFBBE5E7C3A3EA8F40F6ADB9D7
LAXREF.cob	9539ECA5DA08BF8B681A6DD48919B8ABDEF7AD23
LOGIN.cob	B9F134C0DAC5C4E0B9D3C9D364C7AE8ABDDCA8D7
LOGIO.cob	D1060AB220D1CC8A0B4C31906F0BD50EF0DB8128
M100CARD.cob	3BD9B27C767F62A51C4D2BA93EA3A5944D8B8CC6
MERGERES.cob	567B99E9EC7857A7B87EE74C09C40495DFD402FB
MNSTATE.cob	61D5D40A4DB2CB8968E7559069D42DC73754F382
MNXREF.cob	BB348C625E4CBAC35E97B7FD6699E8D69CF09138
NAMEMNT.cob	9149A2910F8587E33FCE07D890783DA550F5303C
NCSTATE.cob	01ADDCC20373CCFB60BBC074B1B1A546A16D886E
NCXREF.cob	6EF26D581EF0B711AF2E21990E2448FCB3FEFAFF
NET650PR.cob	0CE6E35F280CAC324957779141296424B5103727
OHSTATE.cob	B206AD9554653C559507F068254A29ABE9C23213
PA030.cob	D2A63710085E71986BD8AB243393D4B4E1F126FE
PA030HI.cob	D6C14D1924C619B21E4CF2E0D00222D2AF29C47D
PA045.cob	112DBC3A2AB064D3DA8FE78DA3F2B2F031EF9218
PA045HI.cob	521D68CE0959FCDE5CE20458822B6234D3B6B111
PA047WEB.cob	AC947F49FE66CB7309255DAF5194740D919D5DFB

PA050ALL.cob	DA2C4593724734791F84EA876144975618CCCAC6
PA052.cob	B5B98F5B9222C6CC5F42C402255C567FC3EC10A2
PA060ALL.cob	544ED414D81F99DDE1F7D2E1911168EE0948B17D
PA068ALL.cob	519B4E7F0EA47E1CC6D3576A83E4ADEF31BB80E3
PA086ALL.cob	783199D4ADA51E66CE9A544D846F7EFAB503560A
PA097ALL.cob	4E9E009262E05906DA9C685FAD305968BB7D0C24
PA111ALL.cob	3F3EF29C85FFD0B775E2E699B6DE38DCDDE7E23A
PA112ALL.cob	BB038CA9BC8EA28B63FCB02F7756B80B636672F0
PA1133PE.cob	262AB6C292C334523E5D84E52FBB351630573B3E
PA116ALL.cob	477D50EAA6329B34230F1952B10A8716EBB15876
PA117ALL.cob	87CF2236DA3FC45D673639D099AF4945EB811D98
PA119ALL.cob	6679587ED069A77172ECA375AECAEFAAE682B064
PA135.cob	B9DD9B8629F1FA87ED619275940A0233CC44178F
PA139.cob	6B79FBA8A3581D24DC5A0828E36BAA3CDF8329F0
PA139CAL.cob	236555C594BE92620B5EB198B1D04D01204C671E
PA139LA.cob	6E6CFB21BBECCAE810624CA10AE5983726DBE1D1
PA139MN.cob	DD08B0B89CD9B025A697BF186803BD40B292DDB3
PA139NC.cob	C476414E65F625464C7EB385070A1ED115EA9E77
PA139SC.cob	09E73E543510CE72DAFCE1C0DEB1F6F163A68F73
PA139SW.cob	3127EC87A5506734FCAB5C10D78522BAE14FDAD9
PA139WY.cob	DB1A5E1D8C908CCA25321CC96B08446DB2800E9C
PA140CAL.cob	EC703988AD70C24B1430976720D8897E02D77FB9
PA150VTR.cob	0BC0CDB50A7C7B285700491F115C56DF12CE94C7

PA151VTR.cob	5041E33CF3FD145ABC38905A7110294BC3E817BE
PA152VTR.cob	152BE6B800F0C3B2DF9E1385E01BFAC856B9444B
PA153UVT.cob	78FE673851631CD46094684692304C6E9CAECAD9
PA153VTR.cob	AE32C245AF7CDA8317ACF3B8C556236BA5B12657
PA155CON.cob	39B61B1A94DF71043FD18B369DB9AC73CABA412E
PA155UVT.cob	F9A3DEBA637B2B6DFA3D5D7C9EAFF703CEBA5BB7
PA155VTR.cob	DF557488C9454E716DF2022AAEC2718AB976D14A
PA158VTR.cob	9ED429817F7F67EDC619EB7911CE173CC375A204
PA159VTR.cob	E5EF9E777C39C5E092188285DCF87DFE91903EFE
PA163VTR.cob	1EFC10CFA7B74CFCC3187FD565F26C2051157A51
PA164VTR.cob	6FA7947C907913E9B8D98FAC32CEE1C843913B2C
PA165VTR.cob	001DE7A1CE97D31BB93B175F7247F4CEA2373D54
PA166ALL.cob	5AF1D9C1E00F9D3E2D1B6010C0FDB4B614AB96AA
PA167ALL.cob	74FB2DC68EC6D7888EC80F7DD175F69C1FA2FDE4
PA170ALL.cob	0DF1320B233D07CA33E79BC87EE89D5F9E53EC4E
PA171ALL.cob	C4EA92E16702CE58AB508E8C8AB62AABFA692668
PA172ALL.cob	32BAEBAE138051F1DA1D9A3787CB4EEDD1BC45EA
PA173ALL.cob	E19881FA1FB4E6F5004B91CEC350FD59FBB42B5E
PA174ALL.cob	599239F2BB89E974C284CBE529F5E1D650D75A0B
PA175ALL.cob	E29B818D7F779428CCCF894974BBE44AFDDA69A4
PA176ALL.cob	437180F5EA8A8862B057A28766F071CA3F00B9C5
PA177ALL.cob	C671C4521936E02ADE9CF41A126A996128F75378
PA178ALL.cob	710B37FC4371323F1C7856D90ED0BE820AC7B7FF

PA179ALL.cob	A54FEFA4EF0D321C3879065D5F69489732A4170D
PA180ALL.cob	51AE445F87EF762474C5DB220654B00EC755AD8F
PA181ALL.cob	BDCA269079408B9F2ED2298F52A5F42AD94FAA05
PA182ALL.cob	2FFED0A60116102613A5B850ABA60C0297A00187
PA183ALL.cob	23A415E0782BF6BE71363A7AF66DF2C8B9BADC84
PA184ALL.cob	9C33E6FADE1BF2EA21286751DC7FAF61C45A1A96
PA185ALL.cob	9A708761FF3941C4E312B4F9A764888AB9623347
PA186ALL.cob	4EC229AB7F60F3FFE35E8F21CA34A11278FD8577
PA187ALL.cob	46D5A622A9CE9E895BD7B6E3129360A3B012FA5A
PA188ALL.cob	A2B082494162EC368E9B8B22AC08A9C88F9700C0
PA189ALL.cob	A2B26FB793EF883BA9A5D9FC70AFF1E76516F314
PA204ALL.cob	465A2474C43B4283C03B65A991ED386C5D0EE4B3
PA205ALL.cob	F1630AF31059125606038B343ED0846FE536A259
PA30AALL.cob	D76AB953480937126559AE82780D7DAFFF88E3A7
PA44BALL.cob	998BAD626BBFCA0363AB070D43C7EFF93D19CBCB
PA45AALL.cob	2D628865AF66825A94C561D5E9E71F9480AE643A
PA47ADS2.cob	2D46AC1A9B1EE45330F85856D6AA5F3BA26E26D6
PA50AALL.cob	D80A84AD8784EF4D8AD397B810D169B1B403384A
PA50B200.cob	7A7C899123DA0D8A165D1154C6D084DD0DB81FFD
PA50BV-2.cob	739AAD69C6C0D113BFCB48CD4752EB1DDADD641E
PA52DALL.cob	9746CF1F6D83DD2046A9192B1FD4F6C4F9043FC1
PA52NALL.cob	BC3C0EA902A9C6D86376CDE042353D6F112C9F7F
PA52S.cob	C9816B873EBA0E1D45A5BCAECA2179742105B4F1

PA56A.cob	07FC252177891180DA6EE28B25169F69D868C9E7
PA68AALL.cob	E7E562A548FB9BE04AA7352A6388E304B523A83F
POPUP.cob	68DBFF027C12DC6AF4F483702910607C628901F7
POPUP2.cob	5B4A561F58340481EDA0451554DA71188A939596
PRECFILE.cob	CD54C30F3EEEF05C47B5EDAE28BC76829CC81914
PRECINCT.cob	8B7B2B98CAB9EBBC82605F217CF92DA9B4C2E2D2
PRECNAME.cob	D0CD3923D989DEDCC52358D45985BC6FE2270E9F
PRECRES.cob	35662CB789634B9E6D712ED28C0C31861FAB40BF
PROMPACK.cob	02E03C7394277F8DA429C57986DDACD3697DA02D
RDPCMCIA.cob	8166B205D6C27B688F60AFB817FA6D99071820B2
READPACK.cob	F4DD9C2E6EA09A54160864487A23997842458B35
RELSUSP.cob	4B1D2E526DD722A8FC24CB232317122251EDDAEE
RESETDB.cob	C2D6D230D6F62998FE2508AE9340543EE4E657AE
RESETLOG.cob	24802A80E03416DE4698B54E06BFA568165BA2A2
RESETPRC.cob	1A83722A3916428545049BF479BB8A78BAA2014B
RESETSPP.cob	6ADE568633F623C0D5310A8CE883F4F7826D1E20
SCSTATE.cob	D90153C166EDADD196D2257B8C64E22730A6C16E
SCXREF.cob	B416213D7A78684E7D1825D4BC10A45BBDF77D66
SPR.cob	5FE33F99F863530E63A5E7E804D401C6DCABEB53
STARTLOG.cob	42137A0559A3335F141F49D3DABD1BB53FB28909
STATETRN.cob	F0B757C4D87B569C6D3C9D25D7E6305614FEFD7E
SUSMAINT.cob	D06340F846BEDA136417D42498665AF48C846D95
SWSTATE.cob	34FFAB4D12ADF10DFE9707215512906490B01F5E

SWXREF.cob	33923950061C980550B8388A56A477B3FB825F6F
TO47A100.cob	63B838C35048FC0240E548DF320BBD726547480D
TORASCFI.cob	02486AB8FE4EF59A6B11F1624A0C0402CF872EE9
UERMMNGR.cob	56FE40FFCDBEF331FEE15B97138BA3E699E702F0
UPDELEC.cob	1E3363893E300E9496D7896FBEE8717D2221960A
UPDETP4C.cob	51B32D770427F7377837FB444BED358BF5503C8C
VOTRONIC.cob	177EEFE8D16164EDD89F44D3DE2400D1A7ABE3E1
VTRREGIS.cob	BF4FC51D07284BC146102A6C169B88954862F4F4
WASTATE.cob	B95CB041B892539FF8D3FDAC62FEB7211059C363
WEBFILES.cob	DEA80E6A29A196A54FC816AA083072225D3C6847
WEBPRELD.cob	9E76EFAC8571FBD2F84C0ED1991CD723270FEB5E
WEBUPD.cob	38069325691C23BDD6117EE314B486458E528EB5
WEBXPORT.cob	698764EBCAC7FEB880866E4157449EE55925D0EF
WYSTATE.cob	BABE20BF3B251E2CEB3A22AE386B94F2427DE880
WYXREF.cob	B39BF30812442EA836926447A3CF5550BEBB793E
ACUCFG.lst	79FFE692CC334CC4AF3722180D0C1DD3DE55C044
AERO.lst	DF7E0669505721BF119B43B948BAEC5E3662CB40
AERODB.lst	9C7943915CF47DA47CDEA8EAFD86F52019D4B782
AS100PCM.lst	7E0297DC116112B42783B5971BC70A50E46C4BDC
AS550.lst	7093813C2373BCEC8F5B0E0A5D65461B4584022E
ASCIFILE.lst	973D10A9A19ECEFF4559FF9556EE505A6C91538F
CANVASS.lst	C597483906D5F149DDCCE4194845588C85059724
CANVASS2.lst	6FB0238AFE4A60DB8B711EFF7D785FE30C424B1F

CASTATE.lst	E765A431E6B8D3D21E16B6213BC1F890E80926BC
CAXREF.lst	10CBC6E759BA454E66404B2BAA26A376776E637E
CCRESULT.lst	22A1F2EF2BAB7256D3699D380D1EC201F5334F8C
CHECKERR.lst	A30FECF2EA11575D979421A89396D97D41813D0E
CHIDISTS.lst	DBC4F562FBF0763B4CBA33082E7645661AF3CEE8
CHNGELEC.lst	61C494CBCA6049D647998ACB2313F274750DCE55
CLEARCOD.lst	CD681DD6995F37A2DC2338A5B35520FAD1925741
CNTLFILE.lst	510B6850FE1F846849FC7E47ED6BEFF7379086FE
CODEDBAL.lst	559EDCEC56212154DA21D707F6135569A380CA57
CODEFILE.lst	BDACD8BFDEB977CCF87C85A79496DABFD0EDF1F3
CONTDISP.lst	16556BB932CB386A6743A9536E3D1C382069DDCA
CONTEST.lst	16EAFE82C1A78392D75BF54F2533C68522B6353D
COPYINIT.lst	32C8D777A23DBB0BC3BFEA5ED53AB44BF56ED703
COPYRES.lst	DFE5B754847EDFDBD72C4CD8A2D12222C5849275
CP.lst	7DA27806F2B44E8E93A9FF5911E5C75641B920B2
CPYMERGE.lst	5123BD74DD8A5B718C0F147E9EFCD5CE6927460C
DELPRFLS.lst	4815DA05D5105041DC238E224BB0031479063C41
DELSFILE.lst	50F8BF6208100D48D032F51DD12A9DFAD438C945
DISPRPT.lst	E2C75A163756D6AA95D333ABF9766F46B47339A8
DISPSUSP.lst	98104BF0F540109560AA46AA459BEDC6EDFA47EF
DS200LEG.lst	3100944356B47FE7C4524B4A754D5D5DBFAC2DE8
DS200STK.lst	24FDB86B1C8C9689A89CAFBE2B068A7FCC338CC3
DSCAN200.lst	A87F6B031B2CC57CEE04024D97D1F57CFDA3F633

ETP4C.lst	AB5E9FDAE87040DBE107CDDB8D7380DD38B4B6EC
FILEIO.lst	65A74D2B5ECFB1747ABA3C367766B8DDB8BB0660
FILESEL.lst	A63696BCAB8A8F43D29D5B57502F94EA3D9075B5
GRPMAINT.lst	45C771632B83D6B3719C440DD2ACF390724392CB
GRPUTIL.lst	34CD7A9E8F4F751945533589D6819B7710B8D66C
HARDWARE.lst	8B8F6971ABC73EB94A705DEECD3BF9F13A3EAE69
JURISCTL.lst	E37AF8DD3185ADD88A782C4DEAC84B3133BBC57D
LASTATE.lst	E3BFCB755376ED50C92D60AD40D2128087050F94
LAXREF.lst	BF59E4BF11D6A1667D9F26C733504DA1E1E0DC52
LOGIN.lst	FDE10E37C8A8456CC179D74275AEA6DFF17116A1
LOGIO.lst	913075896B5054996C5CFB4B4F32F838E8CD6E41
M100CARD.lst	2D569C04EA1FFD8ADF87BCC632F20703AD01F5B5
MERGERES.lst	64F86800FCD2B69D60B648450450453E15BE5F59
MNSTATE.lst	E6EA0FE1FBF0C4436B4BF4BED11C9E4E6B9A0185
MNXREF.lst	8875134A67317C708CE0712F22FD593E3BA0641C
NAMEMNT.lst	967D07CB1C20FF1837F8BD43A0E4220574F54517
NCSTATE.lst	9878E6D086FE329D5F6E8FAC49990FD37DAB5CB3
NCXREF.lst	CD0A5782533B38CA3C9CFD949D0BF9D010883E3C
NET650PR.lst	FDA7D13EE5D50A084CFAE234AA80FFD8540B5367
OHSTATE.lst	0F04DF93B3E79CC47B98059078F317BCE0AF4BE7
PA030.lst	82BC1C01724EC83A3638C6597465463E5BF9535A
PA030HI.lst	CB6B8364BED5B6240FF3FB3B7C2A5488ECD69443
PA045.lst	9CB45B3C675D60806166009E9D67C325A66DF8AC

PA045HI.lst	50C7848BA17142A9337F527736191CA38E06A5B2
PA047WEB.lst	7F04A545431562129B523F17DC0B30510A505568
PA050ALL.lst	B9BE883A83838C91A4F9717272F248E667CEF54A
PA052.lst	25B7A5917368F3D81E3D9377377A5D6295AD8279
PA060ALL.lst	3C73D453CC656BB33467E81E82DC768B1050DCAD
PA068ALL.lst	DB494C571789765D25C5C8FECA89761D27C78013
PA086ALL.lst	E02FDF41077EBB681D39627D26E9AFC68B28F045
PA097ALL.lst	AEBEA04A76CCA1797BE17C0F31ADACEF9F056C0F
PA111ALL.lst	0F3FAC810BDEFC43C7AAF8A1D0FC4AF84194FA82
PA112ALL.lst	DED73DA133E36A283A3AF697384F22EF262424EC
PA1133PE.lst	B4B558E4C7D128AD140DBA301F659239EFD554C4
PA116ALL.lst	C4C8F60C11945E6873E00C71282A46FE7AB75E84
PA117ALL.lst	595364DDEB872ED9A526E3D776568129F7B21CA9
PA119ALL.lst	9E8FD810424488E1D0A98FD3FC208298F6C51D33
PA135.lst	440C59A51744F9A9AD8E0EE2C896C49F16C792DD
PA139.lst	47DF6C42C63C920A07ECCDB6AAC09C7ADF67BB19
PA139CAL.lst	2F2D53864DAE3CD5757FF2845284E66FD3DCBB16
PA139LA.lst	5B0B63634525D4C6765E9026F49BDE3D95D7B477
PA139MN.lst	809F31901BAA5DE6945F04C1A0734A13EF1AF8E7
PA139NC.lst	E4153E2FDB65B1A1CC5E76CAE3ECAD7166DF6153
PA139SC.lst	B6EE80CF34C0DBB9C34BFDB8BBDFB04974700370
PA139SW.lst	F5152F362707A52ED4036EB2277EB269328E10D8
PA139WY.lst	36D320D8F1BF291D6CE9AE4E68342DFBBDF43988

PA140CAL.lst	232D0E6EB6CBAF68BCF61164501A69F045CD7220
PA150VTR.lst	2CE449FCA6303E673E426EB6B90DC57A0C675448
PA151VTR.lst	C7DB2D44CDF5B8EB9078FBC504924DC8E79FD813
PA152VTR.lst	BC4B7DAC9B9EC40A69C0D6B0A3AAEDDC69F5C968
PA153UVT.lst	1E0D9DE113A07A0B2F131643B0BF0B772D100FF9
PA153VTR.lst	9B24350B56159F4121501C5E44C669696E0EB8FC
PA155CON.lst	FB716AD6AA43EC7DC18943787D29DC401D8E0ABB
PA155UVT.lst	1DC78A4DD6F00F04282CF17754A18E71EA69B911
PA155VTR.lst	D0F38D12F08B4CEBAC20B2E9107839616BDF6833
PA158VTR.lst	EC44D35B2DC9BC8017A76941F02EACBB136F3E4C
PA159VTR.lst	B12E9DB3429607C1116119CCF85951A2337DA6D0
PA163VTR.lst	E2CB0320668E4F0CBBA26304998D1318E59BD631
PA164VTR.lst	C8509C469771EAF7BCF59BDAB0478EA43876CDF9
PA165VTR.lst	3A45C2B120CFF9EC0D4211292172DBEDC7DF6E02
PA166ALL.lst	AA330798F200011C9759AD036BEDCDC86B8FB119
PA167ALL.lst	A8D5862F349087774566BF7FC8B40FE7C4DD457A
PA170ALL.lst	96E309AA557C23DE633E082BA24E120A08DB7B60
PA171ALL.lst	9FC4AB169FD830C255887F5CDD9D4BB8EFE184FA
PA172ALL.lst	E27E549B62134716E00708EC2D072490DDADC118
PA173ALL.lst	A1693207DC0E74E548264354445FFFA5F5F39F55
PA174ALL.lst	B23543A190D6396EE0641D5758DA020CF4241029
PA175ALL.lst	95330DEE7581C824AD6B41DC9967E4C4D85D6770
PA176ALL.lst	0727749D0D03D9B649BA083EA19884B207C8CBCD

PA177ALL.lst	AC27C7BBC02E21BA2A3AF797FFF9C6E708527631
PA178ALL.lst	9D2FEA0C6D0250E5DCEC79301815DAB766E51BDB
PA179ALL.lst	EB3BBDC68CC0238A06BAF9B4E4B356FF9BFA5E44
PA180ALL.lst	4A488BB3AD5D7D54BF4CB4EFC45FD959883416F6
PA181ALL.lst	CC1A8BEFF5402EDC30D8CCDC8131C75AA9239829
PA182ALL.lst	D2439F11A6CB27577E7CA517D3A498720050DC23
PA183ALL.lst	3757C2B038F3DF0FED6F873439A22298724EB154
PA184ALL.lst	41EBA1665B7C0B3FD8F36155DB6CF83128411217
PA185ALL.lst	AFCB98785487C220C550072CECC953B80EEBEA1F
PA186ALL.lst	8B6BE15225B8D80FB845D24E087A33C26AB632EB
PA187ALL.lst	2571C97DF7F50D08938EDB98BE1E53634EF6DBB8
PA188ALL.lst	3503FFE9CFDBD55C317B5DCEC9856B8E17CB4F31
PA189ALL.lst	B3CF52162E68D8A7DEEC088C25AC14D675F67169
PA204ALL.lst	9063A6DE0536DB6FD580B848D9016181C35041C8
PA205ALL.lst	76CFDF09B017187CEABFD8CF819903264AB11C35
PA30AALL.lst	031BF3FD3DE5D9C63AF272115956DD94D5300FCA
PA44BALL.lst	3C22A297A4BA327EE6E46BF51EE5F53F82B84660
PA45AALL.lst	758989829FBC970B9E3171D58FD777182C75C0E7
PA47ADS2.lst	AED533ABBEE3FA95AD606FA67E8C1DAA3B354330
PA50AALL.lst	EDE28B4E422D387A74F9F2F5A4FDA055C26C27FF
PA50B200.lst	6D6FF8CB2FBF381AF4680504FB352D73526E1A12
PA50BV-2.lst	03C8DC7A564B0EED00665ADE97DBDF67B1803EA8
PA52DALL.lst	D4FFE5D6B9E8AC6CBC67E5DF31175AF63EDCCD73

PA52NALL.lst	C139BCF8E55667C066FE0A78D84956DE5FA71E57
PA52S.lst	334EA8CB1DB18C6608EE8A17C503746F032130EF
PA56A.lst	BA674A83779F466A5C27E7508D861A5BA466971B
PA68AALL.lst	D759FC73F3D74876A13E9DF93A55F0061FC929A4
POPUP.lst	E787AA56CF7C093B677678E9AB3A90868BC6802D
POPUP2.lst	E8321C8392B921A7DF563C24C6CFC6D77FBDA4E0
PRECFILE.lst	C2A48DBB472E0C478BC550EDBBE51DEA6B76B0EF
PRECINCT.lst	EE25FEF14C4C1B6750CF30C545708BE278A62125
PRECNAME.lst	BBFE0E36E165B2AE2DA30F8BCABCF0D72E7A7202
PRECRES.lst	A3F5CD188654E2014A641F5279F49BFF78FC760F
PROMPACK.lst	E33538A5BA0F44E08C814B696FDD7D996B2278EE
RDPCMCIA.lst	237DCD7C482D62A25169297BDDE73683CF907D53
READPACK.lst	7CF4798BDFD357F1FF7453CC2809CCB370562002
RELSUSP.lst	995418EC99320022E5DAD171DC0390DE566EEC64
RESETDB.lst	771BFB654F7B851C78AE8FE0DFD48A02FBF74450
RESETLOG.lst	C16F5ABE909327373D60132179E8F7376D1A06E3
RESETPRC.lst	6BA6452CADD2E9DCC90A80455C18485BDEB68F48
RESETSPP.lst	8B375B9043FFAE9D99F035163E2B378B079100F8
SCSTATE.lst	BC3DFB08D36B23643B5CC1AEFD06DEC6C01FCECD
SCXREF.lst	EF5EEC97AC744DA549942815B1281711E9311013
SPR.lst	244679FC85DB98ABC5904BA0859DDD9209A2936F
STARTLOG.lst	1441DBBA4CD36502D12CCF68E9D0DA02F59070D9
STATETRN.lst	BDEC2A3EB8D55A3656440E9DAA16289E3D8E0049

SUSMAINT.lst	CCA15893CF4067282BCA9F4F1C0805EDAD2AC373
SWSTATE.lst	0B0D639FFCF7C12FB83321F134F211E09116B1A5
SWXREF.lst	6DB144B72785C111FB82AB91FFB26730C07E7BAB
TO47A100.lst	5E6799A0B91166BBBACC70B103820AFD485F737E
TORASCFI.lst	9724EBEA7279D1EE6E15BEF84A77134D65A2591D
UERMMNGR.lst	C39112687F55F1AC6F900A461DFE8381CEB9D616
UPDELEC.lst	0D90006F98B06FDCD0275F1CF0712733B5DC541D
UPDETP4C.lst	FB34A46210660CA867873806BAAE4A749AD2C4A1
VOTRONIC.lst	6D1659CEFD1E58A92EDFA15F110E4130B98A9C7C
VTRREGIS.lst	35A53081646DF14FCFEE573BE46F7AD5B17B9F14
WASTATE.lst	921D125DE4A632F2E8E304D9890F09998534937B
WEBFILES.lst	F148E9405282D28C8E8947CD7C93AB440CC272F7
WEBPRELD.lst	805C6648C7EAE8529E6806EA06228C2A8DF99B84
WEBUPD.lst	7DE040B25710D7C407EF8C435F8C80266ECECFD5
WEBXPORT.lst	0EB6ED07768E2D41A9B6D85BB58D1F231C1F16F6
WYSTATE.lst	FFCB5D1A68A0C3DED2B19A36AD6F7645A58719BE
WYXREF.lst	C668F86D7827A89A6CB27FB3674DC4F97A4E83B2
ERM_UserShell.exe	4E19ADB89F8D083A8514823A454D09B5992873EF
ERMXMLConverterDLL.h	B85210AE357B97CD8075B64AC039F43B7315F630
ERMXMLConvDLL.dll	56983ADA102C128B17C4B3A21249D57EDCC48649
ERMXMLConvDLL.lib	890ACDD43190A1A3471F576A9A909B94121E4AA6
SFTPDownloadFiles.scp	992C40E1F1440FEA191B1899784FF4462B677C2F
validation.cfg	EA5BA7B2C31EB143F6F8017E5D33ACC5A96AF032

DataTypesPollPlaceCollection.h	D9F0AFCC0C9EF781F920AEC249B71466FA225928
ERMXMLDATAInterface.h	1377D97D7ED3D93FE6F4218636478D9AB4522CE7
ERMXMLDATA.dll	D890B38DE86D10903EB60D014F153E8281EE0087
ERMXMLDATA.lib	5D7B82B8159BDB616CE59D9591F6226F9C8B67CB
BlowFish.h	51A4683C412805C7DCFACCB5C1B8DFB5214E8912
BlowFishDLL.h	40CE6A37F621E16F3F13DDC08F8C66F3AAD0E1E3
ESSCRPT1.DLL	19A59C7CB20C27D9EDD824A76A7DF4895A6E4CD6
ESSCRPT1.lib	4DB849D3C6F6452EA8442CA76DBD2F348C477371
ESSCryptLib.h	66266E6756964FB42DF589BE2918FEE43DF103D3
EssCrypt.dll	479B625718B0B677E29931D14E35FEF85D93EC6D
EssCrypt.lib	F5ED5EDCE28EE16010B340F1754AB88C15FDD517
ESSDecpt.exe	BCE615812D03A5D76EF7430FC47F1CC847DDC954
ESSEAGL.H	87FDA27CFFBAE5B63F472769C7D79CC058E01B95
ESSEAGL.dll	39A5D4505FE4B0D011A73AD7A776CB3BECBB773E
ESSEAGL.lib	F155BA31AE0962D04FA69BD426480A00104A5C2C
ais.exe	8FB2C3C5243AD4BB87DB5DCEC7F4640CA699A1C6
ESSM100.dll	6D43B9B8C0D27DA4CC5AB54DCA4F07AD7F787BBD
ESSM100.lib	2E280ACADBD517DB5E35F5439B393F20233E75AA
ESSPCMIO.dll	3502A7AF7D8BF39C649D619CE0687676A7B6BF8D
ESSPCMIO.lib	636C909C3938549EA1669E15B8347FB7D44D09EF
ESSPEB.h	9576188FCCB7C679222878AE5842EE5F6DF52CB9
ESSPEB.dll	D93C44AC42755E7307C0FBD228506C830BC5FC4B
ESSPEB.lib	298122A9F642B267DF7BDC322C046032C6EA8DC6

ESSAttribute.h	A6252FFA8712E57D5FC8A42CE2B7A24198B9EA3F
ESSElement.h	D710C21D58E9FBE9CB87265DF3B5A9A8C6A9C14A
ESSXmlFile.h	5BBBB0DC80DB3E82B0D64175BE6B97C703A90320
ESSXmlUtil.h	F7DC18039485B2CB6DE0FE7EF9022CF960CEBA24
ESSXML.dll	AC2CD22DF49DDC4B3FA3E2E61EF224F4D5820799
ESSXML.lib	29C139F6AB43EBC4720DBF8FBB0CA6B10D059D78
InfoZip.h	D87C4B6DC507576ADC0CE0DABC915879B92792CC
unzapi.h	7887A74AF0BEF6A3298BBC73D3B31B57BBEA0C09
zipapi.h	69C1B64900D9B7A2441F3266A31A4D5691A0AFEA
EssZip.dll	F268B49EB0849B9C950011E9101AB601640C3A36
EssZip.lib	A02D8EA0DA4C9D6B87587AA5AB8B4C46C73A185B
Events.exe	07B64F0985D6116A8D7257C8A3D3D140A0A90D8D
GetAuditData.exe	8FE73E8B4745E0DD02D8B6B5AECEB0504488D85B
HPM.cob	3E423AC2421124A6E3A5491696AEC3C20DD4333F
Hpm.rev	5AACF9761EC04DAC2F6C217DF1D13394AF09099E
LOGIN.cob	B650F8085EBF839FA04F3CD8590245F400F84053
PARAM01.cob	BAD0D4E4288835EB8D169EB616B64F8E1D20820D
PARAM02.cob	5DDF5BF6AD38969F6E44A3C2AE0F75CACC454ABB
PE001ALL.cob	C3A1A27B29E6FCDF27003164484D8EACA16994BD
PE002100.cob	12794CCAA24D8393A008FA5365B34A1281507CAE
PE0023PE.cob	DC311D686CC00A5BFA84EF74B8A745CBD33B7F82
PE002ETP.cob	A626ADDCF7C279102798FD74D5887BBE79C08D3A
PE003ALL.cob	3907CEBF0EA7938D3400BDAEB07D75188E622D09

PE004ALL.cob	68EE23C93580A37D4CC5228F0442093494AA6342
PE005ALL.cob	DF6681F892B723EF9C59D498EEBDD87CADF777A9
PE006ALL.cob	988AAD4E51A4EC215379F018D27B4E9F2D377115
PE007ALL.cob	FF91D0FC83C5A43E123C0358475198F1C2B3FF2D
PE008ALL.cob	D7F2AF5A7724A7E45623D5C52A4F0E739D3DA17B
PE0093PE.cob	A4720A5CB6A941525116B2EFE02EF95770648777
PE009ALL.cob	C003C134A419B5EC7DB9A198A65E7BE941E17363
PE010ALL.cob	D6082F023E9C60F0E1CF21C5DC12621EDB97B1A0
PE011ALL.cob	C72267C1CE2D6E3CB351DB44E68B1B21D8947346
PE012ALL.cob	9AFC410CBF78EA08E0602609FB2AC53969D78A0F
PE013ALL.cob	10FA9E4C6B24362CE393892293545438013849E5
PE015ALL.cob	41535E7EC30F3F5992F85EA3282996F7CD0179B5
PE017ALL.cob	B40BFE0F37A0E9C7312125DF090E87905B4A8091
PE0183PE.cob	FB2FFF07C2CF2A07088B06F789CFEF8CC3285E92
PE020ALL.cob	8FDEC7E59D33ED0DD06D8E7D32197AD5A3E6AE7E
PE022ALL.cob	40D7542D033E7F267C1F19D973172A401C1D35DE
PE024ALL.cob	F3E6AC76FEAF66C5F71671B8154731A5A0E5EE61
PE025ALL.cob	9EEAA7F8FF12E79950CB320BA6713F19EA124E4F
PE032ALL.cob	77F49F28C18CCCF2F782C940C8CCB3CC9608D8C5
PE041ALL.cob	0E893DB9EB08F2CBD3D205C8B58508BE6BA35E5D
PE0583PE.cob	3161630ACD82983402D8079997EF80CA960B25C8
PE062ALL.cob	1B8BA24E9AAAAFE8FB6C2B363EE37149A844128E
PE063ALL.cob	FAE37F9A9A0DA8A736D4A03D157AF61F25A571FE

PE065ALL.cob	42B7C485F5C3230D92E26C60ABF4AF85A21B304D
PE070100.cob	3DA17CEEE15ED7A92E3AB8CF6A4714A258BA42F0
PE0703PE.cob	785CBF8FDB396D11395519BEDCD18DEE53A2ECC1
PE070CES.cob	4CA8A21F437ED4108D495F377E279A80AC6B9C31
PE076ALL.cob	1A4247E2E0F2BD0E71FF97D0C9D2DF91F14DBFB0
PE07A3PE.cob	89FBDD10F61BC2A9D594DEF06F94772B8434142E
PE07AETP.cob	0FD076D94240C0F61F80D79C23173D554666DD11
PE07BCES.cob	492894C16A35A0637B25347BEE0E822B04474487
PE07CCES.cob	0448B5116138358BEA8DB08AB3CA7D9AF95F0693
PE07ECES.cob	192F3FBD0A69E1A5121C5820672353D18E93A532
PE07FALL.cob	E771E996A8FCA7DE64D13B823E0CBFA2D2334EFE
PE081ALL.cob	81101DC68CF73B61B6C7062D7B883983FEA1C692
PE100ALL.cob	AB4DF2C4B7A30E36F4DE8E63CE62F1B94D27229D
PE106ALL.cob	E358E567C0F6374BDA4D9DC829C24AC0FB4E6D64
PE107ALL.cob	73AE41EBA187721ACA08918445BDD643BE9F17D3
PE108ALL.cob	F66658F294678DBF30B44F22A8FD27BCEE3D7830
PE109ALL.cob	08A2C7E7AB14B4FEB4895D8ED6DF9D1DD38F66D7
PE119ALL.cob	710189113A7EC130424C6869180B8EB2F30D266B
PE121CES.cob	EADB673298CE80E16242A5032A04654DA3C79E7B
PE122CES.cob	5EA3C98D609979A2E62BDB83C0B5988D14C97E4A
PE123ALL.cob	42A0DA5841FA42C17E69EDCBA49516551A4F0360
PE12AALL.cob	64FB5EC36CDEA1A0A4B7AA0B1771E84C5F134AAB
PE130ALL.cob	989E9FCE134C4A4E9E7478EFF306B5248452BEC4

PE131ALL.cob	3C55AAC946583B569586A437E94ACD0907D51F0D
PE132ALL.cob	E3D71E2B4B839D818CAE4AEB70BF3A2DC102ECB5
PE142100.cob	FFE293B6E2D8812D04FC27DD192968AD5BFC2597
PE143100.cob	2ED34997019EBC3C3596FD3F934067ADF518692D
PE147100.cob	6C7812268D8EE303EB83599903160DE5A34C1E0D
PE148ALL.cob	ECBC64F67388451F8CCCEC92FD4F0B3E124233E1
PE150ALL.cob	E0A0F2C1F2B8586B97B61506C3A35D3A8D95D96E
PE18BALL.cob	8B8FC652D08143E115E3A11AD48E55A172FF27D6
PE20AALL.cob	1565908AFAA055DD8609D7BB3DA511AE7B93FD54
PE25AALL.cob	5B0B2458E14D896EBCAA4F8418B46D336A63DD29
PE25BALL.cob	F06D0908F195DD9DFF49BAA846ABD2EB1F96F415
PE25CALL.cob	70933B6261B42D50FFE474336F4354C37B864AFA
PE32JCES.cob	D68DD495344C603790735DF6CB3958A5AD8DBE54
PE32K3PE.cob	F3D413D518A20D79E93A47A27ED22F6E371AD7B9
PE32NCES.cob	04E283E694EA98E005865AF6C04B0134EB25EAE5
PE32QCES.cob	997A2B6B68D07D2954E4B38D1E198A24C480B488
PE32RCES.cob	5FD3D44BFDA2AAEBD8F3C26A58117DD593C155BD
PE32S100.cob	84DF689F8C7D2F55B22C6AD5959730DA9FBC1475
PE32TVTR.cob	F8303ABA4572BA4AA8C8741C0F6C86A37B812482
PE32UVTR.cob	AFDD4A9B6361394873BCD50D7070EF10E0F6C826
PE32V850.cob	1D56F924F1979F4AF6EA8D2536594E771DB1C714
PE33BALL.cob	56DDECBEA430374F0261516EFE9D0D405B89B562
PE33D100.cob	225986383B5F50F37A06C4F4565C3A06DCA0E282

PE33EPEB.cob	13B36158C3A649DC4F1778B2043A0E7CAC1B523C
PE33EVTR.cob	5822896153C3A29126ED61A4FD34D3B4C9B0D04A
PE33F200.cob	72637C55A2F47175E76DEBAB3D9D7D7CE94A4078
PE33G850.cob	714B9C0C1E48E66A33F9F1A28115A9470E198F8A
PE34AVTR.cob	6FBB11670CDF7D12FF384F1117F5219ACDF9C683
PE34B850.cob	F3EA107D212551B0736F15597D596CDA9D6B7307
PE34C200.cob	E2D1AF4DB97F62E7BE5A424086C7A02BD19074DC
PE81A3PE.cob	50ACB0028C95F565902D8B537AA7669476B2B561
PE81AALL.cob	8BC5D6990E4C17E464AE98C8FFB295B11524E25E
PE81BALL.cob	12FB54CF0EB1B317FEBB04FBF7748428E380DB6B
PE81C3PE.cob	818167A48EA73D55717C03BB169B5609CC716F99
PE81CALL.cob	D2E57C7BD74B4BA860ADE125BE45C39F5AA4BCDB
PE81D3PE.cob	852C9946DA2F2139FB404F2FCFD6DF0381A4AA0E
PE81DALL.cob	7066A4C9CA0E2D219149636CCBC0E42450A8CDCE
PE81E3PE.cob	7CBD3CA0B1162E75404645C88FEC79EC857F8A27
PE81I3PE.cob	27338A1A3B9102C143DC6172D767F77B27B7C694
PE81JALL.cob	812980580C24CDF0FC3E52BEC95947BA10FC9435
PR014ALL.cob	A9A00A477B6B57648459456E1784F094ADABE911
PR049ALL.cob	008CF47C078441F58092CCBAC2C8A3C2CEB63232
PR064ALL.cob	2E3443DA07127B8728E21E1D6B8EABC74320EF47
PR069ALL.cob	EAE6FDF1356EA2C8FAB0053612C6CAFF8E2F51DC
PR074ALL.cob	2411D547119BC717C54F4FC47983189ABA0F442D
PR0923PE.cob	BF8D8BC3A075CE8A9476E90E7F79AF31BB9E2909

PR133ALL.cob	B6A0CD418DC8194DE03BF8E97969B284B1FAE9DB
PR49AALL.cob	FB903EA8593B005603A3CE872E3C263613DB0BBE
UHPMMNGR.cob	E68F6EDD80858254094C5F3DF6D8EAF5AA97F3C5
UT008ALL.cob	989FFB426FC2E6A3E618486A94155943305501B1
HPM.lst	3E94937BF0011C90D9CE19C9B0471409A7A95B3D
LOGIN.lst	A3B2D30C6812E1F7086EC7111BED94E339D44181
PARAM01.lst	866D00D536D02C819538787A404CDDF2AB6A56B1
PARAM02.lst	F09FC5D93B655A483C319DEBCC3739C79DC3D577
PE001ALL.lst	032A951A579AA856F8AE4A9F20647FAA07C84781
PE002100.lst	A5E7606A49D08D1682ADEB3EA128CD71572BA6AF
PE0023PE.lst	03E3836D9087E7A7EA5F185981F8187E33224D55
PE002ETP.lst	2BE91593B643CF268BEF90A4E843D84F0D8C81FE
PE003ALL.lst	C0DDEA0D3958D71D86B7D9D29D4E280B9093C906
PE004ALL.lst	7FF72B629F029D2C4B9A13E859234258E56D7C01
PE005ALL.lst	0DC4C8A9D1E279AC084C9C6B2752F720E64792EA
PE006ALL.lst	666D33763DCAC848441E90AAA14001A49BF09ADF
PE007ALL.lst	71859EDCD89031DD80DF77567E39E0A19E9EDA93
PE008ALL.lst	AD7274832DD10692FA378E64C5DC6929156BF1EF
PE0093PE.lst	28C7A5FC6E22BA9D22ECB072AA824839C634333A
PE009ALL.lst	6B442141B8368920A13629A32C45F92AD15F87F7
PE010ALL.lst	22CDA4CAD71C9E9479DA7437364C14EED34292BB
PE011ALL.lst	074F8E35427601AFB590E2560665953271C92114
PE012ALL.lst	63CCAF0DD9C6858F8A282F5AF88ACB37DB6BB085

PE013ALL.lst	13D0453C5B5BE45004AAD39A760E1B397E5FBA89
PE015ALL.lst	EE38DF3E5C61A3C6123C49AAAA4F3D4CD2D31A12
PE017ALL.lst	FB39442879660F94473269EFB92C7246EC112229
PE0183PE.lst	DFC6794BDD4C4E9EF6B7BC21346135EF0529F96B
PE020ALL.lst	19A5586CADECD19322ED35205A326833B901EC32
PE022ALL.lst	44F7F6B02A15631E0BC39D705B9B7CB43067EAFF
PE024ALL.lst	497FF7EED574BC5952C4F2E26DAB7E709886CD83
PE025ALL.lst	A85AC728B3FA32E990296FFB164572C419E1EA22
PE032ALL.lst	AC31C45D28079CD08B14BCABD74279DF6D8F00F9
PE041ALL.lst	4F2C8B6D9C4DAC6D2DBBD3A25F62FF0537ED81C1
PE0583PE.lst	DEC723F2C61F73107A1E79F925899097E85F8364
PE062ALL.lst	B7821A236AC524588BD14E44ABA0C322E17299AA
PE063ALL.lst	D318EA0F08ECAE46C947B8120D75BBEAED5400A8
PE065ALL.lst	3D7ADC84467A8920E45898511EBD5FB398C4D808
PE070100.lst	D404379BF27004AB36C06E7E50CF0E08CBDD50A6
PE0703PE.lst	2CA3271171CDC346618A137C281E058E4E0888FC
PE070CES.lst	2D285D918D5A8E8C806B1CA2C1EC00FF733DC6C3
PE076ALL.lst	4FD6B7550298A28330B5A7CE7AFD9CE4CFBBDD69
PE07A3PE.lst	0D7A04D67D5CF73F90FEB21DAFDBD7B0917F771A
PE07AETP.lst	A04D3BA493002B13586EFCB693E9CD7FD2410BDA
PE07BCES.lst	BBB9F0B00869BDE1A84C5F6F0A8BEF407F64D69D
PE07CCES.lst	7B07E0B24CC6E9539FC6C72944C837DC61A86C10
PE07ECES.lst	4A886448E44839B69817D42D376D8B3AEDA1F58C

PE07FALL.lst	D8CB108D468323BE6AFD99279F89DC189972DF68
PE081ALL.lst	1457B8B12A81081223ABA044741A30814D605274
PE100ALL.lst	8F85D33A67D1076A7061BEBF9D88D75603069599
PE106ALL.lst	26ED28D7BB779DC84FD3124F7F889C1466F7BCE2
PE107ALL.lst	EC5B31604797FC7007EF38C4355FC3EF20DED1B3
PE108ALL.lst	A3A41092D2ACFCDE68461C1EF2FD184D23CB3BC7
PE109ALL.lst	2E9BE408EF74EBFEE40D93FA38D53F09FD76BEB4
PE119ALL.lst	F32087534D81D0D54A580A9A52002677B6BC813F
PE121CES.lst	962F75D70ABC81197D7147E0BD7C37E64D4404F1
PE122CES.lst	4216B8E6D3542AE73AFD7E29DC4DDCD6BA12192D
PE123ALL.lst	53DC7A4AADCAD573828BC33DC8D13A977DF04EFC
PE12AALL.lst	EBB4E6DD0AF99C191FEECE000773F29938827C81
PE130ALL.lst	17EBBFBB886A6DDE50DB3E39DE341AED2E2C07F4
PE131ALL.lst	9779B0D713A19FB67189F31626254AEE742ADCAC
PE132ALL.lst	122735C6FEEFD91CCBC41CA23AAF3D2C575E31C3
PE142100.lst	172ADF6FFC44DA22DD0B0724C2D107AC61469F6F
PE143100.lst	D8BB09C24373094A447B429D82CD642E9F6C60BA
PE147100.lst	62E7103E190DD66EDD0523F77FE06EAB2F9C7DF5
PE148ALL.lst	03284D3BA5CCD42D9873ECB4B7F32934438DF4F2
PE150ALL.lst	35EE134DFF97919D5EE9FEF2DEFC43E592478809
PE18BALL.lst	A533FCBFC8B19C897C6AEE4F036269722ED805B5
PE20AALL.lst	C4F31AAFAC5BD92F42293F3B324259A01A932517
PE25AALL.lst	B79749BE48FBCAB05F3BE99D6EF9AAD7812EE9A6

PE25BALL.lst	4285DFFD9B7CDF5DB0F0D059AF66771D4952F863
PE25CALL.lst	995CFE93A8D8ECA4542D8637ABD417004850907A
PE32JCES.lst	EF0A024788C4FDCB134675BB894ED8955F04463D
PE32K3PE.lst	73225D005684F770434604DEBF2F744003AF9D27
PE32NCES.lst	2D45C45E11A0650A48C95C1431BEFAA28D62B807
PE32QCES.lst	CE0A17753FB6B7B47EA5E15F21115EAFF55516E3
PE32RCES.lst	859B912994BC854028DDD4E847F198D436ADB122
PE32S100.lst	CCE2A6261514AB0B97CBBC52DDCF15DA74D655BE
PE32TVTR.lst	CACF0E06A3C0AE8FE4DA2F305121EECCB92A48E7
PE32UVTR.lst	DE8F4C9D60A16E12FFE2D766B82341B8F0BB3BAC
PE32V850.lst	EF3018EA223DBC35A7C336653F3CD9AFEA5F634A
PE33BALL.lst	1359BEEA5DA7C3BBC5A431BEFF3DCF1C23816D86
PE33D100.lst	288504AA54F8D7B0627BBCC2062E197B771A0AEB
PE33EPEB.lst	DAEC947F3E528012E86FB129474D55214FA60AD9
PE33EVTR.lst	53D4FA08A92F26380379919F45BD8B74D1810531
PE33F200.lst	1EF72A1F5A1D6F85C09C0DCE61C6362C6CED24D4
PE33G850.lst	B937AFA9CE84ABAD463E3F3A8F81D5EC4CA5AD73
PE34AVTR.lst	381BC45ACA9BF775236BBDA8E7D89FB62C622479
PE34B850.lst	4042E5DB5B476529680ED5C25C856CB7954E6DFF
PE34C200.lst	CE1D4C5F33B042020A416FD8CD448FD9B1525C49
PE81A3PE.lst	ED955AB2E094226CB236CDB5337A14B6EC4645F8
PE81AALL.lst	6992306B7F2C978D1C8D529B33C76E0C91AD93FD
PE81BALL.lst	CBEA55E9225C388970CCC1654630D03FF177FD25

PE81C3PE.lst	4CEDE2D7A121B3F22F21A229EFDA2BE5DF741745
PE81CALL.lst	B73686AFA13EB19C5200E95B97565358C5B0165B
PE81D3PE.lst	D0D7E61FE755B3ABDC6F544D910987D86184FAF9
PE81DALL.lst	42DAB3D6FCE33220FD20A41AF302900D4F5B7A42
PE81E3PE.lst	630EFB32D74EEECB9E071D332A35F91E80506EF4
PE81I3PE.lst	31FF64CDB1387E4EDA4E2BA7DB13A8518FC9EB5D
PE81JALL.lst	FFD934EF6FA40C362D70CAC9925E2FD360493487
PR014ALL.lst	321DD24F475AA9B54B709A81461182FDC28F3FD2
PR049ALL.lst	EF42348BC7E56DFF2AD19349EA0A8B52E7A5B7FA
PR064ALL.lst	D0CDAD08D69F85AAC0A79FF9A1F6A61F4F0116BA
PR069ALL.lst	A74479128113961477CE8B339047F5FB40DAEC07
PR074ALL.lst	FC30B925691F1F8F8580D8F414B5E33994705C1E
PR0923PE.lst	CCA6D94C6C5FC473FFC4A8465B5351EF78F56404
PR133ALL.lst	76618550537F447108FFBA42131366059BBDA797
PR49AALL.lst	6F82B66897D602DA39DFFA384EB9BEC7831E22FE
UHPMMNGR.lst	16EEA0C5611015C85C7812C30350ED19EF8F85A6
UT008ALL.lst	42DF8371A90BA4649214BB9EB1E24BF055F95B64
HPMCoNGDLLInterface.h	1B532F5554E3666FDB12F7716FFDB67A076F785E
HPMCoNG.dll	BAD6B1627DCF4802F4D2DAA343E3A7E613A0AA06
HPMCoNG.lib	CFD93DFD9A762F488D3644A81884071F24797471
Images.exe	8237B232E3286B7622C97143BC032293B8EB5940
LogMonitor.exe	C5A4523D242BE41FD9E378208862313BD7083090
makeIbin.exe	BA3398CBA48657F8FA1474B1660C7218E93196A0

MPRBOOT.HEX	A1E18DF1596B6F79EC150B103A6D114BB2A6940D
mydll.dll	A4B527B186F90839A7A339B93AEC4D23AEBA1A7C
mydll.lib	F5B8D1ACCB8A9BE0E76F047DC96D3A55CE81DF4C
pbmtobmp.exe	48A76318AA7EE08BAF300148EFA61554CB18F1E4
PCCARD30.exe	0F039151C29C509DBE55790AF15C062A6872C036
pmb.hex	C9AAB1AAF797631ADE72E16520EDF6A3588371F4
RegUtil.dll	27B5459FD410888E9DE6EDC1B1840205028BF02C
RegUtil.lib	6B31CE6F6FA1F0D91EA9D410D0C18DB770F4A026
ccme_base.dll	652F5069FEA72F20FAEA001C887073B69C8281B0
ccme_ecc.dll	1A2F71F2AE1B215739718F04B23A6CDF0EAAF432
ccme_eccaccel.dll	0F90EC44C40227D9B59C9DBC7E1E3B51618513D0
ccme_eccnistaccel.dll	6698462AA02D592CF9A5A9C9DAD512F047D289D9
cryptocme2.dll	CC10515599CB629A1137CEDBF68BA0C9CE445FE3
cryptocme2.sig	61174BC0385D8A0E5A697F8E4148FF8114BA13A1
Microsoft.VC80.CRT.manifest	2E12C6DF7352C3ED3C61A45BAF68EACE1CC9546E
msvcr80.dll	9FD3A7F0522D36C2BF0E64FC510C6EEA3603B564
RSACrypto.exe	242CCC84E7073D8F0113C7169B3498787078FE8A
unzip.exe	E1652B058195DB3F5F754B7AB430652AE04A50B8
zip.exe	55C5A72010291FCA2275CCFB5B497DD0BAC11A60
fw.iic	5F724DD804109159C73E5000FDEC7CF5254E602A
UndrVote.exe	14325A4F50400EAC1E262AC148F044CC41E39509
VioDialog.exe	0A4A9BD4B4AF81DBE75C2EC8C6363C485ACBA53B
vioWin.exe	D4AFC68C9DCC68B2E57759991A0316FD9EDACD4C

Init650.exe	22F775BFCD875A4282415C1C0EB9895FADDC79A5
serve650.exe	CA881B6DB367EA2C5550CF4D8BC022BC825B9BC4
0x0409.ini	310395FDE36429B08B615831152399DB7E4267A2
1033dotnetfx.exe	16A354A2207C4C8846B617CBC78F7B7C1856340E
1033dotnetfxsp1.exe	E4DC1493179AC01C508FF1C85D323A36C7EC7BA2
ACCESSRT.MSI	EAB13071E516D00AAABE8E50C42A278E0E589715
EXTRACT.EXE	6D461A06C14F62008F2263EA736D7D5617E3CD51
MLANG.DAT	9AC8D920C1150382B4431D32C010BD5895C5FF3D
MLANG.DLL	7203020843DA53DF054780C41E5C9E79E2462D17
MSXML.DLL	F23BE28E6574C1C04E514C185C2DE175E6C68BB2
T2EMBED.DLL	590B3156E79C0C74A43D706E6A9A291AE59C1522
OSP.HLP	515C166B14D31B2AD64FC5A5D8628A128AA29FFA
PSS10.TXT	8A16C242706F4CBA6A613FAFDE68ABF2071781FF
ACTSETUP.CAB	C23F78E27FF64B1AF8D187C99F730259E179105A
ADVAUTH.CAB	D60D44A6FFD670473B0310CA9DC7C260A608036D
AOLSUPP.CAB	5611169751371AFB6311CD6A52853DFA6163E74A
AXA.CAB	1818D7AA8A1E15D5CD2F20A106F54689F10994E7
AXA2.CAB	CC9E2AD45466FA4071426E50B34F754C62BAA88E
AXA3.CAB	C795FF15F037F009B01D6992B2977AE7A1298B15
BRANDING.CAB	140D6C7657D507255B062D2A474689043D51D3DB
DCOM95.EXE	5229EA35EAB98FB77DDA6233BB001CEC684196F1
DXDDEX.CAB	FD7DB6B82E373EB5E5F95A4F0D964DF2554198D6
DXMINI.CAB	EABF4D82E23EBD3923621156577B1D39168DF2A3

FONTCORE.CAB	781BEA3E0839EFF2CBB51AF74EC6EB487DADA532
FONTSUP.CAB	40127D3F288F8266E7488330F7784FB97453D794
FPESETUP.CAB	43AC3813EECF09A8F3CE08697349F05DD7BE065A
GSETUP95.CAB	AB5DC31BCE482EA40FBF9359ED276866176A8870
GSETUPNT.CAB	EE02286900E7F8E5E369F6120F673A02A3C8DA8E
HELPCONT.CAB	F3366A59253AD3C1A60CF4892B5449456B5F56A8
HHUPD.CAB	3B0768D1CAB290710E25BCDFA0A0DDF5BA8F40FD
ICW.CAB	FC78861D16A9F814D713C72412D0320D8ADD7765
ICWCON.CAB	9D3012F116C050C89D1ED2EA5A749F22C7C62E9A
IE_EXTRA.CAB	07FCEE1B01E2198DBDFC4FA7A53B690007E78B6A
IE_S1.CAB	1D98F0864FDF0C946D784FD533BD2E8EA5452FFC
IE_S2.CAB	020A013E1D5291D15F75CBBDA49221763E3ACD3D
IE_S3.CAB	35ABFA8419884F9FF6F93953F944F989E213CA38
IE_S4.CAB	02CF35FCFE2FA2FC27FEE3EB4235305B960C7E87
IE4MFC40.CAB	3079C1DE006BDABA7B7C469F9FA198F6859B0219
IE4SHL95.CAB	21C955C2DFF515B894F087E0E4220E1B562B18D2
IE4SHLNT.CAB	3BA92E23A2A94AC45997E813B49A574C7B8EDAE2
IE5COMP.EXE	3D9AB767FBDC393D0EC58182C76805ED859BE1A4
IE5SETUP.EXE	129877A2A83E93C4452D6146604E79391503C07F
IECIF.CAB	F360C6A71C34E5E2F92A315ED695D67F1C1F744F
IEDATA.CAB	2DB7D15B0047C9BA8E93C50D8986D20C6932D70E
IEDATAJA.CAB	1FDD4859366A97D4D44720B388B9CDA3BEEEE0AE
IELPKAD.CAB	7EC5974E8F2D705572A7055E964A53F04B4FBC69

IELPKAR.CAB	0E14FBF3FABC633C84DE7C37286A81EA11B94986
IELPKIW.CAB	80410BAC5AB70B9986686A64581B1A5F5FA1C61F
IELPKJA.CAB	A188736A7686814E2AEC4DF8B2B1012D7307A092
IELPKKO.CAB	C1C2A1682308C75679F60CF1F476852ACB5FCAE4
IELPKPE.CAB	5B601685A1421E1272D22E5FB200491315A11477
IELPKTH.CAB	246C422B45B06F7FA2D9DD6E8919CBA50E8A1B3F
IELPKVI.CAB	F779FD5AEC7CC0FA70C4FA6C469EC6168EF35DC8
IELPKZHC.CAB	2B05892248FD37CB5A7D71B676C84F6EE8D94946
IELPKZHT.CAB	2700893E211F400D190FFCA4AF77141AA1AFEAFC
IENT_S1.CAB	B4F3E715DE71CB88D2BACDF014DCC720B7CE658A
IENT_S2.CAB	7807C5F8C06649ACBB18565DF5F088ABBF6B075A
IENT_S3.CAB	65F849DB4D5B50ADC47BD17F7FC3B860862A197A
IENT_S4.CAB	0E400CDD7E5E9340C2E6D7E50C704CF253F2162C
IENT_S5.CAB	1E5DC187F37ACA72D9AC67B53ABB60F0EDCFBC24
IESETUP.INI	B3276C724A43524C6E8191F1AADBBCE96A998845
JAAIME.CAB	FEDA507B9CE0871986298943C9E812DE2526205E
KOAIME.CAB	FE446CD6BE9A5A023A06B859C617DD0F9348A797
MAILNEWS.CAB	0941BA1573E8FE5EF097B8242BBB014ED80909D9
MDAC_IE5.CAB	FD5942CAF064118E8AB8A5040D04E6FA8EC3B5E0
MOBILE95.CAB	4E7DA1DC8E5A649EB95D2F76DC4DD4DE763C3392
MOBILENT.CAB	4DA0463AFAF3FCEC955FC6DF4E7F279924B96370
MPCDCS.CAB	FBC6DC7725D84DD6035693C4ACAB6FAF287A7C1E
MPLAYER2.CAB	53EBE1127BCAC3DAE6710E225D59457705662B04

MSN_AUTH.CAB	6B70B0F79A01B64B041347A8B3D36802EA715870
NM30.CAB	7E16D6569AA9D9FAAE99021517A6065D07685ED8
OAINST.EXE	8F849E4981B4FB7A76249DCE02AF8DC9782782CF
SCAIME.CAB	713B3523E483D98C381716A91D43F2727806D431
SETUPNT.CAB	C0788051C3BF680906CF59792FF4558D92D354AD
SETUPW95.CAB	A68A0104E142475C79DC16368182D1E153EEBB9C
SWDIR.CAB	CCF668494CDB53379EF0EB2B6BB0955C235DB528
SWFLASH.CAB	C908FB01766C47A1BB670F8152C9D4AD9893152D
TCAIME.CAB	45A45D9F23C265EC62BBA9A7E4D9C644FBCC693D
TS95.CAB	0751FDEFB7A3AF1488036EE15A128FC4CFCC6D50
TSNT.CAB	3C5331F547FACC3E548B261429AF61CD146B46D6
USP10.CAB	FFF0858B16575A74095D9E269160BD62B0B42F46
VBSCRIPT.CAB	73E494FC0D7570F85EA82C75FAD719A48E22DAAD
VGX.CAB	00D951A5BFF9A480DFA5026CA7F72AE08FA92A50
VMX86_01.CAB	8C7CD806CB81D0B3DB4AE1B3472BF924E3882BA4
VMX86_02.CAB	A58D581B6AFA198CAF4DCC694745F9D73F61B7FC
VRML2C.EXE	324D019AA32172407ECE6673275467950A866791
WAB.CAB	859302206D8FCEB37A3312B6413CFB128B281888
WEBFLDRS.CAB	E7E0A659AE84953F97217DF403416CB72B61C2F6
WPIE5X86.CAB	75B13BD9A103C6C6C6788118EFC2B2C581CE1618
MSOHELP.EXE	F5F9E1B74F5FDE30931DD491AE21DC8DF21880B9
Office1.cab	5D5D480F9AA787B260B84FB173CB4A31C5DCAC35
OSP.MSI	88C02A44DBA3F0A7612D607C67F6579659116132

OSP1.CAB	7981B26F56858027EB735DD69A3D5357B85C4531
AIMS for ES&S 1.3.257.msi	C0B53B9D57BEE964F4E7EE2E2F1639ABEA09F186
Autorun.inf	D0B67C20ED1B09A741D1A5B55A32DA0BA029E6C4
dotnetfx.exe	BD4A44820A8C888990908599208798E44A4C2E7B
dotnetfxsp1.exe	74A5B25D65A70B8ECD6A9C301A0AEA10D8483A23
ARIALUNI.TTF	D9A78E55980C6DB61D46EDBBFB4FD3589C1089C6
BATANG.TTF	07332539DB82D9690FA93E7BD519DFCB7A3D7FD7
MSMINCHO.TTF	963D293A469E2DD84EF27ED5E731F1ADF5CE8B0E
PMINGLIU.TTF	CD7C8609D50343BAC9D765F5850205B26C620617
ISScript1050.Msi	5FF5D4A846BF87EC7A859B3E2A86A811F9FD3AFA
AIMS.mde	BFF0833CA1D9E6B2298AEACF76BA08CC37C058F4
blank.wav	5AB3AE9298BC9FE84C2046A147A8A3C59BCBB910
blankCant.wav	5AB3AE9298BC9FE84C2046A147A8A3C59BCBB910
blankCre.wav	5AB3AE9298BC9FE84C2046A147A8A3C59BCBB910
blankTag.wav	5AB3AE9298BC9FE84C2046A147A8A3C59BCBB910
blankViet.wav	5AB3AE9298BC9FE84C2046A147A8A3C59BCBB910
CantoneseNo.wav	D682845527B9B7266E65FD2DB8A9D72402739373
CantoneseYes.wav	BBC3F008C7B624939719C76A262C5B9589A6586F
CreoleNo.wav	F240101D8F51E6813CFB099D710404AE4F24D4C2
CreoleYes.wav	6B0C28718026FD1587CD1CD1DD03362FB96F9174
t_no.wav	3BF824F76EB962B406C95105EEB074388E5F3123
t_q1.wav	EF87FCC9897C3CE274D139EAFDF5EEBEF87F76B7
t_q2.wav	A57208F9791CA5B081F80993B76D01BAF9584258

t_votefor1.wav	A9C1E535D39220E6E857C9B84D6D6A7F67AB8832
t_votefor2.wav	52599B2F62C224D17576CDE79E71E9D924DDC1F0
t_yes.wav	43DEF1D6568A166FFCDFC2B5C70617E33E015446
v_no.wav	CB91F12DE1208DFAB382689D14B5B019FF3AECC7
v_q1.wav	7DD6B09D15A8735AB8AB98E689CF2F8005F891EA
v_q2.wav	499304869475F98DEB779F0BFB2D9ACA44319191
v_votefor1.wav	C673FFC6DE39622A1C3B5362B2C9B325E61FA984
v_votefor2.wav	F895B1014FCAE07E495F2383A5DCC171D7278A70
v_yes.wav	59A226A98AB55EC9D7681D008D535B5929D12B36
LangLangCantonese.wav	B0DFB7FF8885F7CA2C3BE58862AC68747D8EA012
LangLangCreole.wav	27F42AEDA3B879AEB6D273A09EC0883A82132201
LangLangTagalog.wav	A6F26D077A8DD776FC8185E4A8C66030A3003988
LangLangVietnamese.wav	9A6C335774FE55879076BDEB68A0AEE3CDEF5565
Nbr10Lang10.wav	10E4003D25D055A2A348AE96DE0EF3E864F65673
Nbr10Lang11.wav	3A7F44C37D82BBC029E68585A2034544164FA540
Nbr10Lang4.wav	DFD38508470FB29EE5589D188A534908B1E18991
Nbr10Lang8.wav	94A68BC96A1AFF70D7733003F5A6CC2B32DEC553
Nbr11Lang10.wav	4C22BF73D91B792F6B010601244C67A3ECEEAC7F
Nbr11Lang11.wav	E38B23BDFCD4AC3E35052A12CF55F0CCAADEB95C
Nbr11Lang4.wav	2E983C37345FD9CA2B07573CF21F6E7261F6BEC0
Nbr11Lang8.wav	5571AE4FD355FA9B79FB4727E2E3784F3A3B86F5
Nbr12Lang10.wav	44C9E44CB533F86C09D6BD81A07BFF78F0392550
Nbr12Lang11.wav	E4C507CAAA86F9250B2BA3CF9712E7C49778EEF6

Nbr12Lang4.wav	093D08EAEABFDD479D6BBEA0E6A6C7FB2DF4799C
Nbr12Lang8.wav	4CE5D331D3581A148B93FCA2AFC2B0B3CFD471F3
Nbr13Lang10.wav	6D08FA9339C48159052BF13D69AC2EA50F2A4683
Nbr13Lang11.wav	0B280E7220305CAB5A8DAE58FDE5FA59BFBCFC43
Nbr13Lang4.wav	73238DE1A9F89E9DBBD07A6B8C2A383208AEB93F
Nbr13Lang8.wav	4CE5D331D3581A148B93FCA2AFC2B0B3CFD471F3
Nbr14Lang10.wav	C54AA963576771065EB9B673B32443EB0F67570D
Nbr14Lang11.wav	E25AF6D4D05BC0EC738614D5702F93E185A30B8F
Nbr14Lang4.wav	575D1625A38A43EF38D4082003BB645AFD9AABFE
Nbr14Lang8.wav	B31AD354E141A10B215F0F633AFA4AA09418A9B5
Nbr15Lang10.wav	A7C9DA061BE1B86F5F6FBAE2E529170978D6DA25
Nbr15Lang11.wav	B9AD54666F6188441066BF46F556AAE470845363
Nbr15Lang4.wav	F023C22463CB1379489480D667CBBF0514252F6B
Nbr15Lang8.wav	DE7004438D398D35E119C66CF847D133F50C8486
Nbr16Lang10.wav	E4ACD8FAC2F71A403D8E84126A6A41A533BC95DD
Nbr16Lang11.wav	73CB7C4EB4C87A71CA7A573ABFBF75BF65FC4B94
Nbr16Lang4.wav	2F0C0DD4E524951B2F7255EBF18476497D69DE9E
Nbr16Lang8.wav	E31164CAFBD6A2C50F87AE800A00C4BE4652E299
Nbr17Lang10.wav	2FCCFFEF62217FBA544C2470E1A935D2E2380A46
Nbr17Lang11.wav	4F85D7B23EF844273DC47612A3A990B3F3F1D439
Nbr17Lang4.wav	71498A8A217EE0F469F88F60B8D1B040C3DF2658
Nbr17Lang8.wav	6D9654ED10E4F8FC9D74630E0DB5BD673D6CA9CD
Nbr18Lang10.wav	6FFEC1FB232270BCDA59889462DD291199028689

Nbr18Lang11.wav	658ADD3E06F65B729568903F76715F8B4EE6D235
Nbr18Lang4.wav	FFA809B70B2DC74E400E558D2C8C0B6C191D4239
Nbr18Lang8.wav	E7CA33E9F986CAB05E819E5AC958AF08883BC106
Nbr19Lang10.wav	2339CA1810CD4787FAAD3F0350129120DCBA6092
Nbr19Lang11.wav	0F1A3136EF428B2C58CA2F106B53506D7D70854E
Nbr19Lang4.wav	12569B405026750B5783114E2FBE59A7FF539E38
Nbr19Lang8.wav	D90C2F0DC2539DC769729509409CCE3B0D290632
Nbr1Lang10.wav	9E82EECA1A196D3DD6EE2AC7E5D6A55D3B2467CD
Nbr1Lang11.wav	1C897A34D44314224D63B925BC8862948AF3570D
Nbr1Lang4.wav	9677F9C2C6CF9CC956348E540DED7A6125A06267
Nbr1Lang8.wav	8180892291E1B8FBF66E9D813DF6EF3BB6CCE94E
Nbr20Lang10.wav	01DF6DC7751D98DAB9DC034A218F002B3CD6714C
Nbr20Lang11.wav	570023A05198A3839602EA49B3548F0E6F5A8911
Nbr20Lang4.wav	E5F2106158C45E8C0422FFFA063F870DF1854B0D
Nbr20Lang8.wav	15BB88E46D2375874E5AD4F0F81F5A9877839836
Nbr2Lang10.wav	10F56A3DD97790F8099F8EDDC2AD64B3F145CB5D
Nbr2Lang11.wav	8B0BF038FFE68DCC0A18E204CD0D0D84EAC2FAA9
Nbr2Lang4.wav	8198F263D5B4C43115536829ABBC32CCD0EC803F
Nbr2Lang8.wav	313D2EE898C1514D7357273E0747E25E52100948
Nbr3Lang10.wav	AC82D90D2E9E8900B81D6FDE9A266C3E96C97A2A
Nbr3Lang11.wav	416FD42CDBB7DCFB04CD7B5B6FA3A7F025666B77
Nbr3Lang4.wav	8EAD780890A71EAF4DA6125ED13C6AB56B527BBC
Nbr3Lang8.wav	7681FD2733CF6BD55ECA189E52A16C83883A8443

Nbr4Lang10.wav	6018BBBB5F945B97E55EA4F6FD214AA8ACB7E2BA
Nbr4Lang11.wav	C4C6AA28500CC2F9506C1DC03C05BE24EEA1DB42
Nbr4Lang4.wav	631CD94AB68FE48B9C053311123C4E7A41FD0178
Nbr4Lang8.wav	6F21E0744F1EABDF63DCDEE9676AF625B25D6650
Nbr5Lang10.wav	B431DECA70C7231B714294095949D1933F479600
Nbr5Lang11.wav	B589559030D6740A28DD8667C8D4FF808AAD4E16
Nbr5Lang4.wav	0BCFAD0223101864B2E0B5DBB5C113F13ECE95CB
Nbr5Lang8.wav	ADA64652765FC7EE4BC94345D04F80A3F2D54103
Nbr6Lang10.wav	E847BF6FCBB695351CC48D05A7EA35E4909D34CE
Nbr6Lang11.wav	5314CD0B621D3FD888327082A937130FFA2D0AE4
Nbr6Lang4.wav	7B065449653429030574BE2254AB356F7020FE37
Nbr6Lang8.wav	05C53B7CE7BBD06AF29756A7C732B3F4F2373703
Nbr7Lang10.wav	03F4E8ACC176B2F2276AAFC3A11258F097D0881B
Nbr7Lang11.wav	3F2368A4DB4086ADABB4B0147F2F3AE62A055371
Nbr7Lang4.wav	7671C40213C3D3B6E8198FBC6773D8D41361FAFA
Nbr7Lang8.wav	30EE844A4960E258063D7811C989889E5CEE86AE
Nbr8Lang10.wav	B83E6C2513D0BD57F0B9E13508422A7CF00BDC5C
Nbr8Lang11.wav	6C38ECD8D3CCA0D696F37E231CDDD47D4F45272D
Nbr8Lang4.wav	CE6AAFB6467FCB628F4510950EAFAA926E4095E5
Nbr8Lang8.wav	2185BD49ED6CD02E16AC31BE99FF1D12F013B8AA
Nbr9Lang10.wav	FE68F8AA93755D4B4B28571377672FD13D39A82A
Nbr9Lang11.wav	E9B05ECD36EBB01CE2F17304C243FCD28B7323BB
Nbr9Lang4.wav	4205BD65F6AED877B7B462E290C834EE97F44C60

Nbr9Lang8.wav	4252E096E5F93116C6069FBBC3AAA49DD1EBB6CD
PromptCant10.wav	07C904E50E5660AD3897AC85E3EA0AF68937031F
PromptCant100.wav	D5CF4009083651AAE94DFEFCDE7883824391B0FD
PromptCant102.wav	88CA83A8AD8AEAF578904789228FB95CBCFA0699
PromptCant104.wav	B3F924A8A08149E40FCEC25215A02A7367963087
PromptCant105.wav	B012CB6737830255758A37B94B405C793E21EC89
PromptCant107.wav	334B023A0E27A6DE6D30298A697A31EB67998305
PromptCant108.wav	72B6AF4E2F926C875A87FDEAB110F67DB9619986
PromptCant109.wav	87C47BAECA640370E428C3E4837C8C2B1EC74935
PromptCant110.wav	28B0BB1478EC13B8298285198519AAA603103CBE
PromptCant111.wav	70BB887114611F78BFD4E00F82E262C7DA03C08C
PromptCant112.wav	6715797AF5933A64584F5229FC1384A4298CD5FF
PromptCant113.wav	46B90CD1E969BD94DCA86C97D2E9C461D4C7DFC7
PromptCant114.wav	C15A1C0587BC1A9E69366037FB61CB84EDE6263E
PromptCant115.wav	FF12E7A7A263A2BC4A276D7B78A107AAC7891563
PromptCant117.wav	AA80936E2C147A195FF4E68AAF2B1A692842E345
PromptCant118.wav	6B98B28277CEECB07E89C7C56AFB619EEEFAD083
PromptCant119.wav	FE56603ADD26F3755FBB4037DAAF5DDD2FA06494
PromptCant121.wav	446C2D67EEBEB7C0DB130A84128C90A9E59FB8B1
PromptCant123.wav	34032C7D8A708593C786E1074DDBB44D6818A780
PromptCant125.wav	9468DE25903720A83A355CD4CB055DA47F5F4A19
PromptCant127.wav	F5A7BD0F4C27057429DC2B5F7808C426659808A1
PromptCant13.wav	13F687705D65A2B8D2639D77D40833BBEBBE0B31

PromptCant133.wav	562D4DFF41EC8A88FF8A960ED649E4773C4DC72C
PromptCant134.wav	FA2D4203276F41B3CBE37E226981E6B5897EE2C2
PromptCant136.wav	7C753AAFEB0A7ED857D96EF1A2C3F065112CD5F7
PromptCant137.wav	F9586F2B826826F23BFEB2E690077D786CC31790
PromptCant139.wav	DC453B176B8C8EE3E32A173EB744C3A33AD61F3F
PromptCant142.wav	1A58209DDD95E12A4D2D03872A528C80057DCC5C
PromptCant146.wav	91AE0B67FEBEF704AC2E1AFD7F4F470C75C704FE
PromptCant148.wav	574329C1284F73A605982A29E3C26B0F31B296E9
PromptCant15.wav	6553ECAE41304925CE230CFCB15BDBF073660EBC
PromptCant153.wav	0F758E137E2A104ED55DE362EDF89BB944401F68
PromptCant154.wav	0B1A8D57F1C9C1805F50D5BD6C12EA28F3AC432C
PromptCant155.wav	1CF9606AAA7C40FECC9D44B3529C010A83545CBA
PromptCant157.wav	872804399103F841F5EB77344BC0ABD835634FB7
PromptCant158.wav	92B8C1A8F226A989B5AB257064D221EAEFFBE727
PromptCant163.wav	62157F7E72529E9992ECC7B7BD388B8250A78423
PromptCant164.wav	14E4364F70448EB1E6030F549A0EA22B21358443
PromptCant165.wav	6B0371C9BFBCE4B0911156E76B773F45B4672D0A
PromptCant166.wav	153F6AB0D9C93A000FC392B1ECDA1356B4271EEC
PromptCant167.wav	5237A056A865860E327C3C70FF1FE5A79C056354
PromptCant169.wav	E3DF701AD774360832736EF2D68035EB1CB5FBDE
PromptCant18.wav	F266587DFD57ECDA2EB15A5925C94BF0EFFDD3CA
PromptCant19.wav	A0419B7B0778FEA817120F58AB658DABDB2B51FB
PromptCant2.wav	4FF481CDF9C49070A6863E436EBDAFAA67A4D730

PromptCant21.wav	C700417E29C8E6DD3E8AC173E2878174786A3388
PromptCant23.wav	AF38F87BB8EAACAE513C31E6B19D3932E1B8A4B3
PromptCant26.wav	EB690B8ACB811106145EB920111F8040589B7FB7
PromptCant27.wav	2A5E8ACF08FD7C4F984B811B847481C9E89C1021
PromptCant28.wav	079284F081EF13E66581A7F0460270777F50680E
PromptCant29.wav	B47D174A95FD7D73B1B2592C44146AA08EC5D6E1
PromptCant3.wav	7E3B01D66BFFB67531FBDFAFA9DDB203C20B7E45
PromptCant30.wav	2CFD902E1C7B2190A9C5508D2887FA3681387383
PromptCant32.wav	64609E9B78B297623D8E12F985E7ECEC6643388C
PromptCant33.wav	79DF4F553B2209233645133D60ECBD361804DA0D
PromptCant34.wav	E3217E52D7DE11E34B66BEC1A6EDA3FEECEE1790
PromptCant35.wav	60D3B48CC074EA7E3086C4AA3EE13241F5464714
PromptCant36.wav	F2B9A8416BFE8FDAFB5F15BA7837545E33065AAD
PromptCant38.wav	407A8B7D7F4DD1F356497BDDC3979687C0A71A9B
PromptCant39.wav	3CDDF0CD3807C76949C5DD9C6F0A8037986C2BCC
PromptCant4.wav	8BAB5B2AE238C0504E88664485A91D7469F61D7E
PromptCant41.wav	D5C9C63460F646678102D322EDA4E21725C45437
PromptCant46.wav	DC7FEA3AAFF212D925E2215FAA4A334816D170F3
PromptCant49.wav	F869C1988182B4B1B5909D24ADA539E6F45394A7
PromptCant53.wav	691CEFB28B46BEA858568D10EC646034DC97BD7D
PromptCant54.wav	AABD4A0D13B755F3A2A7E1C5CD1CFF08137F74E3
PromptCant55.wav	991C0821A868D84A0619BEC8DE589517554D2B4E
PromptCant56.wav	B7B0FF378748A059EF3DC1B1FD302E42E3ED5C58

PromptCant57.wav	169C71B863774DDD3D8F51412FFB4BAB7357387D
PromptCant58.wav	AD31015F7D04CB922DF4BF0F6DD68BAB8F61D2BB
PromptCant63.wav	B78E47EB0C7FF69D9080A98EF9B69D4AB4FB7EB8
PromptCant68.wav	CA11B4EE9D14D4F22640CC3F3235C1E26C6F5D53
PromptCant69.wav	07C79682158D83C7B723D9AE64F6A25AA0E352E2
PromptCant7.wav	B34DE944C08658E92188123B4C76D424C899B29D
PromptCant72.wav	18245730802403D02012A439ED9B527BA40E1E64
PromptCant74.wav	BEB443BCDAEE89C252F367C1DEA2F1D7F782991B
PromptCant77.wav	FE7FE5C32E31B7CD189CB44EDE5260A07F8E9CB5
PromptCant79.wav	4B5A8C8D1DB8056DD24EEA009F143C0C671B9B93
PromptCant8.wav	937C74C12A6833429AEC61028D8C0FCBBB20859A
PromptCant81.wav	1368236A69E462D7EA0A6A57D1FB6FBF2F3594E1
PromptCant83.wav	A98475779083224E2DB5DFF524693D6D009B2BDA
PromptCant85.wav	7B29FBE2871BAC2EB266882EDFDE043ECA49BDA9
PromptCant86.wav	51A4C775E5456E79D1B3CA58E96FB29F0B0A2256
PromptCant89.wav	3490B88B66E8D1ECACD0AE11DC73A7CB54554292
PromptCant91.wav	F6E00533340274FB053BB3BC18DD2AD43F439492
PromptCant92.wav	593C7FBF9B2ECC7817FC833E1917F657BF05CCA2
PromptCant93.wav	4F9B93B909EE7A9FC88B0DB211D8B3883CF5DCBE
PromptCant94.wav	8A34F4AD869B4505487ED778A4ACD802D20C6908
PromptCant95.wav	F84E43AEA08E7B3DC4D2704723C7462DC563E595
PromptCant96.wav	10A09EF76C4DFFF4DEEDF1D56B2E865EAD4F2810
PromptCant97.wav	CFB27AAE1EF6E2897619ECBC75F97C5A4E6E82F3

PromptCant98.wav	A81D0BF4ECE5F8C5C31B0389B17A2C838C6CC79D
PromptCre10.wav	4948247CD93973F7AC004462204AAD9B4D75A683
PromptCre104.wav	A32DE61601ADADFD3F8FC55C8A9FF1E9A4548F26
PromptCre105.wav	077BEDCE120C5ACBF09858ABE15E194788A1B497
PromptCre107.wav	819DAD681C0829B4B41EC345767B2DC677123E09
PromptCre108.wav	A8730F2B76C2F9AD6EBE85553CFC44880A2A3FF8
PromptCre109.wav	56A234FF693FE65452D78F1BC5B341F0774C6F78
PromptCre110.wav	A326BC3101034BC0FFA417E9338DF8B418063059
PromptCre111.wav	6B0C28718026FD1587CD1CD1DD03362FB96F9174
PromptCre112.wav	F240101D8F51E6813CFB099D710404AE4F24D4C2
PromptCre113.wav	40596B31917E1DE6F8BC0A73841AB9201A193C43
PromptCre114.wav	D3CC1A7A60CEDC3091A705BAA44A51F40EB53CEF
PromptCre115.wav	11576C019842EE01693D8C5BA27ACD1A9B1E03CF
PromptCre117.wav	FDB72EA27EE861BED80AAACEA26036EE6BC9E843
PromptCre118.wav	E359D903313C793EC986125BBEB9B865ED0E6109
PromptCre119.wav	D6F9698D2A17C9ACE155CD78B826C734491AC50B
PromptCre121.wav	E17F99DAABD2EB4604DEBE4B12B4E8192EAB316E
PromptCre123.wav	4B99F0FCF163C9431DFDCA0D40F67A16CF87338B
PromptCre125.wav	0E062EE9204C78467221373C473D48C6FE46F553
PromptCre127.wav	E4E69228D70228F4F81C3157093D4E80D3227C9D
PromptCre13.wav	210A23FDD98A101D618F8AC37EF8596667377365
PromptCre133.wav	3A009E7DED48FC272B8500F1C8F23F8D96248CCB
PromptCre134.wav	C372BE2D5DF0586235472543D9E2ABB90E55FCC7

PromptCre136.wav	55377EA7852502C87B437A8B79BED51F3CCD4A9B
PromptCre137.wav	0894A9811D41ABA2DFFFE42ABF736A45914ACA23
PromptCre139.wav	F0BC454BEDF69808CB8A5FBA5356022A23FCE2F6
PromptCre142.wav	5BE136AAFF96A39AB90B3AD696CB2AD3803DDB05
PromptCre146.wav	AE8E437A39E965B71C09A59C0C2F461A2F750D8A
PromptCre148.wav	24A145B55E0E40C3D15C5334D866A8A35A78906C
PromptCre15.wav	96E09BEE889A5182070B7C3DA954D559C2C7E40B
PromptCre153.wav	B123A85A35145280737510EAD5E20C139246F98F
PromptCre154.wav	DD2523DD09B9C7BB90C939A24FDBB012735621B0
PromptCre155.wav	3A45EDD6DA5DC7E87B9975B0E780E343CA8EC285
PromptCre157.wav	7230EEC46E4E64A32BEE8ED334517C1D5C3D959A
PromptCre158.wav	D7915D677764383300433F47BE82691528799418
PromptCre163.wav	C53A569B898B0CF7C58071A174DA08B116B9615D
PromptCre164.wav	A4C031EC213622E6913D8B7FC6E8AA10D9D34C93
PromptCre165.wav	B37E83EB1998101781B3A4D18EB7488D0D741A11
PromptCre166.wav	B9FF7805DF352D085A0B5F310CE13A3B01336368
PromptCre167.wav	CE69BA56DE5EF6232EE35D6F6B4BCDECA2E63075
PromptCre169.wav	EF9B56E1CFB399853453258595D736A9CCFDF433
PromptCre18.wav	5F6172ACBC6E033E413E38E75F2BB774ABD87690
PromptCre19.wav	60D720892460658F5D6AD45AC7931D9F11200579
PromptCre2.wav	EAC213BB7057EF06603DA05E6DFE46305BC0CE68
PromptCre21.wav	621B40FA1404A48E5F896EFDB747A6D094F8C7C1
PromptCre23.wav	E15D4708139BC3DEF2877E4DAE3177407A5D6E6F

PromptCre26.wav	990AA3055ECB55744E939F72148B3C4CA256B982
PromptCre27.wav	B486FB99EE35FFD1B8BBEFF65F905D304B32A7F2
PromptCre28.wav	03AD518173A84DDE3F722A90DEA56A1C0054EEE2
PromptCre29.wav	8D1869E21B62FAD258AF8B8B14495339748653F5
PromptCre3.wav	1D74F8B0C37F0E4F57512637F7B1D1F51DCC811E
PromptCre30.wav	58A31A335F4FE09DBEC92042E1AA1ECA4BBB7026
PromptCre32.wav	A14EA800F56BE844BEF7266141EF26C4B0867910
PromptCre33.wav	790B8C4E973CBB4832FDB7C7CF51754EDB0C67B1
PromptCre34.wav	7E3C7F45545A1DED9AB49CC6983C13A4C77F6699
PromptCre35.wav	A970A42C10A116E42883A87C0D713815AC8842D5
PromptCre36.wav	D90306EBCA20AE0173A00DD1E5A5DB11ECD29CA4
PromptCre38.wav	EEED43A7AC67660E33AE9AF2EA30FDCC63CDE644
PromptCre39.wav	E4140E4CEE4A368ECA80C5D142DEA214CC086BE0
PromptCre4.wav	4D5BD88BDC01CE2169DD4CB5D67F46DAD067205D
PromptCre41.wav	3CB2009BECCF49E1921B03F374DF44B6DB13AD1D
PromptCre46.wav	3ABD3F22EC5E621AD8BECB273C4C74E1D4592888
PromptCre49.wav	D438AE349E628C3F2B375D46DDE7C44A707866B4
PromptCre53.wav	971F336B745A5D757E8D8A3641DAFEDC675A253E
PromptCre54.wav	A8228831E1CEEDFE1F197A144070F3F473FCEFB0
PromptCre55.wav	077182C54FF89BA7F5CDFA3AAEB1B71B1FBF295F
PromptCre56.wav	26405360F1679E6BD7A4BAEBAFA7B93BE96D9D9D
PromptCre57.wav	4C1694F84ED3C862769DB8C4439F411E41907FCD
PromptCre58.wav	A9B27880E7D71868C845F1DE272B2292BC513FCD

PromptCre63.wav	CD454E7B8C48944C9E6BE05FF0FFD65C134F0E9C
PromptCre68.wav	241457C87587E4379C1218D22312CC7E820B82CD
PromptCre69.wav	29F6904A18EAE4571F2F768FA8D3D8055473E920
PromptCre7.wav	6BB5524AAA2D8E18990B2F711AFDD0E757E266C9
PromptCre72.wav	595CFC2F42E9A57E33180685E0912B73D26C4157
PromptCre74.wav	E0C435DA728E1381B6552CA1AA430E58E964271B
PromptCre77.wav	63EEF58DEE61807745B5DD47FCF2CCE679CEAABB
PromptCre79.wav	7437B8CEB5947980BA09EA0F9B79BF85969D5657
PromptCre8.wav	51F8E83DB0DD2FF085536AD1AA7EEF2296A39BBA
PromptCre81.wav	29C4F8DF420DF2307D70C0DB0775C69D6B118D77
PromptCre83.wav	49C515A4AF9537B657FB8E3EAE98FF12DCF34AB3
PromptCre85.wav	18FE4F4B3580DCF41B3BA37EC22C05FBB582FB2B
PromptCre86.wav	C2F7B8BEEC7E5CE15A6B68396E4F46F6F8E2A741
PromptCre89.wav	7382718E8AEAF6846EF2108DE3E6FBB0FFDD2FA0
PromptCre91.wav	520A6CA89D9CD77B050C6472D3B895C7E6D43A74
PromptCre92.wav	86846AC540E64387AC8917DB86AF96E7BD19ADC1
PromptCre93.wav	633BE9BF4C7BA52E3BAC5DB278F44A5C1DC4DE07
PromptCre94.wav	744D3513CAFDED71B4452D555748A93532A83884
PromptCre95.wav	1E6F9BFF9D68C396BB75189941C2903663C4DDC7
PromptCre96.wav	D99E89B60280F03991C9B7C6A0900811F33B80CB
PromptCre97.wav	2E203262EBEE18733BCCAF97A4BB74EBCD4925EF
PromptTag10.wav	1579D8A8DE533F96C0DC828770F3616F1BBBCCF1
PromptTag104.wav	8A94C86C6A254D889D1A664CBA311A1EEB2B1A0E

PromptTag105.wav	AFF39789EF7E7C34EF7C85214EBF3A1F7436CA0E
PromptTag107.wav	0B721DD344B4C977DF37307C7330EAF2B677122D
PromptTag108.wav	BF49B4374B569997B6CA4D82F8C0917C986F7B8E
PromptTag109.wav	594A34F5845C0D2180EDD8400F9E235CD57A0A9E
PromptTag110.wav	316BFC588F36D5AECFF2EAD6DE12CC04B6C2F357
PromptTag111.wav	A506231B819C8F3A39A157B52B805E3FFF863BEF
PromptTag112.wav	9604B4C2841D277ECF198D8B1DA6EED95854E126
PromptTag113.wav	25CB678B3A2922C2158F8A6C615D3174A9B10BEA
PromptTag114.wav	F5D6D2A05350EA5BD71B3153B4B5BA00761F0699
PromptTag115.wav	EA3748381F55602E3690A439AD8C708295B17238
PromptTag117.wav	D892A2426A6DDBD5766CF63A1C4FBF4A2EEED472
PromptTag118.wav	DA9603901CF2A811362052DBFA1260FB63680B2E
PromptTag119.wav	16D624131219E58FB3AB28351C50D5E00AB63C1B
PromptTag121.wav	0C15A8B4F3BCF220BD0959E51B01C099E8CE1E32
PromptTag123.wav	4ABEAB0C6676CEF54E24C6FAD4247909E653D9C5
PromptTag125.wav	FE6AF841672C5F9F489FCECA35FB174E50B324E5
PromptTag127.wav	70B178BD1A79E4C187B6DAF472679CFC9F254629
PromptTag13.wav	C13479C80ABECDB61B28E8D03434AB318D0D3C15
PromptTag133.wav	7BB2E23A7729BB263AFDBA48A330C4811E492ECC
PromptTag134.wav	14B41AA9669060CA9EAD88AAEF86C6AC17D6EF37
PromptTag136.wav	009730166FDA7A3CA050A321AB605DF8949A4EB1
PromptTag137.wav	8BB89CB745777680D9D90DAADF5A6D39862DB8B9
PromptTag139.wav	6B91B64A8633FE932658C358663EE4DEA8054322

PromptTag142.wav	0EC3F209A5E621EE341F206FCB9C3A44A67A20E5
PromptTag146.wav	C69B64BCD5EEECB8AF9AFB9E7A97F805D6994181
PromptTag148.wav	0B8A71407671DB6AF7635BBC94F27B879B9F98BC
PromptTag15.wav	708A69BB2FAB25D34654B5669342BB1D70902372
PromptTag153.wav	37CEAD8E6F0F9E4FF9A80EA838759BA43A378193
PromptTag154.wav	787DE19308B5F49496D168E958C6B0F27B3AA442
PromptTag155.wav	3B51D3A2634376C5D01300D64FF98DB71C21F2A1
PromptTag157.wav	93BFF91AFE35212E5E1D1BB62D366BB9D21F8DA4
PromptTag158.wav	5D713F9F7017B03B401130FB5FE202B4C4560348
PromptTag163.wav	DA9E9EC7B42FB6B22B30EC737DDF48E698124151
PromptTag164.wav	3B80F3BD27977533EE499BB5B7612339BBD3E3E6
PromptTag165.wav	3D4484DE49C38A0668364221E08C2BF0F4D33193
PromptTag166.wav	5247BD560AFC3A98F5CCD436D7D9F8C2972D2986
PromptTag167.wav	47CA2CF086A36942D0970DA21DEA143EDE05C7FB
PromptTag169.wav	DE4171CB1A94254FDFEBF5741784D51420BE4BD3
PromptTag18.wav	49F386B3E7651ADD5D75100D54852D53A854332D
PromptTag19.wav	BDA4255F520012FA3394A9EC4AB29AC42F535A8E
PromptTag2.wav	B8A1C817D9589FD8E7EE031FB4C956D888ECC88B
PromptTag21.wav	4D13EB2D5FDD62D026BE4534520C1065B9EBC6DA
PromptTag23.wav	188DF305F2827A41B8EA6FC2A19111F7EDB25AE6
PromptTag26.wav	560E6ADB4351EA92D850BAF3C6D490532BE91102
PromptTag27.wav	83F1D4866920183E35D68B279E2A00094F6CA374
PromptTag28.wav	4B83F00354A4CF01ACF37155F5F1CCC4EA22BAA3

PromptTag29.wav	F665FBAAC27B4691DEF98F5212B72D822BD3023D
PromptTag3.wav	6BB62960D7515316446DEBC7A334E1021AEE1CE1
PromptTag30.wav	AEDC20BAF54FA225EA6DBB8792F8305904D79867
PromptTag32.wav	8D80DDAE7D8A7ACDA79AE7791C02E78FEF9C8FDE
PromptTag33.wav	E4787D1A8FE32C7963CED1B8E2E3674FBB5F4A3E
PromptTag34.wav	938937345E55163E00B3DEBE9982400B71724A66
PromptTag35.wav	1F54E0CCA8A6E54AFC838E4F6B0C827C05EA11C4
PromptTag36.wav	298590DC58009DF6F09B61785CCAF8CF62BE192D
PromptTag38.wav	03E05152C202DEB5901038EB6C81DF0DF59F416B
PromptTag39.wav	D1BCA1942028A1800E653EDBBD43B11EDCA9B4F5
PromptTag4.wav	A2076044E7E18F0084335B94BCC0D068C08FADC2
PromptTag41.wav	24FC326FBE25ABBA9C5AD1ED3126F45B95145611
PromptTag46.wav	C87D2C67218628253AF8F9F32B2F6FEC8E80CD78
PromptTag49.wav	88160E05679734BDD1EDBCC42761ABEA1FCE7B15
PromptTag53.wav	FEA87CCBF9D2AD4883EE4A82C7C9DDC8AE181A58
PromptTag54.wav	C85382EB4155E9B92F155FDD0BCFDB239F96AD45
PromptTag55.wav	5E0D67A6907A2BBA743588F83CAA1D42FDB9FAA4
PromptTag56.wav	E4B07CD3382ECD2A7A9FFE26D9D2B9EF8DE3F68C
PromptTag57.wav	8940C68D4D213F668029DED29D62AD3F3FBAEAAA
PromptTag58.wav	876094F2FB625500C111D369A97D81114407DF45
PromptTag63.wav	F9FB81630E65F361E4AF0CE3CD57A69C0E3AEDE2
PromptTag68.wav	E7B234DD4217979B5A9E0B06059B48319C2700F1
PromptTag69.wav	53F71132F5F035223921ED4D0E7404BE2D68A408

PromptTag7.wav	802D67B4B0D9B51D5A5801F136005DBE3DC037BA
PromptTag72.wav	4D158F2FC12EF32C6AB1FBCFD026F68F79976C19
PromptTag74.wav	6561ED23BB276A1E758CE01423B6FFF0DF088621
PromptTag77.wav	7506B486EA1D9C36D882F16C4994EBEE6A9602C9
PromptTag79.wav	25E38FFB33D0EF05D8FE84F0BEF8CFAD728C9C5F
PromptTag8.wav	F36FE444225A61607183B3E3CE7DC4D7C340A36E
PromptTag81.wav	F74260005E8A668286A4CBE601095A33643DD332
PromptTag83.wav	5DBC1C2D2B19469B1165FB711D086F42CF1101AE
PromptTag85.wav	01609B06FB9B911B85EDB9AB2FE38B6C2471DA7C
PromptTag86.wav	7DAA7A7A4F653430A34F166319CCC39CED1A1ABD
PromptTag89.wav	2F527FA107248BCB8E437B7FE3AC97D1A4E7503E
PromptTag91.wav	112B340F1AB1443297D76730CC7BA66E3E1B93EB
PromptTag92.wav	1DC1027925DF63B89EDE2B0362A168E2A64DB6D8
PromptTag93.wav	3943D02EDE2F1EEEC1FE95B655A8D3BF3332F480
PromptTag94.wav	E9F4C00D75C3EB598053B642F9720231CCC531E2
PromptTag95.wav	A18894655C521DD39289260E30F87D497672D916
PromptTag96.wav	1A659CF459D70901EBA648CEA070EB49C776DDF1
PromptTag97.wav	624F16D946074FE57E1629849494F4F8998BF360
PromptViet10.wav	478089B603583174B507BA2B3A822051DA6FF47B
PromptViet104.wav	BA0980D49D487E28B1B5921517AE08BB04E176F2
PromptViet105.wav	3BDECD325882B483D948DAD6DF4C6913FA89F0FE
PromptViet107.wav	23B0B1FAE1A98F748191D996B123B140A1A90B8B
PromptViet108.wav	EC198CA0397D9F2FE764996589D211C53801AB94

PromptViet109.wav	241BC815C8D00B4AAC6CC0804D027A2F0C7EB6FA
PromptViet110.wav	4908D1CD843D0A9D0F4152150A9BF149B7B555BD
PromptViet111.wav	BCA73140831143E92ADA6A3239BC3C7D5DEC68B0
PromptViet112.wav	E326360CC01132CCB37EA7AECBBCE08C02B06189
PromptViet113.wav	9BF77574B69B08DD23316FADDD2CA66F01402A93
PromptViet114.wav	887D7D1FE34BEE8A430C4E3090403BEB8B8900AA
PromptViet115.wav	C4BC00BB63D00C05295DA3430A30843AEAF0C9B4
PromptViet117.wav	E0EB4C22F34551A8DE6850F9A0F4220B05333B3D
PromptViet118.wav	43B24139EE5DB20067B7B13376F2D83E44E61754
PromptViet119.wav	05A80E9CE06E62D992B94EE9C203E179DE435DA4
PromptViet121.wav	BC7A80E29B7DE60150219C00A9F9E4F221160518
PromptViet123.wav	4C60F7772B517399F4252D09A8303E8AE24CAE53
PromptViet125.wav	DA3F207986054D0E818AE7FA775417FDD7832B1A
PromptViet127.wav	65874058F3CD0D6E47BAD353291A838DDE13DE0F
PromptViet13.wav	EA6FCBAF449405338B1A8AFB7A292265609236DF
PromptViet133.wav	51720413661B2143CC0F2B2153EB7CE37680B321
PromptViet134.wav	4D97363FFB8EB4B511586065EB5D15F78AEEEE05
PromptViet136.wav	E1EF8279F3C3851878AFBA0C93132E28EBBBDD08
PromptViet137.wav	DE874EA41C4243CC9229A649341B0DB49D0FF9A0
PromptViet139.wav	BDEB90D558C1012C8041D1625DCEB264C89EBCFD
PromptViet142.wav	4C4011216CA705686498BAE6B92BDFF51A63D952
PromptViet146.wav	42ECE6E086566F008AE765D8BA7424F24ECE8944
PromptViet148.wav	02E56CDD7BFDA3C215AE16329FDCFA84685F1A95

PromptViet15.wav	338BDF0B00272D8DFC74DAE56EFA66FF26982670
PromptViet153.wav	F1A1F1F56CEF211A4A7A3FE84DCC7B68353D9986
PromptViet154.wav	90FE4FAE0CD79EA23493965A22F7E1E0B5126013
PromptViet155.wav	FBF91CB12E6C2C962CC26689964338AD8DD6B09B
PromptViet157.wav	38780A28C223DDD7DB96C59FC093404F2D149019
PromptViet158.wav	0C7C9F474C7BF997CD9C4EDC5E3B45EB540B3677
PromptViet163.wav	FC4172855AA87A13C2F57DC45E7D5B65A8D12A89
PromptViet164.wav	40C9C7758FCAC2CE4B34AD96415DF8FD52443844
PromptViet165.wav	95CFC04433AED160A752A437FC0ADE90B664A5E9
PromptViet166.wav	EDFBBF195115AE5728D29398E2A96F6D46B8F1CC
PromptViet167.wav	D8138A4F88252AD0758172A6AE084EFE1548220A
PromptViet169.wav	EAAA45FB0841D4D7AB5D1A932B3DB5A16D7B6FA9
PromptViet18.wav	DAE00F4B1AF3E09DE3FD15815805E66CB7A59F6F
PromptViet19.wav	9E97A977EE6B0D11C05EAD1CBC04A1948F9DE15F
PromptViet2.wav	3992E39CC1E2DCF625B7FBB566B8A830ADF0393E
PromptViet21.wav	86A41BFA0C9A78D92905F2AB7AFD3A378361167A
PromptViet23.wav	AAB28AEBC5D02A2F70002211313D53A2079A714E
PromptViet26.wav	D2AFE897A0F4A2BAE8CDDDC262BD52F33BCB07FD
PromptViet27.wav	6E297018CD4D96768F6824B3314B4F8147388FB7
PromptViet28.wav	4A45967E71F7C7816F0580A0D2947C2D75B2EEF5
PromptViet29.wav	EE794C57F9F8A51A983EC35639E2B1F3788AE105
PromptViet3.wav	8F0BCD4A7E7B6BF0B7056DAA0791760FE116BCF9
PromptViet30.wav	16C525EB715C46A0E3DE15E23F9075115DD1EFDF

PromptViet32.wav	EE7724C070A1374B41A1169D64DE38559209B792
PromptViet33.wav	532A6728F897BE4BCB89A0953B0023930C9BDE1A
PromptViet34.wav	71A1505505911AC882E7CE8BFF70C508AAF159BA
PromptViet35.wav	487059C66459E1D78E1CED37A618A1B6D3EE52EC
PromptViet36.wav	53E3D8E06654A5EFDEF6510E5F1C1D6356AB81CC
PromptViet38.wav	D3A7729A33532EAEE95818629EA8D1AB536ED024
PromptViet39.wav	E47945BC4CB2468E20B081D834461C61A912FFB3
PromptViet4.wav	7306E25FD49B47343E9D9B064D5D2350E37AE444
PromptViet41.wav	FF5AFFA042747B2404BC12AF08E6E8A203A4555C
PromptViet46.wav	44B69E37245987718CD0EED3F7865D6A530EA844
PromptViet49.wav	91BACDFC8B6BA92BDFB29E70DE221186D1AE52B5
PromptViet53.wav	7E2A943A5249E1B769842B2886391A7F889914D0
PromptViet54.wav	BAF9F1073056A67727D64E1E4A16AA6F4961C940
PromptViet55.wav	66FC79E07325625AB8793ABCEE070C612904B7FD
PromptViet56.wav	02C966F1007BFACCD2FD85374D364DF01EF10F4E
PromptViet57.wav	CF8688CFADADB098BF6CE20A04CE32B4CDE02743
PromptViet58.wav	053673859B01E2C975D502588D5A8BA408C526F3
PromptViet63.wav	08C86956A4CA6688A1DA88640667D193999FFC1E
PromptViet68.wav	3C75EC45CB26FF5B64DF6389FFC8D5918B778AD6
PromptViet69.wav	ABEA69BFF7516A5B272600FBDFF87FDDCE39BABC
PromptViet7.wav	65F9AA49D71090B6A25B1FB14C3D5C1427708707
PromptViet72.wav	735B107DAECBAE0E9C23B78B612359832D30E85D
PromptViet74.wav	A164F013993C19D0422DB867C7C2DCBA97BE2391

PromptViet77.wav	5F0FA97E98E45BA63647F5499463C0411B7028CA
PromptViet79.wav	DABC75D65F015D28FDC449B82A9DD0B8E280B85B
PromptViet8.wav	A2BC8146B0E9F8BF997E48F808B6E42865F1BB67
PromptViet81.wav	1D89E46070F963554CC2BD937A2DFBB44BEB15A7
PromptViet83.wav	C66F4AA9247B4796BF2B65342872CE6BFB05469E
PromptViet85.wav	ED8A8D0E862DD24A5832709196E89DDC114E5B7E
PromptViet86.wav	44ECA93A3B00FF5C2E4BB440EE7235F7D2E32530
PromptViet89.wav	D13EBF1E2F1DEA271212D8A0261489C34B321337
PromptViet91.wav	20D3F835B97155654B0A5297731BF8463FDBBA45
PromptViet92.wav	50F3DDEB1FD2DBA187BB20D085C52D8EF17D1B2C
PromptViet93.wav	22DB69B8ABED2BC79BD663BDDADBD47E618A8304
PromptViet94.wav	2332DC0DF6F16A41B5A99693EBCD8DC3E0C5E4B2
PromptViet95.wav	5488FA21B731E18D48644FD21825918E6DA10804
PromptViet96.wav	C18FEC190B13A7766584F13426AA5F1600E16E64
PromptViet97.wav	95E7938FD2A012AAAF103E7A90245AF561C58BDD
ElectionHeader.bmp	174126B96601D0DBB1AB1EEA6554415C7F5076DE
AIMSTemplate.bak	F68029FD8DB37329E8EE2930B6B7990ACC147CE9
AIMS.ico	3DFE99F7AFC65291E9B2051E9F7BF22B4FC8C8C6
Black.bmp	819E3E7AE66BE1410910247E482D6656DF5F94A1
ESS-1.0.xsd	44882351D1207E408F3D2EB801D4AE24749469FD
ESS-2.0.xsd	784AFBA4EE1F5F9AF47E742D8DBE518417EBA0BF
setup.exe	AD9D138AC48AD86EF09DFE9B3235383D9B9F5C7A
Setup.ini	B8024562D05DD4DCFA5C3C72DA97BB536D5440CD

setup.isn	650204A126C15445F21F291F62E8EEF9DA2CEB93
automarkencoder.dll	EDF07058406B17452293A8877C9140E1ACD73FCA
chs.syn	FF7C1873B84256C25DA601D70AD280333E5CE167
chsrom.dll	F3AE8A1F7D0369D387B8F2EE0A47A76EFEE2BC2F
eci.dll	7AA1085174B7BCE6016C8074297BC6CB40B823DF
enu.syn	3E69875D11E0A53C39C211C484CB6520F8D87F25
esm.syn	D8037D86E5F677E89ECA7834AE47FBD030A043AA
EssCrypt.dll	C773495CE71E5D75F2853873DD33F623280C34CB
jpn.syn	99A931E76E6008DA9F01B91B4D91C116ECE8F7D7
jpnrom.dll	7557C00E8ACE29AFFDABEBDDB73F466D0877A866
kor.syn	F32F8AE286ED278320DBB829DF338B97A2C846B5
korrom.dll	76219D7F9F76F021B4815FA796F80E3CA49E3446
asycfilt.dll	72FB4F088C6AC02097B55FB267C76FBF5E0FA1F7
comcat.dll	C2A409311853AD4608418E790621F04155E55000
msvbvm60.dll	CE82D1CCF593088D09694EF90E44C4EA2761BE92
oleaut32.dll	6B58E20B2538CB308091DA838710F6AAD933A301
olepro32.dll	8ADFF69050D14A57D7F553CA8978439AF188C192
stdole2.tlb	36F701CCEC78A5D218FEA23FD05351890F14CF7D
AuditManager.exe	AAE61B3732C30E6FDD2D57F560D4DD8C0B18953F
bdm.sys	F0789738D3D3A80FFC15EB3A395475854C4E7D3D
EDM Setup.exe	3E09CC02A25E359BA69A071FE657C3C9EA72B8EC
Setup.exe	46ADCE6E9FF277D80FA10EB3F3CF654D6E6EE564
ais.sys	DFF2A9C1743049E4506DC0F7C29EB4CDB46D2729

ESSIM Setup.exe	C92E35B26DA29812BE9F64D4930E828EBC120612
update.img	A6C419F81EB9EE111C6A3FF75313F89F15D8C740
PBC5445.HEX	51F8EAE6A109F733A31AF9EF6AE42128266781BB
PBC5445.PCM	64AF432E65AF07575C77D132F3ECAE276608FE4C
display	194502AFD591D250775589F79CA6A35511B33103
shutdown	1C8C0CBBD728819C36610C6685DE6D2F956D62E5
update	27C3C7F0DF93A6858EA8277969B873DDB9DCCC6E
bindates.bin	C2B3CB2C82BCE82AD533950EBD3E01A939904769
init650	212F7024E92C7BD79A60BAB4D9C7BDBEC8D02D01
install.sh	0CB1AB80B0E309FF6EC7D143A1FF44576655A3D5
licenses	27B307A57D58F3F55D75A4052C7CAD032BD13DA4
params.etp	C2206F36F1AC800C71786A9E3C9537BB38BBF829
sysinit	FCB67F0C87FE32EFA7932DC59CBFFA049AE79EF1
tab650	C9798CE735E4F9FA645D11D2C3D41F8F4107C11F
tar	9B046A815A5ADAAF9BEA92D6504FF086C97DE1D4
tcp.tar	44B703B3157B57843BA30D696663E0A8BAFACF6D
version.etp	8C3D094E307583879A184A271FAF54BC37D1F4CA
version.etp	8C3D094E307583879A184A271FAF54BC37D1F4CA
AutoMARK.THUMB.CAB	2383CBF054B0CC6FBB705E00DE46C5054F626110
automark.thumb.lst	4A708ACF1A2EBDDF2C5F1267CFA04A6C233154D4
VALID.CDE	475E51FB6D1414B4C23A33BE76BE7B072B1F639A
Setup.exe	8897C0C9329E7A602BD2D2733AC1BA906B1B08E7
LogMonitor Setup.exe	5830DDC5EE215EA1BDB4F321E6905575EB7DDBC3

rmcobol1206rp.exe	F5E65A75A14131F0D947BF1A71A9BCB1CDCD58E7
Autorun.inf	D0B67C20ED1B09A741D1A5B55A32DA0BA029E6C4
data1.cab	F72A1C9BF307AACE9FE256A4383C2BF511B38B07
data1.hdr	C2BACC9DB416EBA6B42E0B23BC6E46B11C772C20
data2.cab	63A9FBA4832506A4BF3CE1E2A05AA1FBEBF08376
engine32.cab	FDCE25C9DD6568B58FFF3D0C30842D8E093774AB
layout.bin	C0250F7319908A4F6513A758853B96EBCCFC6CCB
setup.exe	10D2CD51FB97197949310EE9595F9E79D5392105
setup.ibt	A55F417AEAEBF1D6EEAA6DDF3FE3BD902E10CFF8
setup.ini	F29F87B64C0389763B8B1BFFF1A44DD69513E0BE
setup.inx	F8F546B4F7201A9B9A76CAF85361738A66D9BDF7
PEB 1.65\PEB.hex	524F8F55BAFF38B91C232F7078A72D6D3D58E1A6
PEB 1.70\PEB.hex	A168685872A0F0E69C13FBE91BE1B0DE759235B7
SIB.hex	157BDA7931AD92D3F5DC255DD4A4AD492B094FF1
ultra.s19	6C19522317D09335142A95F0EF0C7F59E28DBE9D
AutoMARKProduction.THUMB.CAB	05224331CED5396B601E551CCAAA4D04DD4B6770
AutoMARKService.THUMB.CAB	0117EFDC862339F41A01AEE304E60C704D5C9F73
prod_release.img	6B3066F634D837851ACB2BEFE231135321CFDB91
prod_release.img	A8B8E2021B51FAE5B0F0351BF33FFA6A33859BB5
Symantec_Endpoint_Protection_12.1.4_Win64-bit_Client_EN.exe	A434004FE8B9CB21F3B4845E93F8DC0FB8D71B3D
AntiVirusUpdates\Updates\20140106-023-v5i64.exe	7F9B2656481A1D557213018B662F8FA4C5E7600D
Autorun.inf	AADBCF490CCBBBFB1F368EF3C09DF34C6DBFD67B
Autologon.exe	8D6080E7A89B294B044A649FFBC40943A940AE04

DownloadLinks.txt	1192372A77FEB561A49857F7247A9CFA4689C387
hashdeep.exe	ED95B93CB6152B337C42947437AE64D524931218
hashdeep64.exe	E5716D7889D34F29E0ACFFE63AF3E38EB3F3C1F8
IfAdmin.exe	521C59ECE4C3609FD34709768F5FC0F1CF41883E
builddate.txt	F1FE6DC628F8C5D3041E30B08A486C5F4B295149
CleanupRecall.cmd	BC75093038473D92395DE5C17BCB47B0E2F097DA
CreateUpdateAdminAndEnableAutoLogon.vbs	D86B76BC4CB39A758CEA7A50C81D86E82A8AD0E0
custom\FinalizationHook.cmdt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
custom\InitializationHook.cmdt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
DeleteUpdateAdmin.vbs	DB706F36D6B57ABCB7662D1E6ACB628A27DACA5A
DetermineFileVersion.vbs	4C731E7B13BA985A84B10037E1700ED26D70BDE9
DetermineRegVersion.vbs	CA5026852C9B9767FFD52D2F4C433EE71F13C8BA
DetermineServiceState.vbs	2CE26FA726B67CF5D7C4F9AF909674242245F29E
DetermineSystemProperties.vbs	4EF494C378F9ED95A74EE904A54FB92B78FAF435
DoUpdate.cmd	480E1666AE0B62068CDEAC95007AD303A4446A89
InstallListedUpdates.cmd	6ABCE11142AC8B8EEA37917BCFEB76AE32E7FB26
InstallOfficeUpdate.cmd	1BD9BA52C6C4060F0D229F5628ABBF37F6197922
InstallOSUpdate.cmd	8C75F5466E6BF0ACAF39013FE26F77E47169A766
ListInstalledUpdateIds.vbs	5D9DDA597AF0110E584C2A6AA8A3C61B64CD38D8
ListMissingUpdateIds.vbs	9BDF4443611F53A08AD9556378572375A7CC8ADE
ListUpdateFile.cmd	774EEF95A3AE7949C5B18B3DAD7BBC19AF99860C
ListUpdatesToInstall.cmd	C3FA7C83D14A93AAE02E272F435421688A546F56
PrepareRecall.cmd	55672E7CDD7572D3C667DB066B99FDE2803368F3

PrepareShowLogFile.cmd	82A5E35DF648CBB5605E47B33B6142EE15D1B017
RecallStub.cmd	457733C652F05979CCE94B017C793E1519AF5EA4
SafeRmDir.cmd	241D72E2F9AC22837F2E9B4AD9D527F4F29FEA58
SetTargetEnvVars.cmd	2509D63B3A2C2891398363B92C457EB2CED7D0BE
Sleep.vbs	846EA912BB50FD17E2087D8C041864A5250BD4B7
TouchMSITree.cmd	689BDE39D44436F2330D48EA52A47CFE1942A69D
vcredist2005_x64.exe	EE916012783024DAC67FC606457377932C826F05
vcredist2005_x86.exe	B8FAB0BB7F62A24DDFE77B19CD9A1451ABD7B847
vcredist2008_x64.exe	A7C83077B8A28D409E36316D2D7321FA0CCDB7E8
vcredist2008_x86.exe	470640AA4BB7DB8E69196B5EDB0010933569E98D
vcredist2010_x64.exe	15D032D669078AA6F0F7FD1CBF4115A070BD034D
vcredist2010_x86.exe	28C54491BE70C38C97849C3D8CFBFDD0D3C515CB
vcredist2012_x64.exe	C17CE31EEA954A7A1E42DF5C49876EF937D74ADF
vcredist2012_x86.exe	F2815511B1903CD7684DFE564D8A5FA76224408D
vcredist2013_x64.exe	BEF7E7CC1DCC45C0C11682D59C64843727557179
vcredist2013_x86.exe	18F81495BC5E6B293C69C28B0AC088A96DEBBAB2
dotnetfx35.exe	3DCE66BAE0DD71284AC7A971BAED07030A186918
dotNetFx40_Full_x86_x64.exe	58DA3D74DB353AAD03588CBB5CEA8234166D8B99
dotNetFx40LP_Full_x86_x64de.exe	D5E783B6F49641FED46F299580737525B3918069
NDP451-KB2858728-x86-x64-AllOS-DEU.exe	943AF34AE1A51C1285046AC828104E7ACB381F63
NDP451-KB2858728-x86-x64-AllOS-ENU.exe	5934DD101414BBC0B7F1EE2780D2FC8B9BEC5C4D
dotnetfx35langpack_x64de.exe	008B43A25D4FAA7A21CDEBB43DB74D08216E6344
ndp20sp2-kb2604092-x64_5346aab176e68995cb19159fc02dca41996ba5a3.exe	
	5346AAB176E68995CB19159FC02DCA41996BA5A3

ndp20sp2-kb2656352-x64_eed59d0c23af97a45c196f1c87e09f6775fa1d3f.exe

EED59D0C23AF97A45C196F1C87E09F6775FA1D3F

ndp20sp2-kb2729450-x64_26a72f0f0db6ebac5aede881c56102b3cf250928.exe

26A72F0F0DB6EBAC5AEDE881C56102B3CF250928

ndp20sp2-kb2742596-x64_d6e4a7e72e0524a87d3de9d3a149ad12f343a60a.exe

D6E4A7E72E0524A87D3DE9D3A149AD12F343A60A

ndp20sp2-kb2789643-x64_d896d551e623ebc82370be7c82687c2d60df4f94.exe

D896D551E623EBC82370BE7C82687C2D60DF4F94

ndp20sp2-kb2833940-x64_facc9b3ddc7dc4b58da184461dface539a6a1886.exe

FACC9B3DDC7DC4B58DA184461DFACE539A6A1886

ndp20sp2-kb2844285-v2-x64_2b803448722b4d0fe43f7431cc50265c0cb1c826.exe

2B803448722B4D0FE43F7431CC50265C0CB1C826

ndp20sp2-kb2863239-x64_adcdc5168104a48d262e164dd5ee0b7376072cc9.exe

ADCDC5168104A48D262E164DD5EE0B7376072CC9

ndp20sp2-kb958481-x64_1392380ef7baabd531f35ee5799c255a03b0dcbe.exe

1392380EF7BAABD531F35EE5799C255A03B0DCBE

ndp30sp2-kb2756918-x64_24139123c6c09a18090978b88cc2c34116b951b6.exe

24139123C6C09A18090978B88CC2C34116B951B6

ndp30sp2-kb2832411-x64_9d4ae00af5e78e6c4fb9680af316956750ba572b.exe

9D4AE00AF5E78E6C4FB9680AF316956750BA572B

ndp30sp2-kb2861189-x64_ae45b8d51e42764a6161d1ad1db9c025f02cc1fd.exe

AE45B8D51E42764A6161D1AD1DB9C025F02CC1FD

ndp30sp2-kb958483-x64_84062cf4c3f303f3641e3f730f60fdea51bc776f.exe

84062CF4C3F303F3641E3F730F60FDEA51BC776F

ndp35sp1-kb2604111-x64_01fb9c1c60d9729d07977a7b142aab80ce9cc389.exe

01FB9C1C60D9729D07977A7B142AAB80CE9CC389

ndp35sp1-kb2736416-x64_d1d9b33957bba14e31988dfdaf4f5d3b13f37943.exe

D1D9B33957BBA14E31988DFDAF4F5D3B13F37943

ndp35sp1-kb2840629-x64_8bceaa39f0da28e17ce593830f2b7abd94740228.exe

8BCEAA39F0DA28E17CE593830F2B7ABD94740228

ndp35sp1-kb2861697-x64_77cfad96c417bcce3f919e6a0e29d656f9d8adc1.exe

77CFAD96C417BCCE3F919E6A0E29D656F9D8ADC1

ndp35sp1-kb958484-x64_e69006433c1006c53da651914dc8162bbdd80d41.exe

E69006433C1006C53DA651914DC8162BBDD80D41

ndp40-kb2487367-x64_766ba6bb94f450633fae2baafe58d2cbd2ac8bcd.exe

766BA6BB94F450633FAE2BAAFE58D2CBD2AC8BCD

ndp40-kb2604121-x64_2e71d482c909a200420e71c39061f48910df5c30.exe

2E71D482C909A200420E71C39061F48910DF5C30

ndp40-kb2656405-x64_0a6d8bf8c91cb5c494365c35c00a16b45139652c.exe

0A6D8BF8C91CB5C494365C35C00A16B45139652C

ndp40-kb2729449-x64_01da0787554f4526e9814300aa34310fc50614cf.exe

01DA0787554F4526E9814300AA34310FC50614CF

ndp40-kb2736428-x64_f5f126738673ae9764d03fe42feeea68f1edece2.exe F5F126738673AE9764D03FE42FEEEA68F1EDECE2

ndp40-kb2737019-x64_00de162f645e62c56ebca48f2cb128c4f5516681.exe

00DE162F645E62C56EBCA48F2CB128C4F5516681

ndp40-kb2742595-x64_accf0a336e7ba49d629c10fd80b4e03547ea7e3d.exe

ACCF0A336E7BA49D629C10FD80B4E03547EA7E3D

ndp40-kb2789642-x64_ea048475842cd169fd371ab3ae75d386ddfcba83.exe

EA048475842CD169FD371AB3AE75D386DDFCBA83

ndp40-kb2835393-x64_7749a86b760f1c7e5539d4b5174e4d163ff1e99d.exe

7749A86B760F1C7E5539D4B5174E4D163FF1E99D

ndp40-kb2840628-v2-x64_d07dbc837ba227b3493b0a2170ecfb3a03ee4369.exe

D07DBC837BA227B3493B0A2170ECFB3A03EE4369

ndp40-kb2858302-v2-x64_33610d262ac3d3779c445b4520e7d986a70b7c66.exe

33610D262AC3D3779C445B4520E7D986A70B7C66

ndp40-kb2861188-x64_6076fcbb9f7df095f2c764534cdeee3ae14f4dd6.exe
6076FCBB9F7DF095F2C764534CDEEE3AE14F4DD6

ndp45-kb2737083-x64_269de1929ca076e21ddf3fe6c7c35b72b09e22b7.exe
269DE1929CA076E21DDF3FE6C7C35B72B09E22B7

ndp45-kb2742613-x64_9e71a06c62b022bef5525155bec5ca5987535e70.exe
9E71A06C62B022BEF5525155BEC5CA5987535E70

ndp45-kb2789648-x64_3c9ec5be0b45abfc4ba02bc833f30878231584c1.exe
3C9EC5BE0B45ABFC4BA02BC833F30878231584C1

ndp45-kb2833957-x64_cf5d7160c3c98f2587700597cbc4f474716273f1.exe
CF5D7160C3C98F2587700597CBC4F474716273F1

ndp45-kb2840642-v2-x64_463747772c905e1c6bb95de7214b1dcd5745a2b0.exe
463747772C905E1C6BB95DE7214B1DCD5745A2B0

ndp45-kb2861193-x64_2758e92f68c4ace31bf90661cca4d177b0010452.exe
2758E92F68C4ACE31BF90661CCA4D177B0010452

ndp45-kb2861208-x64_2dc5af64a62ee63cf2f9d8f7cd5298f6444273fe.exe 2DC5AF64A62EE63CF2F9D8F7CD5298F6444273FE

exclude\ExcludeList.txt   C4C245DC9FE38760BF9C31DBFEEEE0A802859991

md\hashes-cpp.txt   8AF3499D96F1C5FA6EEDC09F4B4189044FDD65C6

md\hashes-dotnet.txt   37AA0E77D19B87A51DDE1999B193877B04550125

md\hashes-dotnet-x64-glb.txt   C3171053A2D3796077D6C4EC38BCBE6F8E33DB37

md\hashes-w61-x64-glb.txt   6EEB49B8E05D7B617A7367CFDAD84BDAD1A680EA

md\hashes-win-glb.txt   D7A742C31520060465812E92B3D139AFC1D1878A

md\hashes-wsus.txt   225C137568BB37E2BC3A1765FD682A55737EB17B

opt\OptionList-Q.txt   07BDEDEDDA98EEF880D84CBE6DA7418848AD5385

opt\OptionList-qn.txt   E3AC4C045E5AC4861EC1231A710CDB8400FF6669

software\custom\InstallCustomSoftware.cmdt   DA39A3EE5E6B4B0D3255BFEF95601890AFD80709

static\StaticUpdateIds-dotnet35.txt   78500CD65997606228895736145D3E2DFE2C77E2

static\StaticUpdateIds-ie10-w61.txt	FC66038D5D663EF670E399EAD7966F37B8F9ACF6
static\StaticUpdateIds-ie9-w60.txt	1EA46397FAF7DD9AA5E807DA3E729ED7B9906DCC
static\StaticUpdateIds-o2k10.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-o2k13.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-o2k3.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-o2k7.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-w2k3-x64.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-w2k3-x86.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-w60-x64.txt	DF68CC4477346D6428CE519A086BE24DF8305F70
static\StaticUpdateIds-w60-x86.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-w61-x64.txt	DF68CC4477346D6428CE519A086BE24DF8305F70
static\StaticUpdateIds-w61-x86.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-w62-x64.txt	151A08C2D20C6A4A0F38F5D6A26E3E2BFBDB5588
static\StaticUpdateIds-w62-x86.txt	151A08C2D20C6A4A0F38F5D6A26E3E2BFBDB5588
static\StaticUpdateIds-w63-x64.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-w63-x86.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
static\StaticUpdateIds-wxp-x86.txt	DA39A3EE5E6B4B0D3255BFEF95601890AFD80709
Update.cmd	0A69AE67690DD7387737E51B455B001CF10BBD25
UpdateInstaller.au3	3032DE7B31414B77B4A1CD782BC2FE4C33077653
UpdateInstaller.exe	AD9A9BE4F6B80930E5946FD5E94B29293C45D1EA
UpdateInstaller.ini	68FE8280B01FDCE1A9633DED090DA2A638B69109
ie10-windows6.1-kb2888505-x64_d46508567fe933db7760da56573bc59765b55abf.cab	
	D46508567FE933DB7760DA56573BC59765B55ABF
IE10-Windows6.1-x64-de-de.exe	47CA5867CE74DBFAED96763B697A1854388B0722

IE10-Windows6.1-x64-en-us.exe   17D1EACA123E453269B12B20863FD5CE96727888

IE11-Windows6.1-x64-de-de.exe   740BC34C072A1E3C4B4B11176EF8C7399A30C240

IE11-Windows6.1-x64-en-us.exe   DDEC9DDC256FFA7D97831AF148F6CC45130C6857

ie9-windows6.1-kb2888505-x64_ce3d63b1757edd948778a0032e283fcc12b36c7c.cab
                                                                      CE3D63B1757EDD948778A0032E283FCC12B36C7C

IE9-Windows7-x64-deu.exe   6D841A3A51D62D4F789732896FC7D8D0132E5473

IE9-Windows7-x64-enu.exe   5ACE268E2812793E2232648F62CDF4BE17B2B4DD

windows6.1-kb2393802-x64_1eba297f187b449686436c1071edf2312804a4e3.cab
                                                                      1EBA297F187B449686436C1071EDF2312804A4E3

windows6.1-kb2425227-x64_129a933b7782669a1ed6207f72050c9ae294f728.cab
                                                                      129A933B7782669A1ED6207F72050C9AE294F728

windows6.1-kb2479943-x64_5f7466309ee6a343cf69bd88d29de4029d3647ce.cab
                                                                      5F7466309EE6A343CF69BD88D29DE4029D3647CE

windows6.1-kb2483614-x64_0db7bdde245db948cfa85028a66d6319e6aad5ae.cab
                                                                      0DB7BDDE245DB948CFA85028A66D6319E6AAD5AE

windows6.1-kb2491683-x64_ab7326434d6b1ba8f04b4f53f82fd85a64912f6a.cab
                                                                      AB7326434D6B1BA8F04B4F53F82FD85A64912F6A

Windows6.1-KB2506014-x64.msu   CC70F2ACCBFBAE5E68F3C7AA3DBA8877D1DC88A7

windows6.1-kb2506212-x64_68431032794b007090bed18fc1adfc349f717375.cab
                                                                      68431032794B007090BED18FC1ADFC349F717375

windows6.1-kb2509553-x64_bcfe608b4d9e514ba1dc24a9e9dd6d45016ed3e5.cab
                                                                      BCFE608B4D9E514BA1DC24A9E9DD6D45016ED3E5

windows6.1-kb2511455-x64_ecfb3fe8e2378fe6f613d723cff6f97ea6798d90.cab
                                                                      ECFB3FE8E2378FE6F613D723CFF6F97EA6798D90

windows6.1-kb2518295-x64_025767634feef3db624fffbb4a29a7da102054a0.cab
                                                                      025767634FEEF3DB624FFFBB4A29A7DA102054A0

windows6.1-kb2525835-x64_7bee786d94ba4faf278f911ba1e2018b525a3306.cab

7BEE786D94BA4FAF278F911BA1E2018B525A3306

windows6.1-kb2530548-x64_5a0df0083041ef2e439d0210887b6f6431e45fab.cab

5A0DF0083041EF2E439D0210887B6F6431E45FAB

windows6.1-kb2532531-x64_4625e47e04e8708b66895de5439ec7221cccd41b.cab

4625E47E04E8708B66895DE5439EC7221CCCD41B

windows6.1-kb2533552-x64_8cf0b38e43622766333ce70426241dc7fa996b4d.cab

8CF0B38E43622766333CE70426241DC7FA996B4D

Windows6.1-KB2533623-x64.msu   8A59EA3C7378895791E6CDCA38CC2AD9E83BEBFF

windows6.1-kb2535512-x64_9abaedef698156c8a01bc2bd2dd17ff32510905a.cab

9ABAEDEF698156C8A01BC2BD2DD17FF32510905A

windows6.1-kb2536275-x64_ac86ae4ce126344bd7913ba527f112c717a385ec.cab

AC86AE4CE126344BD7913BA527F112C717A385EC

windows6.1-kb2536276-v2-x64_5980a26e376c8fc98e589cc1b85b03eeb0c3da8d.cab

5980A26E376C8FC98E589CC1B85B03EEB0C3DA8D

windows6.1-kb2544893-x64_21bb7cf8af8571e12267e165c4687429dc966544.cab

21BB7CF8AF8571E12267E165C4687429DC966544

windows6.1-kb2546250-x64_cdc3d02de4b267fc6cb2cb257ac664a3c3981a77.cab

CDC3D02DE4B267FC6CB2CB257AC664A3C3981A77

windows6.1-kb2552343-x64_51acdacad4855a2a04f35e2ac511fd3832a5d931.cab

51ACDACAD4855A2A04F35E2AC511FD3832A5D931

windows6.1-kb2560656-x64_a68ffedc9b03d6c95129e468baf42cd06bdc9853.cab

A68FFEDC9B03D6C95129E468BAF42CD06BDC9853

windows6.1-kb2564958-x64_656c242c83fae2c63b243e1c8941d7253a4114eb.cab

656C242C83FAE2C63B243E1C8941D7253A4114EB

windows6.1-kb2570791-x64_9f32e0144f188f15690d8a51efc87cc43ab01141.cab

9F32E0144F188F15690D8A51EFC87CC43AB01141

windows6.1-kb2570947-x64_381ccb025636afa9935bd39b64f444e497f37816.cab

381CCB025636AFA9935BD39B64F444E497F37816

windows6.1-kb2571621-x64_bf0eec81e9e284494c5ac7d7093356dd38ddd729.cab

BF0EEC81E9E284494C5AC7D7093356DD38DDD729

Windows6.1-KB2574819-v2-x64.msu A0B7FFFF5C8FC9B2F16B323E582BCDA3BBE972D5

windows6.1-kb2579686-x64_936d4dc7de3d7cac4f66a65da7c87a65c1398218.cab

936D4DC7DE3D7CAC4F66A65DA7C87A65C1398218

windows6.1-kb2584146-x64_e0c816a683326f69e8df8178889f555acbb051ce.cab

E0C816A683326F69E8DF8178889F555ACBB051CE

windows6.1-kb2585542-x64_e72f3f3a9af91a9ed6b3e444954a53fbf33e1b0d.cab

E72F3F3A9AF91A9ED6B3E444954A53FBF33E1B0D

windows6.1-kb2588516-x64_ce96b6888b79a06dcfa53940131b0bfb894ebe81.cab

CE96B6888B79A06DCFA53940131B0BFB894EBE81

Windows6.1-KB2592687-x64.msu F5CD9F3DAB8CDBBF287FEE84148E8EA69042BCC3

windows6.1-kb2604114-x64_d1fd3debcb8dd2da164c45f689a1c0e449c38159.cab

D1FD3DEBCB8DD2DA164C45F689A1C0E449C38159

windows6.1-kb2604115-x64_60417c781611597392c69457ad924e52649266b7.cab

60417C781611597392C69457AD924E52649266B7

windows6.1-kb2619339-x64_ed46064e0138564a6cb0000dea96fe5bf8198ec1.cab

ED46064E0138564A6CB0000DEA96FE5BF8198EC1

windows6.1-kb2620704-x64_c631fef931252fbf25a4a61875738021876d78a9.cab

C631FEF931252FBF25A4A61875738021876D78A9

windows6.1-kb2621440-x64_c38a7ca505cd266b6d1fcb25fea4b2a421096f54.cab

C38A7CA505CD266B6D1FCB25FEA4B2A421096F54

windows6.1-kb2631813-x64_626b002a3957fdf3e7512331efa1a8987519f6db.cab

626B002A3957FDF3E7512331EFA1A8987519F6DB

windows6.1-kb2633952-x64_d091e6369ee759b63634bc6447771ee8bc8de675.cab

D091E6369EE759B63634BC6447771EE8BC8DE675

windows6.1-kb2637518-x64_73c14c33acbdfe6ed6bf96229c7085d4839f08f5.cab

73C14C33ACBDFE6ED6BF96229C7085D4839F08F5

Windows6.1-KB2639308-x64.msu   67EEDAF061E02D503028D970515D88D8FE95579D

windows6.1-kb2643719-x64_212f2290f29586cdc75836ea3638352eb5e9083e.cab

212F2290F29586CDC75836EA3638352EB5E9083E

windows6.1-kb2644615-x64_29dd7e13efb5d772252c60cd3120094499ca88df.cab

29DD7E13EFB5D772252C60CD3120094499CA88DF

windows6.1-kb2645640-x64_6684c1b4cb5c18090ff3d7f903404894704330d3.cab

6684C1B4CB5C18090FF3D7F903404894704330D3

windows6.1-kb2647170-x64_7473723374b11dbceb390e7aa9c28ce5340652ba.cab

7473723374B11DBCEB390E7AA9C28CE5340652BA

windows6.1-kb2653956-x64_5cfdaba5a52326088faab671f21fcd807c8b8768.cab

5CFDABA5A52326088FAAB671F21FCD807C8B8768

windows6.1-kb2654428-x64_47bc9f3fd4bac1e6d5263fd71ad4e9611e6a209f.cab

47BC9F3FD4BAC1E6D5263FD71AD4E9611E6A209F

windows6.1-kb2655992-x64_6fc3816b974ab92b861ff4109ed92307721991db.cab

6FC3816B974AB92B861FF4109ED92307721991DB

windows6.1-kb2656355-x64_2e7caf92b258c076267a6b76740c5b68d1a2a440.cab

2E7CAF92B258C076267A6B76740C5B68D1A2A440

windows6.1-kb2656356-x64_01b0f5428ef6eb2782e6f2c617f06fba8bbf4460.cab

01B0F5428EF6EB2782E6F2C617F06FBA8BBF4460

windows6.1-kb2656410-x64_eedb105f4dacad913eedfb90e5764189865a17a3.cab

EEDB105F4DACAD913EEDFB90E5764189865A17A3

windows6.1-kb2667402-v2-x64_69f4c36d8349e589b0e8937efea6134de881c5b5.cab

69F4C36D8349E589B0E8937EFEA6134DE881C5B5

Windows6.1-KB2670838-x64.msu   9F667FF60E80B64CBED2774681302BAEAF0FC6A6

windows6.1-kb2676562-x64_ef1435c87d5e42d6866549733e10b5df59b48990.cab
                                                                EF1435C87D5E42D6866549733E10B5DF59B48990

windows6.1-kb2685939-x64_a2223c234072710efd1c0f18ee31d271fc8f424d.cab
                                                                A2223C234072710EFD1C0F18EE31D271FC8F424D

windows6.1-kb2690533-x64_636fd758b1266c6c8ddbe9994847e45f51a73cf8.cab
                                                                636FD758B1266C6C8DDBE9994847E45F51A73CF8

windows6.1-kb2691442-x64_77b15a8245fe43591a5c254c1c5ca41acbe924ba.cab
                                                                77B15A8245FE43591A5C254C1C5CA41ACBE924BA

windows6.1-kb2698365-x64_bf20bb36fc73c0d1f53ea1e635b8aa46c71d7b1f.cab
                                                                BF20BB36FC73C0D1F53EA1E635B8AA46C71D7B1F

windows6.1-kb2705219-v2-x64_8e8e0175d46b5a8d52c4856fa3d282faa12acd63.cab
                                                                8E8E0175D46B5A8D52C4856FA3D282FAA12ACD63

windows6.1-kb2706045-x64_bfff5d3f12c8eaf897ea7abf15dc123765eaa552.cab
                                                                BFFF5D3F12C8EAF897EA7ABF15DC123765EAA552

windows6.1-kb2712808-x64_060b60401b3de3dce053a68c65e9eb050874eb80.cab
                                                                060B60401B3DE3DCE053A68C65E9EB050874EB80

windows6.1-kb2716513-x64_18dd3e9d399071c448b22423f8ed78f8644ab125.cab
                                                                18DD3E9D399071C448B22423F8ED78F8644AB125

windows6.1-kb2719033-x64_e33fe9ab76a25eb7250b50732cc7432ab8919bb8.cab
                                                                E33FE9AB76A25EB7250B50732CC7432AB8919BB8

windows6.1-kb2722913-x64_d2e0999fefac40e8b9118ff8d5fcf6a9c7dfe150.cab
                                                                D2E0999FEFAC40E8B9118FF8D5FCF6A9C7DFE150

windows6.1-kb2727528-x64_80bd082f9278d5db8c7373720c26330e592ebfd8.cab
                                                                80BD082F9278D5DB8C7373720C26330E592EBFD8

Windows6.1-KB2729094-v2-x64.msu   E1A3ECC5030A51711F558F90DD1DB52E24CE074B

windows6.1-kb2729451-x64_444bda5997b67b7df06a22464c3cb358e686cea6.cab
444BDA5997B67B7DF06A22464C3CB358E686CEA6

windows6.1-kb2729452-x64_9047bd1de5048637a2482fcd37831481c628ef62.cab
9047BD1DE5048637A2482FCD37831481C628EF62

Windows6.1-KB2731771-x64.msu   98DBA6673CEDBC2860C76B9686E895664D463347

windows6.1-kb2736418-x64_5699216a6c5a5e736af288a4b746ec3501c94525.cab
5699216A6C5A5E736AF288A4B746EC3501C94525

windows6.1-kb2736422-x64_72f0410361e1f0ed91f68cf4ebff46fcdaa5a2ac.cab
72F0410361E1F0ED91F68CF4EBFF46FCDAA5A2AC

windows6.1-kb2742598-x64_89092d187dc5c73ea3d982421ad3d71bf73f5dcd.cab
89092D187DC5C73EA3D982421AD3D71BF73F5DCD

windows6.1-kb2742599-x64_cc314ecc5eccc5658138c4f4ac2719190db2187d.cab
CC314ECC5ECCC5658138C4F4AC2719190DB2187D

windows6.1-kb2743555-x64_35dedba60a04e482820e3217418b58f6a9ee6aba.cab
35DEDBA60A04E482820E3217418B58F6A9EE6ABA

windows6.1-kb2756822-x64_1cb60a98c68abfd98349f8a815afc681eb0028da.cab
1CB60A98C68ABFD98349F8A815AFC681EB0028DA

windows6.1-kb2756920-x64_2957fdf8a23872f7631f0d680df678ef5795e4c2.cab
2957FDF8A23872F7631F0D680DF678EF5795E4C2

windows6.1-kb2756921-x64_99e7c5328cf3f61156ad54c22cd0f68fd3bac0a2.cab
99E7C5328CF3F61156AD54C22CD0F68FD3BAC0A2

windows6.1-kb2757638-x64_b5903142a221eedd9f50ea7c55b917f9dec261c5.cab
B5903142A221EEDD9F50EA7C55B917F9DEC261C5

windows6.1-kb2758857-x64_5e0aa18e88295276eb27aee6161c6a0ba3093d70.cab
5E0AA18E88295276EB27AEE6161C6A0BA3093D70

windows6.1-kb2765809-x64_9ec667721ea4ee940905d11fe74497f205b36454.cab
9EC667721EA4EE940905D11FE74497F205B36454

windows6.1-kb2770660-x64_8b9d890a943130e35b7c7c1c729fcc7f112b2487.cab

8B9D890A943130E35B7C7C1C729FCC7F112B2487

windows6.1-kb2772930-x64_7293ed604d7d270b0e3c8e67bdf3b4832ddaa637.cab

7293ED604D7D270B0E3C8E67BDF3B4832DDAA637

windows6.1-kb2779562-x64_f9b17c43379bce87b8875b9e868d2e16e9b3618d.cab

F9B17C43379BCE87B8875B9E868D2E16E9B3618D

windows6.1-kb2785220-x64_6897c0bc2789911a1bb5bea4fd85a01f28dcbc89.cab

6897C0BC2789911A1BB5BEA4FD85A01F28DCBC89

Windows6.1-KB2786081-x64.msu   DC63B04C58D952D533C40B185A8B555B50D47905

windows6.1-kb2789644-x64_4b0403b2579b47a107630e0f8e5bdab44c002491.cab

4B0403B2579B47A107630E0F8E5BDAB44C002491

windows6.1-kb2789645-x64_95fd50ea8d9012da99ab753eca00957e66e00b6c.cab

95FD50EA8D9012DA99AB753ECA00957E66E00B6C

windows6.1-kb2790978-x64_68af5b21a15980f61c701632dca32d03b3cd0c9e.cab

68AF5B21A15980F61C701632DCA32D03B3CD0C9E

windows6.1-kb2803821-v2-x64_6f79184299510b18c008dd142282138120030b12.cab

6F79184299510B18C008DD142282138120030B12

windows6.1-kb2804579-x64_967ffae85292fda3037c0ae8e7bbe4b827f07a9c.cab

967FFAE85292FDA3037C0AE8E7BBE4B827F07A9C

windows6.1-kb2807986-x64_7382d49f2769d90a69ed430b7a991531bf7bcf51.cab

7382D49F2769D90A69ED430B7A991531BF7BCF51

windows6.1-kb2813347-x64_1838da1b088b18a9474de29d77fd7249fd83e94b.cab

1838DA1B088B18A9474DE29D77FD7249FD83E94B

windows6.1-kb2813430-x64_4b9efde2b43f5eb05b7c5b93791144614845ff2a.cab

4B9EFDE2B43F5EB05B7C5B93791144614845FF2A

Windows6.1-KB2819745-x64-MultiPkg.msu   5D40D059B9EA7F1D596F608A07CCA49E4537DC15

windows6.1-kb2832414-x64_57fad634705d693f99d44c9189e783278060ece5.cab

57FAD634705D693F99D44C9189E783278060ECE5

windows6.1-kb2833946-x64_08b0e684d7c15390bd8b1400ee4c63d60cf5ce21.cab

08B0E684D7C15390BD8B1400EE4C63D60CF5CE21

Windows6.1-KB2834140-v2-x64.msu   3DB9D9B3DC20515BF4B164821B721402E34AD9D6

windows6.1-kb2834886-x64_2c037856548bc601a164ee59a4b82316c9217786.cab

2C037856548BC601A164EE59A4B82316C9217786

windows6.1-kb2835361-x64_132f52f57e9785acc63ed369465c2511c700b8af.cab

132F52F57E9785ACC63ED369465C2511C700B8AF

windows6.1-kb2835364-x64_b56b78e8a264e23fe56cdfd4c9b73b182a4bdd71.cab

B56B78E8A264E23FE56CDFD4C9B73B182A4BDD71

windows6.1-kb2839894-x64_b431aca90bafec22e5581d5d5e8de17dd9899605.cab

B431ACA90BAFEC22E5581D5D5E8DE17DD9899605

windows6.1-kb2840149-x64_26191fcca52d4d37b1771187c0760d669f486e52.cab

26191FCCA52D4D37B1771187C0760D669F486E52

windows6.1-kb2840631-x64_022ec000034f19b7ce059c0f5175bb921b53badc.cab

022EC000034F19B7CE059C0F5175BB921B53BADC

windows6.1-kb2843638-v2-x64_c30519c8226410b89d7cc2ddd7a66f989fcc28af.cab

C30519C8226410B89D7CC2DDD7A66F989FCC28AF

windows6.1-kb2844286-v2-x64_5cb5674f212becdd33beb0af1c71fff33bec6949.cab

5CB5674F212BECDD33BEB0AF1C71FFF33BEC6949

windows6.1-kb2845187-x64_5d1bb1418fb2d7e4760ac6ce6ccdff651e8727e8.cab

5D1BB1418FB2D7E4760AC6CE6CCDFF651E8727E8

windows6.1-kb2847311-x64_30d80b72d1b686c2b011048608e2f988c903be5e.cab

30D80B72D1B686C2B011048608E2F988C903BE5E

windows6.1-kb2847927-x64_54e1e9670c22adabc3fe48e2914391f9be73a54e.cab

54E1E9670C22ADABC3FE48E2914391F9BE73A54E

windows6.1-kb2849470-x64_a4ab42dcede73008f1f3d19594c766505969c81c.cab

A4AB42DCEDE73008F1F3D19594C766505969C81C

windows6.1-kb2850851-x64_8dbeea2421daf9c77767525ea70b5dc9b7b5d57e.cab

8DBEEA2421DAF9C77767525EA70B5DC9B7B5D57E

Windows6.1-KB2852386-x64.msu   3F924A0866401D6796413AD46ADA8BB862E6C2C9

windows6.1-kb2853587-x64_5b9e4f1271a5babc89e8c4bd697f948d1db50aec.cab

5B9E4F1271A5BABC89E8C4BD697F948D1DB50AEC

windows6.1-kb2855844-x64_7a3704cc1a253f64ba83a520cf09b07fd3651e4b.cab

7A3704CC1A253F64BA83A520CF09B07FD3651E4B

windows6.1-kb2861191-x64_152b12767b8bc08548b0af20dda38958b1388aec.cab

152B12767B8BC08548B0AF20DDA38958B1388AEC

windows6.1-kb2861698-x64_653f5e3961b00d6472eb84b815926dc972103e1a.cab

653F5E3961B00D6472EB84B815926DC972103E1A

windows6.1-kb2861855-x64_d43421b0bd0fe599bef3d1c9eb67766e0f602258.cab

D43421B0BD0FE599BEF3D1C9EB67766E0F602258

windows6.1-kb2862152-x64_ed45dcf054886800ff4dc5e0028e817c5cc270d3.cab

ED45DCF054886800FF4DC5E0028E817C5CC270D3

windows6.1-kb2862330-x64_213031d94bfe471a27a99bce363d700a61d0b916.cab

213031D94BFE471A27A99BCE363D700A61D0B916

windows6.1-kb2862330-x64_81ad4b199362b13225f4442cc6a80d882e728ec9.cab

81AD4B199362B13225F4442CC6A80D882E728EC9

windows6.1-kb2862335-x64_e9eb22293f4b1fcd4c50112fa3deec47b98ea9e9.cab

E9EB22293F4B1FCD4C50112FA3DEEC47B98EA9E9

windows6.1-kb2862966-x64_6e807472a05b772df7be522d1eadcfc967df5161.cab

6E807472A05B772DF7BE522D1EADCFC967DF5161

Windows6.1-KB2862973-x64.msu   5D276C1167C59328EF7EE6BA40399F1B8529BB71

windows6.1-kb2863058-x64_c6c0e83a98f17a356eb98de3babc5ea3f27b0076.cab

C6C0E83A98F17A356EB98DE3BABC5EA3F27B0076

windows6.1-kb2863240-x64_00fd735f7bcac1df99d8dfd24f3264d951ea0572.cab

00FD735F7BCAC1DF99D8DFD24F3264D951EA0572

windows6.1-kb2864058-x64_bacdc64e488e9a44d35940f1d5cdeaaa4972b9cf.cab

BACDC64E488E9A44D35940F1D5CDEAAA4972B9CF

windows6.1-kb2864202-x64_3c74356ef1b73e7ca4fbb84eb3915c4919f45825.cab

3C74356EF1B73E7CA4FBB84EB3915C4919F45825

windows6.1-kb2868038-x64_1f1c9af221b5257a0f42aedd6039b10cfc63287d.cab

1F1C9AF221B5257A0F42AEDD6039B10CFC63287D

windows6.1-kb2868623-x64_c747dd8b5c03e5c3f0679edf983f1b6110809690.cab

C747DD8B5C03E5C3F0679EDF983F1B6110809690

windows6.1-kb2868626-x64_3b34d4c8e2c29a394ad3c536549347c37adfa734.cab

3B34D4C8E2C29A394AD3C536549347C37ADFA734

windows6.1-kb2868725-x64_75471709fda7bd141a380f727ab5fb0fcbad27fc.cab

75471709FDA7BD141A380F727AB5FB0FCBAD27FC

windows6.1-kb2868846-x64_bdf1252057e5c53a2424e85a5f696aec6c31811f.cab

BDF1252057E5C53A2424E85A5F696AEC6C31811F

windows6.1-kb2872339-x64_ed77529848fc96105bb325727d73246684664df3.cab

ED77529848FC96105BB325727D73246684664DF3

windows6.1-kb2875783-x64_955fb39b3731cd728d9746ee2c5ac965cf4723fe.cab

955FB39B3731CD728D9746EE2C5AC965CF4723FE

windows6.1-kb2876284-x64_dbc75dd1c49dc823f0eef83545b8c700d1c2c56a.cab

DBC75DD1C49DC823F0EEF83545B8C700D1C2C56A

windows6.1-kb2876331-x64_f4617c3614983559855feba808bb29d0a67b93ef.cab

F4617C3614983559855FEBA808BB29D0A67B93EF

windows6.1-kb2879017-x64_8ac0122f713fcc3175b4bf3035e9a6e78456dd4c.cab

8AC0122F713FCC3175B4BF3035E9A6E78456DD4C

Windows6.1-KB2882822-x64.msu	EC92821F6EE62AC9D2F74E847F87BE0BF9CFCB31
windows6.1-kb2883150-x64_9948daad1af6b3637c82eda62e5a8b3c97a23415.cab	
	9948DAAD1AF6B3637C82EDA62E5A8B3C97A23415
windows6.1-kb2884256-x64_32fdf7ad604b4f5074bd90fd28e9f119424a8ab7.cab	
	32FDF7AD604B4F5074BD90FD28E9F119424A8AB7
Windows6.1-KB2888049-x64.msu	FAE6327B151AE04B56FAC431E682145C14474C69
windows6.1-kb2888505-x64_3fe8d089c8ffcc320e15c8e3f23ecf93d2320fb9.cab	
	3FE8D089C8FFCC320E15C8E3F23ECF93D2320FB9
windows6.1-kb2900986-x64_9e555e1b4de1446d09f65b28415ab1d836980933.cab	
	9E555E1B4DE1446D09F65B28415AB1D836980933
windows6.1-KB976932-X64.exe	74865EF2562006E51D7F9333B4A8D45B7A749DAB
glb\capicom-kb931906-v2102_5891b5de8ce331dc998656e20f1ce0b795e88786.exe	
	5891B5DE8CE331DC998656E20F1CE0B795E88786
glb\directx_Jun2010_redist.exe	F8F1217F666BF2F6863631A7D5E5FB3A8D1542DF
glb\rootsupd.exe	2F61A0A102B7AEDEDED0362AB4FD023D2016F5F0
glb\rvkroots.exe	4B146500CC3C0A3FEDEF1A3015642DD95BD2492C
glb\Silverlight.exe	C15E492E7368FE764A16E9D95F452C615C7508DF
glb\Silverlight_x64.exe	DC33546E8492FDB5AE0AB2A3A3EBDC681263ABE2
wsus\WindowsUpdateAgent30-x64.exe	FC0EE3A9AF88EF2237AAC450BC94B2FC08AF79F5
wsus\WindowsUpdateAgent30-x86.exe	50186EC913A4896A92D72E5E5384693BF3A71182
wsus\wsusscn2.cab	C0A4C6FADBD9A50D759338EBA6A714CC8508670D
Win 7 Prof\Win 7 Prof -From MS Official Disk.iso	266819481F6D05EF4BD745E6925A5D3C52FD95B2
WinServer 2008 R2 SP1\WinServer 2008 R2 SP1 -From MS Official Disk.iso	
	1DDF7C1D17C97B12367739321BCA5429B15036EA
HardeningScripts\CreateNewERM_USER_ONLY.EXE	3E666D40A07C2DE29A0AE3C713641759318EAE0A

HardeningScripts\CreateNewUsers.EXE	B85123C8650C4C26BFD7B83B1B40CA74681A0BC1
HardeningScripts\NoNetwork.EXE	1E425AF5A3D16EB50D442C0E45BBA4FD9B955AE5
HardeningScripts\PostInstall.EXE	2FE85D6420D2105A314FD8C1D9086668C0A01743
HardeningScripts\PreInstall.EXE	11684053928BCCE483BD4A7EF227FDC8E147AB8B
HardeningScripts\ServerShare.EXE	C5943EDD1F74F0F9AEC933FF6E9AFF00AA85145B
DS200QuickHashscripts\createHashList.sh	83F8E66156B7B7BC8CF267CC016223C61427199A
DS200QuickHashscripts\CreateTrustedHashFilesCard.sh	063AAF331E002F0EF8DB632A44BE8430B08C87C1
DS200QuickHashscripts\CreateTrustedHashFilesStick.sh	D302AFD677C4B76F21014B37CE4C76FCD096AEE4
DS200QuickHashscripts\CreateVerifyHashFilesCard.sh	D5B3EB7FC24F293BDDB2A898A7C7DE54615C66AA
DS200QuickHashscripts\CreateVerifyHashFilesStick.sh	3F816DC5C4387FA0E905BD66C1D026D9C8263A71
DS200QuickHashscripts\filterDynamic.sh	D3514EF128E160A10A4F01B95F62FE54F4380E0C
DS200QuickHashscripts\genHash.sh	96A26C4E918B376EC2446136F4BFFEEF39A4BAF6
DS200QuickHashscripts\SetupValidateDir.sh	568FE6C8CED53E260FDC193F23C8C77DEAE8FA08
DS200QuickHashscripts\ValidateHash.sh	8DD827338EF1207BFCAE3E0A35A34D5DBC1EA1C9
DS850QuickHashScripts\createHashList.sh	C3F37EB875180B157BE2058442A785B12174526C
DS850QuickHashScripts\CreateTrustedHashFilesCard.sh	47D369ED592CAEB592724783F87159909662FF36
DS850QuickHashScripts\CreateTrustedHashFilesStick.sh	AED7CF3AB299093D4BF21E1CC51DA308B47A6765
DS850QuickHashScripts\CreateVerifyHashFilesCard.sh	D7CE431DFCC95E46BA7C8BB80894245D2064A2B3
DS850QuickHashScripts\CreateVerifyHashFilesStick.sh	3D1BAA6BDD53D636738203448CA173E4B1A09E97
DS850QuickHashScripts\filterDynamic.sh	F96AAED7A9C7C346C871E8FE48F55AB3FB517566
DS850QuickHashScripts\genHash.sh	A24098D66B593ABD5900DFA963CD841EE36CCCB1
DS850QuickHashScripts\SetupValidateDir.sh	49AC018F2E3AD964396FD3D243E46B19461566C7
DS850QuickHashScripts\ValidateHash.sh	4886D21958440F7E1819D2AAB35BD0BD35FCC39F

VAT_1.3.2907a_Source.zip	56B34F958B321D2D7AFBD4F45F5E26D925B84A5D
DS200 Ancillary Devices\PowerManagementMsp430_1.2.11.0a_Source.zip	
	1555E7A68A7134367214D40DB5F50DEF9CB0870D
DS200 Ancillary Devices\ScannerC8051_3.0.1.0a_Source.zip	66E880B6F64E724E5AC37A2EE31E46A9B8F60B3D
Ds200-1.7.0.0n-Source.tar.bz2	BE980F2882EE4DBA0D08371AFCC687FE2D9D6CD6
DS850\CONG850-2.9.0.0j-Source.tar.bz2	6539EEEA744ABA5130251AD65C747643E53CA62C
DS850\MCP850-2.9.0.0j-Source.tar.bz2	B7EC9A90C5AD2888C671F4D3227ED7D669D931E3
DS850\UI850-2.9.0.0j-Source.tar.bz2	D6B70E07BAAA1DED5C213AD8D642E01017093CAB
AIMS_1.3.257_Source.zip	F8A97075C7DC2804139CAE4621BD921810187113
AIMSCrypt_1.0.0.2a_Source.zip	27965E5E3802015745157B6E3ECE902C44B62568
AIMS-MDB-Version-1.003.257.zip	2A84C3FC7B552849D8863B41F608B460635261E3
AIMS-VBA-Version-1.003.257.zip	05B1CBB746B08307916F508680BFF5F364ABAAAC
AuditManager_7.5.2.0a_Source.zip	26B7E78D891579C6AE89A2DDA217C1ED322962AD
CB_650_1.2.1.0a_Source.zip	CEF36EC304377E66F531B5525F6902008AD6E5DA
CB_EAGL_1.3.2.0a_Source.zip	4B9293C1FB1072EDDFF34D9F3E2B376B8B9F2302
CB_HPMCoNG_1.1.1.0a_Source.zip	07E246134DFE8D9B4C7AD9445E46BDA392A98F3F
CB_M100_1.4.1.0a_Source.zip	4ECAC40AEF23B81D608AB05DA802A1D2C30F4814
CB_PEB_1.0.2.0a_Source.zip	D0D7F1A5B0DE2B83A9CDB0BB6BB99AEC408328FE
CB_RAND_1.1.1.0a_Source.zip	F13D68DFDF56396843ECD7BABDF380F492220500
CB_XML_1.3.1.0a_Source.zip	F33D37F9BB8B917A88891BF548A60DAE968B379F
CB_XMLConv_1.3.1.0a_Source.zip	69A2C3ED817C2EC3153F7DE899C0F49F5E1D4920
CF_Utility_9.2.1.0a_Source.zip	52FA2BC435F45C489B4176E36641FC36B86ADE6D
CRCDLL_1.4.2.0a_Source.zip	48231126C077C8E8CC26E67CF2D1669F34602834
EDM_7.8.2.0e_Source.zip	643CE385F54EAB0DAF6BAE6052F91001D921C70A

ElectionPackager_1.1.0.0a_Source.zip	ED5067DEA304C7A597D88A87A04E21423122EA1C
ERM_7.9.0.0n_Source.zip	7A596BA6DBC61A4DCCCD862C3D9C7B59245478C7
ERM_UserShell_1.0.0.0a_Source.zip	0F05F362F883321D6E945CFB816882DC5B40E844
ERMXMLConvDLL_2.3.1.0a_Source.zip	9B97BE7409E57FBA5233FB10D18A25CB43356C74
ERMXMLDATA_1.3.1.0b_Source.zip	F30144B43D7D553FB5786698E2E459BB75149F05
ESSCRPT1_1.1.1.0a_Source.zip	991C3C87E09CB926FF6C64BB676D85728BCC6A18
EssCrypt_1.9.3.0a_Source.zip	06C2B26B2D788307CD40444778E761169E14F491
EssDecpt_1.9.3.0b_Source.zip	6FB3314E9784E515C990334C01413AD0430B8989
ESSEAGL_1.3.2.0a_Source.zip	DB6E020133412B425AA7FED5502031917F3635FE
ESSIM_7.7.2.0f_Source.zip	B0B8D48FBF060AF008DABA3A1915F24033818C61
ESSM100_1.7.2.0b_Source.zip	F15E0237E9474D643A22FB5A96F74989902FC40B
ESSPCMIO_1.1.1.0a_Source.zip	FB7C8E39F112C8156C19041CF4AA55AFE301D132
ESSPEB_1.0.2.0a_Source.zip	8BCB3ABC8762607ADF1E5B123FA5FBEBBC83D956
EssXml_2.1.1.0a_Source.zip	711A3C32964D6D2AD9C7E12B37BF812497FD0BBE
EssZip_2.1.0.0a_Source.zip	4E1AA144F271984614B89CB4CBDEB4B658EC7A54
Events_9.2.1.0a_Source.zip	A822D089F0FFBDD27A8D703D7ED2D7C37E07FAC6
EXITWIN_1.1.1.0a_Source.zip	ED51B18A36FCBD8F67050A7C36E0DC03E541CA01
GetAuditData_9.2.1.0a_Source.zip	34A72F4BB92A2C5399FE5F5CD3E76E9A1D4F2DFD
HPM_5.9.0.0h_Source.zip	AE88317093A7FFDB969710748041E89D98EA08DD
HPMCoNG_1.1.1.0b_Source.zip	6C40994B4F1C2ACCCD98723176D60C440FCFF260
Images_9.2.1.0a_Source.zip	FD58B69A75DEF97D6FE52E93981FF6BE021BA798
LogMonitor_1.1.0.0a_Source.zip	A93F6486297539AB307DB256DC59F1894C376382
MakeIbin_9.2.1.0a_Source.zip	C24AD257AD38FEF4E8F146DF5CD8715340A928BA

MFCSharedSource_1.1.2.0c_Source.zip	48962C04370A5E01E95D3F3B26490F6F96C1D75D
MPRBOOT_2.6.2.0a_Source.zip	141571BFB07B2A2B44AB83173CBFEC0DF971E582
MyDLL_1.1.0.2c_Source.zip	9E4DCED4A1E16147A993536704BEE87CE9676E2B
pbmtobmp_1.1.0.1a_Source.zip	98FB7078137660BBD811A1D8BCEB39A472EB4068
PCCARD30_3.5.2.0c_Source.zip	F0664191C73E6DE22492A08EE6B53FDA05C2933C
REGUTIL_1.1.0.1a_Source.zip	4436B346069FFAE5092DDFABC7B55B055EBFCE0E
RSACrypto_2.3.0.0a_Source.zip	43D545C845B8ED3E946C819C42B314EE9A28E241
Shell_1.1.1.0a_Source.zip	92237540A62C2643330F1A0438E7D71D5EC5B1E9
ShellSetup_1.1.1.0a_Source.zip	6EEE839D065D7064B68B3B5C80C57D4E39097990
Undrvote_9.2.2.0a_Source.zip	C2F66C8B34A21949EAC19E9C526CBDBB3ED6868D
VioDialog_9.2.2.0a_Source.zip	1040E6F3AF9ACD86C39D29D496E282DAEEFCFE2A
VioWin_9.2.1.0a_Source.zip	73EE7742FEE2B09F9CF2733CAD2D5709BF6A7E70
Win650_2.2.2.0.1_Source.zip	AFE2F860337945A7453483913717259FB38BACBA
M100\5.4.4.5.3\source.tar	C5A6F63FF8C797DC5A75AFFFA08E3566CAC8C815
M650_2.2.2.0.1_Source.tar	3CB9F0C34E0755F84DCDD80E482E9CD3DC4D9106