

TABLES & GRAPHICS

Graphic images included in rules are published separately in this tables and graphics section. Graphic images are arranged in this section in the following order: Title Number, Part Number, Chapter Number and Section Number.

Graphic images are indicated in the text of the emergency, proposed, and adopted rules by the following tag: the word "Figure" followed by the TAC citation, rule number, and the appropriate subsection, paragraph, subparagraph, and so on.

Figure: 28 TAC §34.1302(a)

Citation	Violation	Fine	Citation	Violation	Fine
	License and Registration		34.517(e)	Fixed system not installed or serviced by Type A or EPL	\$2,000.00
6001.152(a)	Branch office registration certificate required	\$1,000.00		Installation and Service	
6001.161(a)	Apprentice permit required	\$500.00	34.517(a)(1)	Portable extinguisher not installed/serviced/maintained IAW manufacturer's instructions	\$50.00-\$500.00
6001.251(a)(1)	No registration certificate (portable)	\$3,000.00	34.517(a)(2)	Service tag not attached upon completion	\$250.00
6001.251(a)(2)	No registration certificate (fixed)	\$3,000.00	34.517(b)(1)	Fixed system not planned/installed/serviced IAW "manufacturer's Instructions	\$50.00-\$500.00
6001.251(a)(3)	No license	\$3,000.00	34.517(b)(2)	Installation label not affixed to system upon completion	\$250.00

34.510(e)(10)(A)	No C registration for U.S. DOT extinguishers	\$2,000.00		34.517(b)(3)	Installation label not signed and affixed to system by Type A or PL licensee (non pre-engineered)	\$500.00
34.510(e)(10)(B)	No verification of U.S. DOT registration	\$2,000.00		34.517(b)(3)	Licensee who signed label was not at final test (non pre-engineered)	\$500.00
34.510(f)	Registration information not displayed on vehicle	\$250.00		34.517(b)(4)	Service tag not attached after service completion	\$500.00
34.511(f)(1)	Licensee not employed by registered firm	\$2,000.00		34.517(f)	Pre-engineered kitchen system not UL300	\$2,000.00
34.511(f)(3)	Failure to notify SFMO of termination of employee within 14 days	\$250.00		34.517(h)	Fusible link manufacturer date not within 1 year	\$500.00
34.513	Alteration of certificates, licenses, or permits	\$3,000.00		34.517(i)	Actuation cartridge not dated	\$500.00
34.514(a)(5)(b)	Failure to maintain proof of insurance on file at SFMO	\$750.00		34.517(j)	Tamper indicator not dated	\$500.00
34.510(k); 34.511(d)	Failure to revise or change an address within the required 14 days of change	\$250.00				

	Adopted Standards			34.518(a)	Shop drawings not on file or not given to owner	\$500.00
34.517(a)(1)	Failure to abide by adopted standards or manufacturers portable extinguishers	\$50.00-\$500.00		34.518(c)	Shop drawings not signed by EPL	\$500.00
34.517(b)(1)	Failure to abide by adopted standards or manufacturers requirements for fixed extinguishers			34.519(a)	Service tag not completed in detail	\$250.00
	Location and Business Practices			34.520(b)	Service tag not completed each time service is performed	\$500.00
34.510(d)	Failure to maintain business location	\$500.00		34.521(a)	Owner not notified immediately of impaired portable or fixed extinguisher	\$500.00
34.510(e)	Failure to maintain shop	\$50.00-\$500.00		34.521(a)	AHJ not notified within 24 hrs of impaired portable or fixed extinguisher	\$500.00

6001.252(a)(3)	Misrepresentation of goods or services	\$250.00- \$1,000.00	34.521(a)	Written notice to owner; copy of written notice to AHJ within 3 days	\$500.00
34.517(c)	Pre-engineered system not installed or serviced by authorized licensee	\$2,000.00	34.521(a)	Failed to attach red tag to impaired extinguisher	\$500.00
34.517(e)	Fixed system not planned by EPL or professional engineer	\$2,000.00	34.521(a)	Service tag attached to impaired extinguisher	\$1,000.00

34.514(a)(5)(B)		Lapse of Insurance			
Months	Punitive	+	Amount saved	=	Total
0 - 1	\$200	+	\$125	=	Warning Letter
1 - 2	\$500	+	\$250	=	\$750
2 - 3	\$500	+	\$375	=	\$875
3 - 4	\$500	+	\$500	=	\$1,000
4 - 5	\$500	+	\$625	=	\$1,125
5 - 6	\$500	+	\$750	=	\$1,250
6 - 7	\$750	+	\$875	=	\$1,625
7 - 8	\$750	+	\$1,000	=	\$1,750
8 - 9	\$750	+	\$1,125	=	\$1,875
9 - 10	\$750	+	\$1,250	=	\$2,000
10 - 11	\$750	+	\$1,375	=	\$2,125
11 - 12	\$750	+	\$1,500	=	\$2,250

Figure: 28 TAC §34.1302(b)

6002.152(a)	Branch office registration certificate required	\$1,000.00	34.617	Failure to distribute/retain certificate	\$500.00
6002.154(a)	No licensed employee	\$1000.00	34.618	Installation inspection improperly performed/documentd	\$50.00-\$500.00
6002.154(b)	No license	\$3,000.00	34.618	Installation inspection improperly documented	\$500.00
6002.154(c)	Licensee not an employee of registered firm	\$750.00	34.618	Installation inspection docs not on file for 5 yrs	\$500.00
6002.301	Engage in business w/o license or registration certificate	\$3,000.00			
	Adopted Standards		34.619(a)	System/modification not planned by authorized person	\$3,000.00
34.616(b)(4)	Violation of standards established by 34.607	\$50.00-\$500.00	34.619(b)	Plans not submitted to AHJ	\$500.00
34.6616(b)(4)	Violation of standards established by manufacturers	\$50.00-\$500.00	34.619(b)	Plans incorrectly submitted to AHJ	\$250.00

	requirements (NFPA 72, §10.3.2)				
					Labels
	Location Business Practices		34.620(a)	Installation label not affixed to inside of control panel cover	\$500.00
34.610(a)	Failure to maintain business location	\$500.00	34.620(d)	Installation label improperly formatted or incomplete	\$500.00
34.610(b)	Designated employee	\$500.00	34.620(f)	Installation label incorrectly formatted or incomplete (1 or 2 family)	\$500.00
34.610(c)	Registration information not displayed on vehicle	\$250.00	34.621(a)	Service label not affixed to control panel cover	\$500.00
34.611(f)(2)	Failure to notify SFMO of termination of employee within 14 days	\$250.00	34.621(b)	Information about yellow or red label not on service label that corrected the impairments	\$500.00
34.616(b)(1)	Installation not performed by (or under direct supervision of) authorized licensee	\$3,000.00	34.623(c) (yellow) 34.624(c) (red)	Owner or AHJ not notified of impairment	\$500.00

34.616(b)(1)	Certifying licensee not licensed under ACR of primary registered firm or certifying licensee not present for final acceptance test	\$1,000.00	34.621(h)	Service label improperly formatted or incomplete	\$500.00
34.616(b)(2)	Licensee attaching label not licensed under ACR of primary registered firm	\$1,000.00	34.622(a)	Inspection/test label not filled out in detail or not affixed to inside of control panel cover	\$500.00
34.616(b)(2)	Service and maintenance not performed by or under direct supervision of authorized licensee	\$3,000.00	34.622(d)	Owner or AHJ not notified of impairment	\$500.00
6002.302(a)(3)	Misrepresentation of goods or services	\$250.00-\$1,000.00	34.622(j)	Inspection/test label incorrectly formatted/incomplete	\$500.00
34.610(h); 34.611(d)	Failure to revise or change an address within the required 14 days of change	\$250.00			
	Monitoring		34.623(a)	Completed yellow label not attached to outside	\$500.00

				of control panel of impaired system	
34.616(c)(1)	Monitoring an alarm for an unregistered firm	\$3,000.00	34.623(g)	Yellow label incorrectly formatted/incomplete	\$500.00
34.616(c)(2)(A)	Connecting an alarm to an unregistered monitoring firm	\$2,000.00	34.624(a)	Completed red label not attached to outside of impaired system	\$1,000.00
34.616(3)	No licensed technician at central station	\$1,000.00	34.624(g)	Red label improperly formatted/incomplete	\$500.00

34.613(a)(5)(B)		Lapse of Insurance			
Months	Punitive	+	Amount saved	=	Total
0 - 1	\$200	+	\$125	=	Warning Letter
1 - 2	\$500	+	\$250	=	\$750
2 - 3	\$500	+	\$375	=	\$875
3 - 4	\$500	+	\$500	=	\$1,000
4 - 5	\$500	+	\$625	=	\$1,125
5 - 6	\$500	+	\$750	=	\$1,250
6 - 7	\$750	+	\$875	=	\$1,625
7 - 8	\$750	+	\$1,000	=	\$1,750
8 - 9	\$750	+	\$1,125	=	\$1,875
9 - 10	\$750	+	\$1,250	=	\$2,000
10 - 11	\$750	+	\$1,375	=	\$2,125
11 - 12	\$750	+	\$1,500	=	\$2,250

Figure: 28 TAC §34.1302(c)

Citation	Violation	Fine	Citation	Violation	Fine
	Certificates of Registration and Licenses			Planning and Installation	
6003.151(a)	Engage in business w/o registration certificate	\$3,000.00	34.717(b)	Failed to maintain copy of updated plans	\$500.00
6003.153(b)	Act as responsible managing employee (RME) w/o holding license	\$3,000.00	34.717(c)	Plans do not contain required signatures/ information about firm or licensee	\$500.00
34.710(a)	Subcontracting to unregistered firm to perform work of fire protection sprinkler contractor	\$3,000.00	34.717(c)(2)	Plans not submitted to AHJ for review/permit/rating/record	\$500.00
34.711(a)	Firm's RME not licensed, or license expired	\$1,000.00	34.717(c)(2)	Plans incorrectly submitted to AHJ	\$250.00
34.711(e)(1)	Licensee working not employed by registered firm	\$750.00		Tags	

34.711(e) (2)	Firm failed to notify SFMO of termination of employee w/in 14 days	\$250.00		34.718(a)	Installation tag not completed, not completed in detail, not attached to riser	\$500.00
34.710(g); 34.711(d)	Failure to revise or change an address within the required 14 days of change	\$250.00				
	Adopted Standards			34.718(b)	ITM tag not attached to riser after installation/required tests and inspections	\$500.00
34.716(i)	Planning/installation/service not in accordance with adopted standards	\$50.00-\$500.00		34.719(a)	Service tag not completed and/or not attached to riser	\$500.00
	Location/Business Practices			34.719(c)	New service tag not attached after service	\$500.00
34.710(b)	Failure to maintain business location on certificate of registration	\$500.00		34.719(g)	Service tags improperly formatted	\$250.00
34.711(f)	Individual not licensed for work performed	\$3,000.00		34.720(a)	ITM tag not completed and/or attached to riser after scheduled inspection, testing or maintenance service	\$500.00

34.716(a)	System not installed under supervision of appropriately licensed individual	\$3,000.00		34.720(c)	New ITM tag not completed and attached after each service	\$500.00
34.716(b)	Individual did not affix material and test certificate on or near riser	\$500.00		34.720(g)	ITM tag improperly formatted	\$250.00
34.716(c)	Inspection/test/maintenance service not conducted by appropriately licensed individual	\$3,000.00		34.721(a)	Yellow tag not completed and/or attached to noncompliant system	\$500.00
34.716(d)	Records not available for examination	\$500.00		34.721(c)	Building owner/representative/AHJ not notified of noncompliant system	\$500.00
34.716(e)	Vehicles do not display company name, tel. number and certificate of registration	\$250.00		34.721(f)	Yellow tag improperly formatted	\$250.00
34.716(g)	The planning not performed under the direct supervision of the appropriately licensed RME.	\$500.00		34.722(a)	Red tag not completed and attached to system with an emergency impairment	\$500.00
34.716(h)	Planning, installation, or service of a fire protection sprinkler system not in accord with the minimum	\$3,000.00		34.722(b)	Owner/representative/AHJ not orally notified immediately of impairment	\$500.00

	requirements of the applicable standards	of the adopted				
6003.25 2(3)	Misrepresentation	\$250.00- \$1,000.00	34.722(b)	Owner/representative/AHJ not notified in writing of impairment within 24 hours	\$500.00	
	Planning and Installation		34.722(g)	Red tag improperly formatted	\$250.00	
34.717(a)	Failed to provide as built plans to the owner	\$500.00				
34.717(a)	Failed to maintain a copy of plans	\$500.00				
34.717(b)	Failed to provide updated plans to owner	\$500.00				

34.713(a)(7)(B)		Lapse of Insurance				
Months	Punitive	+	Amount saved	=	Total	
0 - 1	\$200	+	\$125	=	Warning Letter	
1 - 2	\$500	+	\$250	=	\$750	
2 - 3	\$500	+	\$375	=	\$875	
3 - 4	\$500	+	\$500	=	\$1,000	
4 - 5	\$500	+	\$625	=	\$1,125	
5 - 6	\$500	+	\$750	=	\$1,250	
6 - 7	\$750	+	\$875	=	\$1,625	
7 - 8	\$750	+	\$1,000	=	\$1,750	
8 - 9	\$750	+	\$1,125	=	\$1,875	
9 - 10	\$750	+	\$1,250	=	\$2,000	
10 - 11	\$750	+	\$1,375	=	\$2,125	
11 - 12	\$750	+	\$1,500	=	\$2,250	

Figure: 28 TAC §34.1302(f)

CODE	VIOLATION	FINE
2154.252(b)	Offering 1.4G fireworks for sale from other than an authorized retail location	\$1,000.00
2154.252(d)	Sells fireworks to person who does not hold license or permit	\$1,000.00
34.815(b)(1)	Purchase of 1.4G Fireworks from an unlicensed distributor or jobber.	\$500.00
2154.201(a)	Issue other permit to a person under 18 years old.	\$500.00
34.815(c)(1)	Failed to return permits by March 1 st	\$100.00
34.832(16)	No site plan on file with SFMO	\$1,000.00
34.809(a)	Conduct 1.3G display without a permit	\$3,000.00
34.809(a)	Conduct a display without the appropriate licensed operator	\$3,000.00
34.826(c)	Failed to conduct display in compliance with NFPA 1123	\$500.00- \$1,000.00
34.826(f)	Failed to conduct a proximate display in compliance with NFPA 1126	\$500.00- \$1,000.00
34.826(h)	Used a flame effect and failed to comply with NFPA 160	\$500.00- \$1,000.00
34.810(e)	Failure to revise or change an address within the required 14 days of change	\$250.00

Figure: 31 TAC §69.8(a)

large-fruited sand verbena (*Abronia macrocarpa*)
South Texas ambrosia (*Ambrosia cheiranthifolia*)
star cactus (*Astrophytum asterias*)
Texas ayenia (*Ayenia limitaris*)
Texas poppy-mallow (*Callirhoe scabriuscula*)
Terlingua Creek cat's-eye (*Oreocrava crassipes*)
black lace cactus (*Echinocereus reichenbachii* var. *albertii*)
Davis' green pitaya (*Echinocereus davisii*)
Nellie's cory cactus (*Escobaria minima*)
Sneed pincushion cactus (*Escobaria sneedii* var. *sneedii*)
Guadalupe fescue (*Festuca ligulata*)
slender rush-pea (*Hoffmannseggia tenella*)
Texas prairie dawn (*Hymenoxys texana*)
Texas golden gladeblossom (*Leavenworthia texana*)
Walker's manioc (*Manihot walkerae*)
Texas trailing phlox (*Phlox nivalis* ssp. *texensis*)
white bladderpod (*Physaria pallida*)
Zapata bladderpod (*Physaria thamnophila*)
Little Aguja pondweed (*Potamogeton clystocarpus*)
Tobusch fishhook cactus (*Sclerocactus brevihamatus* ssp. *tobuschii*)
Navasota ladies'-tresses (*Spiranthes parksii*)
Texas snowbells (*Styrax platanifolius* ssp. *texanus*)
ashy dogweed (*Thymophylla tephroleuca*)
Texas wild-rice (*Zizania texana*)

Figure: 31 TAC §69.8(b)

Leoncita false-foxglove (*Agalinis calycina*)
bunched cory cactus (*Coryphantha ramillosa* ssp. *ramillosa*)
dune umbrella-sedge (*Cyperus onerosus*)
Chisos Mountains hedgehog cactus (*Echinocereus chisosensis* var. *chisosensis*)
Lloyd's Mariposa cactus (*Sclerocactus mariposensis*)
small-headed pipewort (*Eriocaulon koernickianum*)
brush-pea (*Genistidium dumosum*)
earth fruit (*Geocarpon minimum*)
Pecos sunflower (*Helianthus paradoxus*)
Neches River rose-mallow (*Hibiscus dasycalyx*)
rock quillwort (*Isoetes lithophila*)
gypsum scalebroom (*Lepidospartum burgessii*)
Livermore sweet-cicely (*Osmorhiza bipatriata*)
Hinckley's oak (*Quercus hinckleyi*)
Houston daisy (*Rayjacksonia aurea*)